


**Sears**

owners  
manual

**MODEL NO.  
101.21200**

**CAUTION:**  
Read Rules for  
Safe Operation  
and Instructions  
Carefully



# CRAFTSMAN

6" METAL  
TURNING  
LATHE

- Assembly
- Installation
- Operating
- Repair Parts

Sold by SEARS, ROEBUCK AND CO., Chicago, Ill. 60684 U.S.A.  
and SIMPSON-SEARS LIMITED, Toronto, Ontario, Canada

# safety rules

Sears

CRAFTSMAN®

## SAFETY RULES FOR POWER TOOLS

### 1. KNOW YOUR POWER TOOL

Read the owner's manual carefully. Learn its application and limitations as well as the specific potential hazards peculiar to this tool.

### 2. GROUND ALL TOOLS

If tool is equipped with three-prong plug, it should be plugged into a three-hole receptacle. If adapter is used to accommodate two-prong receptacle, the adapter wire must be attached to a known ground. Never remove third prong.

### 3. KEEP GUARDS IN PLACE

and in working order.

### 4. REMOVE ADJUSTING KEYS AND WRENCHES

Form habit of checking to see that keys and adjusting wrenches are removed from tool before turning on tool.

### 5. KEEP WORK AREA CLEAN

Cluttered areas and benches invite accidents.

### 6. AVOID DANGEROUS ENVIRONMENT

Don't use power tools in damp or wet locations. Keep work area well illuminated.

### 7. KEEP CHILDREN AWAY

All visitors should be kept a safe distance from work area.

### 8. MAKE WORKSHOP KID PROOF

— with padlocks, master switches, or by removing starter keys.

### 9. DON'T FORCE TOOL

It will do the job better and be safer at the rate for which it was designed.

### 10. USE RIGHT TOOL

Don't force tool or attachment to do a job it was not designed for.

### 11. WEAR PROPER APPAREL

No loose clothing or jewelry to get caught in moving parts.

### 12. USE SAFETY GLASSES

Also use face or dust mask if cutting operation is dusty.

### 13. SECURE WORK

Use clamps or a vise to hold work when practical. It's safer than using your hand, freeing both hands to operate tool.

### 14. DON'T OVERREACH

Keep your proper footing and balance at all times.

### 15. MAINTAIN TOOLS IN TOP CONDITION

Keep tools sharp and clean for best and safest performance. Follow instructions for lubricating and changing accessories.

### 16. DISCONNECT TOOLS


before servicing and when changing accessories such as blades, bits, cutters.

### 17. AVOID ACCIDENTAL STARTING

Make sure switch is "OFF" before plugging in cord.

### 18. USE RECOMMENDED ACCESSORIES

Consult the owner's manual. Use of improper accessories may be hazardous.



The operation of any power tool can result in foreign objects being thrown into the eyes, which can result in severe eye damage. Always wear safety glasses or eye shields before commencing power tool operation. We recommend **Wide Vision Safety Mask** for use over spectacles, or standard safety glasses . . . available at Sears retail or catalog stores.

# TABLE OF CONTENTS

## INSTALLATION

Cleaning and Moving .....	1
Mounting Lathe .....	1 & 2
Mounting Motor .....	2

## LUBRICATION

Lubrication Chart .....	3
-------------------------	---

## CONTROLS AND OPERATION

Back Gear Controls .....	3 & 4
Changing Spindle Speeds .....	4
Headstock .....	4 & 5
Carriage .....	6
Tailstock .....	6
Chucks and Face Plates .....	6 & 7
Sequence of Engaging Controls .....	7
Mounting Work .....	7 & 8
Machining .....	8
Threading .....	8 & 9

## MAINTENANCE AND ADJUSTMENTS

Cross Slide Gib Adjustment .....	10
Tool Post Slide Gib Adjustment .....	10
Cross Slide Crank Adjustment .....	10
Tool Post Slide Crank Adjustment .....	10
Carriage Gib Adjustment .....	10
Tailstock Gib Adjustment .....	10
Carriage Bearing Plate Adjustment .....	10
Back Gear Adjustment .....	10
Spindle Bearing Adjustment .....	10

## PARTS INDEX

Compound Rest Assembly .....	11
Tool Post Assembly .....	11
Threading Dial Assembly .....	11
Carriage Assembly .....	12
Half Nut Assembly .....	12
Handwheel and Gear Assembly .....	12
Headstock Assembly .....	13
Tumbler Gear Bracket Assembly .....	13
Bed Assembly .....	14
Lead Screw and Feed Gear Assembly .....	15
Tailstock Assembly .....	16

For more complete information regarding the operation of metal-cutting lathes refer to Sears **Manual of Lathe Operation** available through Sears.

# craftsman quality 6" METAL TURNING LATHE

## **CRAFTSMAN PRODUCTS:**

### **CRAFTSMAN 6" METAL TURNING LATHE FULL ONE YEAR WARRANTY**

If, within one year from the date of purchase, this Craftsman 6" Metal Turning Lathe fails due to a defect in material or workmanship, we will repair it free of charge.

This warranty service is available by simply contacting any Sears store or Service Center throughout the United States.

Sears, Roebuck and Co.

## **CUSTOMERS RESPONSIBILITIES**

ALWAYS USE CARE WHEN OPERATING THE METAL TURNING LATHE. FOLLOW SAFETY RULES FOR POWER TOOLS. TURN OFF MOTOR BEFORE ATTEMPTING ADJUSTMENTS OR MAINTENANCE. BE SURE WORK PIECE IS FIRMLY SUPPORTED ON THE LATHE. ACCESSORIES SHOULD BE MOUNTED AND OPERATED FOLLOWING INSTRUCTIONS CAREFULLY.


KEEP THE LATHE CLEAN, LUBRICATED, AND ADJUSTED AS INSTRUCTED. DO NOT LEAVE CLEANING RAGS, TOOLS OR OTHER MATERIALS ON LATHE BED OR AROUND MOVING PARTS OF THE LATHE. INSTALL AND OPERATE LATHE AS DIRECTED IN THESE INSTRUCTIONS.

## **SET UP INSTRUCTIONS**

READ THE INSTRUCTIONS FOR CLEANING, INSTALLING, LUBRICATING AND OPERATING BEFORE ATTEMPTING TO INSTALL OR OPERATE THE LATHE.

THE METAL TURNING LATHE HAS BEEN COMPLETELY ASSEMBLED AT THE FACTORY EXCEPT FOR THE MOTOR AND MOTOR PULLEY. A GOOD SOLID BENCH IS NECESSARY FOR ACCURATE PERFORMANCE OF THIS LATHE. THE LATHE MUST BE CAREFULLY LEVELED USING A PRECISION MACHINISTS LEVEL TO MAINTAIN ACCURACY.

The motor cord used should be equipped with a 3 prong grounding plug. Cord should only be connected to a grounded receptacle for your safety. Should an electrical failure occur in the motor, the grounded plug and receptacle will protect user from electrical shock. If a grounded receptacle is not available use a grounding adapter to adapt three prong plug to receptacle. Attach grounding lead from adapter to receptacle cover screw.



**CAUTION: READ THIS —**  
BEFORE TURNING HANDWHEELS OR CRANKS —  
AVOID DAMAGING PRECISION SURFACES AND  
PARTS.

Carriage and tailstock are LOCKED TO BED and should not be moved until bed is cleaned.

Leave the lathe on the skid — easier to move.

Check bags and cartons for parts.

Read all instructions — a few minutes now may save hours later.

Clean the lathe — machined surfaces are coated with rust preventive which must be removed — see CLEANING.

Handle with care — this lathe is a precision machine.

### CLEANING

Leave carriage and tailstock locked in position until exposed bed ways are cleaned.

Using a good grease solvent, thoroughly remove the rust-preventive from exposed bed ways — tops, sides, bottoms — and from all other machined surfaces.

Next, loosen the carriage lock screw (located on top of carriage at right side) and move carriage to a clean section of bed. Then, loosen tailstock clamp nut — move tailstock — and finish cleaning bed ways.

Use a stiff bristle brush (not wire) to clean lead screw and carriage rack.

Apply a light coating of machine oil to all machined surfaces — for protection.

Don't use an air hose — it could blow dirt or grit into bearing surfaces.

For long service life — make it a habit to clean and lubricate regularly.

### MOVING AND LIFTING

Leave lathe bolted on skid, it is easier to move to final location.

After cleaning, move carriage toward tailstock end for better balance.

If skid has been removed — lift by bed feet or underside of bed — DO NOT use lead screw, handwheels or levers.

### LATHE BENCH

A rigid bench is essential for precision work.

A wood bench built to the following specifications will provide a solid foundation for the lathe.

Bench must have a clear hardwood top at least 1 - 5/8" thick, cleated or well doweled to form a rigid table. Bench should be built using bolted construction.

Bench legs should be solid 4" x 4"s, well braced and securely anchored to bench top — provide legs with lugs for bolting securely to floor.

### ANCHORING BENCH TO FLOOR

Bench must be bolted to floor.

A concrete floor is the best foundation. Wood floor should be rigid and capable of supporting the weight of the lathe without deflection.

Make sure the legs rest solidly on the floor.

Place wood bench in final location — to provide working room, back leg should be 3 feet from wall. Mark the location of mounting holes.

Use anchor bolts to secure bench to concrete floor — use lag screws to secure to wood floor.

Move bench, drill holes and install anchor nuts in concrete floor — drill pilot holes for lag screws in wood floor.

Reposition bench and start anchor or lag screws — DO NOT TIGHTEN until bench is level.

### LEVELING THE BENCH

Use one precision level at least 6' long — place level on bench top — refer to Fig. 1 for level positions.




FIGURE 1

Place shims as required between bench legs and floor until the bench is approximately level. Shims should be of hardwood or metal.

**NOTE:** Doing this eliminates excessive shimming between top of bench and bed legs when leveling the lathe bed.




FIGURE 2

Tighten the anchoring bolts or lag screws securely.

Recheck the level of bench — unequal tightening of anchoring bolts may have pulled the bench out of level.

## POSITION LATHE ON BENCH




FIGURE 3

Remove bolts from skid and place the lathe on the bench in the position shown in Fig. 3 with front edge of the lathe leg (D) about 3/4" from the front of the bench. Mark the position of four mounting holes (C).

Move lathe and drill four holes in bench top. Reposition lathe and start bolts — **DO NOT TIGHTEN** bolts securely until after lathe has been leveled.

## LEVELING

The lathe should be kept perfectly level at all times. When carelessly mounted, the bed may become twisted. Even a slight amount of twist will move centers out of alignment and result in inaccurate work and excessive wear. Make it a habit to regularly check the level of the bed.

### THIS IS IMPORTANT:

Use *one* precision level at least 6" long — level should show a distinct bubble movement when a .003" shim is placed under one end.

Clean the bed ways thoroughly.




FIGURE 4

First level bed longitudinally. Compensate for variations of bubble readings with thin metal shims placed around bolts between bed legs and bench top until bed is level — refer to Fig. 4 for level positions.

Shims should be the only contact point between bench top and bed legs.

Refer to Fig. 5 for approximate size of shim. If the outer or inner edges of legs bear on bench top, bed may be twisted or bowed. Next, level the bed at headstock and tailstock — see Fig. 4. Place level at right angles to the bed — use a square to align the level. Do not turn level end for end.

Level readings at headstock and tailstock must be identical. Compensate for variation of bubble readings by placing shims between bed legs and bench top at the bolt holes. Tighten the four mounting bolts securely and recheck level readings.




FIGURE 5

Check level of bed at frequent intervals. Chatter — turning taper — boring taper — facing convex or concave is the general result of an improperly leveled lathe.

## MOUNTING MOTOR

Place motor pulley on motor shaft with small step toward motor.

**NOTE:** The lathe is designed for a 1/3 HP, 1725-1750 rpm motor — of the type shown in our catalog.

Position motor on lathe bench to align motor pulley with, and parallel to, spindle pulley.

With tension pulley in uppermost position place belt over motor and spindle pulleys. Position motor to tighten belt — just enough so it is possible to shift the belt.

Bolt motor in this position.

Tighten belt by moving tension pulley down on belt and locking in place — see (A) Fig. 6.

**NOTE:** Properly tensioned belt will pull a normal cutting load — too much tension will cause excessive wear of bearings and shafts.

Install belt — pulley guard.




FIGURE 6


## ELECTRICAL CONNECTIONS

Before connecting motor, make sure that line voltage corresponds with the requirements of the motor. If there is any question, call your power company.

Wire motor so that pulley rotates in a clockwise direction as viewed from pulley end.

### DO NOT OPERATE THE LATHE UNTIL

- the bed has been leveled, see page 1.
- the lathe has been lubricated, see page 3.
- the operating instructions have been read, see pages 3 - 9.



## LUBRICATION

### IMPORTANT—LUBRICATE LATHE BEFORE OPERATING

#### CODE

**D—DAILY** oil with S.A.E. No. 20 oil  
**W—WEEKLY** oil with S.A.E. No. 20 oil  
**M—MONTHLY** oil with S.A.E. No. 20 oil  
**R—REGULARLY** clean and keep oiled at all times.  
**P—PERIODICALLY** lubricate gear teeth with a cling type

outer gear lubricant to obtain smoother, more quiet operation. Remove oil and dirt before applying grease.

\*Remove screw to oil bearing.

\*\*About once a month clean with kerosene and a brush, then cover with oil.

**NOTE:** Spindle bearings are sealed-for-life ball bearings and do not require lubrication.

### KEEP YOUR LATHE CLEAN

Oil and dirt form an abrasive compound which can easily damage carefully fitted bearing surfaces. Wipe the bed and all polished parts with a clean oily rag at frequent intervals. Use a brush to clean spindle threads, gear teeth, lead screw threads, etc.

### CAUTION: ALWAYS WEAR SAFETY GLASSES WHEN OPERATING ANY MACHINE

#### CONTROLS AND OPERATION


**DON'T TURN ON MOTOR UNTIL YOU'VE READ THESE INSTRUCTIONS.** As you read, make a dry run with each of the controls — start with **BACK GEAR CONTROLS**.

#### BACK GEAR CONTROLS

**BACK GEAR DRIVE** provides the slow spindle speeds — 55 to 300 rpm — required for heavy cuts and large diameter work.

To engage the **BACK GEAR DRIVE**:

1. Turn off motor.
2. Remove belt — pulley guard.
3. Pull coupling (A Figure 7) to disengage pulley and gear.



**FIGURE 7**

4. Move back gear lever (A Figure 8), on rear of headstock, up to engage gears. It may be necessary to rotate pulley by hand so gears will mesh.




FIGURE 8

DIRECT DRIVE provides high spindle speeds from 430 to 2300 rpm.

To engage DIRECT DRIVE:

1. Turn off motor.
2. Remove belt — pulley guard.
3. Move back gear lever (A Figure 8) down to disengage gears.
4. Push on coupling (A Figure 7) and turn spindle pulley by hand until coupling slides in, locking pulley and gear together.
5. Replace guard.

#### CHANGING SPINDLE SPEEDS:

1. Turn off motor.
2. Remove belt-pulley guard.
3. Loosen belt by moving tension pulley up away from belt.




FIGURE 9

4. Shift belt to position for speed desired, as indicated on spindle speed chart (Figure 9).
5. Tighten belt by moving tension pulley down on belt and locking in place.
6. Replace guard.

Much of the success in metal cutting depends upon the choice of cutting speeds. Too slow a speed not only wastes time, but leaves a rough finish — too high a speed burns the tool.

#### HEADSTOCK

LEAD SCREW DIRECTION LEVER (B Figure 7) has three positions. Center position is neutral — gear train is disengaged and lead screw does not turn. The upper and lower holes are either forward or reverse positions depending on the gear set up.

**NOTE:** Whenever a new gear train has been set up, shift the lever to test the direction of the carriage travel.

**CAUTION:** Always turn off motor and let spindle stop before shifting lead screw direction lever.

#### GEAR SET UPS FOR THREADS AND FEEDS

The gear set up used determines the rate of rotation of lead screw in relation to the rpm of the spindle.

To simplify gear set ups the three different gear bracket positions have been assigned letters. The outer end of the longest bracket slot is called "Pos. A," the inner portion of the same slot is "Pos. C." The "B" position of a gear is the position toward the headstock — the "F" position is away from the headstock. See Figure 10.

FIG. 1  
SET UP FOR 8 16 THREADS

FIG. 2  
SET UP FOR 18 32 THREADS

FIG. 3  
SET UP FOR 36 64 THREADS

FIG. 4  
SET UP FOR 72 128 THREADS

FIG. 5  
SET UP FOR 144 256 THREADS

FIG. 6  
SET UP FOR 288 512 THREADS

THREADING CHART											
A-B-C ARE GEAR STUD POSITIONS B = BACK POSITION (TOWARD HEADSTOCK) F = FRONT POSITION (AWAY FROM HEADSTOCK) I = IDLER GEAR      - = BLANK S = SPACER GEAR    XXS = STEEL SPACER											

THREATS PER INCH	GEAR ON SCREW	POSITION C	POSITION B	POSITION A	SPINDLE STUD GEAR	FIG.
8	32F	32	64	---	64I XXS	32 1
9	36F	32	64	---	64I XXS	32 1
10	40F	32	64	---	64I XXS	32 1
11	44F	20	40	---	64I XXS	32 1
11.5	46F	20	40	---	64I XXS	32 1
12	48F	20	40	---	64I XXS	32 1
13	52F	20	40	---	64I XXS	32 1
14	56F	20	40	---	64I XXS	32 1
16	64F	20	40	---	64I XXS	32 1
18	36B	---	---	64I XXS	---	32 2
20	40B	---	---	64I XXS	---	32 2
22	44B	---	---	64I XXS	---	32 2
24	48B	---	---	64I XXS	---	32 2
27	54B	---	---	64I XXS	---	32 2
28	56B	---	---	64I XXS	---	32 2
32	64B	---	---	64I XXS	---	32 2
36	36F	20S	32I	---	XXS 64I	16 3
40	40F	20S	32I	---	XXS 64I	16 3
44	44F	20S	32I	---	XXS 64I	16 3
48	48F	20S	32I	---	XXS 64I	16 3
56	56F	20S	32I	---	XXS 64I	16 3
64	64F	20S	32I	---	XXS 64I	16 3
72	36B	56I	XXS	---	32 64	16 4
80	40B	56I	XXS	---	32 64	16 4
96	48B	56I	XXS	---	32 64	16 4

FEED PER REVOLUTION OF SPINDLE											
.0024"	64F	64	20	---	24	48	16	5			
.0039"	64F	64	32	---	24	48	16	5			
.0048"	64B	20	64	---	48	24	32	6			
.0078"	64B	32	64	---	48	24	32	6			

FIGURE 10

Before setting up a train of change gears, examine one of the change gear stud assemblies which hold the change gears to the gear bracket. See Figure 11.






FIGURE 11

Each stud assembly has an outer gear bushing long enough to accommodate two gears. The bushing has a double key which fits into the keyways in the gears. The bushing and two gears (or gear and steel spacer) fit over a sleeve and the assembly is bolted to the gear bracket. The washer is a bearing for the outer end of the gear bushing.

When setting up gear train, sufficient clearance must be allowed between two meshing gears. Gear clearance does not reduce accuracy of thread cutting operation, because all play, or back lash, is taken up in one direction — see Figure 13.




FIGURE 13


A suggested method to obtain proper clearance is:

1. Place a strip of thick wrapping paper between the teeth of two meshing gears.
2. Tighten gears in position.
3. Remove paper.

Clean gears occasionally to remove any chips which become lodged in gear teeth. Chips in gear teeth result in inaccuracies when cutting screw threads. A small amount of grease, preferably a "cling type outer gear" lubricant applied to gear teeth, will aid in obtaining smoother, more quiet operation.

**NOTE:** Remove all oil, grease and dirt before applying lubricant.

A REPRESENTATIVE GEAR SET-UP for 36 threads per inch.



SET-UP FOR  
36 THREADS

FIGURE 14

1. Place 36 tooth gear on front position of leadscrew stub.
2. Place 20 tooth gear and 32 tooth gear on sleeve and mount in "Pos. C" on gear bracket with 32 tooth gear in-front position. Tighten so that 32 tooth gear meshes with 36 tooth gear in screw position. The 20 tooth gear is a spacer.
3. Place 64 tooth gear and steel spacer on sleeve and mount in "Pos. A" on gear bracket with 64 tooth gear in front position. Tighten so that 64 tooth gear meshes with 32 tooth gear in "Pos. C."
4. Swing entire gear bracket upward and tighten so that the 64 tooth gear meshes with the 16 tooth stud gear. The gear bracket is tightened in position by locking the nut (A Figure 15) on the side of the leadscrew support bracket.




FIGURE 15

Shift the leadscrew direction lever to test the direction of carriage travel before starting to cut a thread. After the lever has been shifted to the proper position, it should not be moved until the thread has been completed. This is important because a shift in the lever position destroys the relation between the threading dial and the lathe spindle and causes splitting the thread.

## CARRIAGE

Carriage moves along the bed by hand or by power feed and supports the cross slide, compound rest, tool post and cutting tool.




FIGURE 16

**HANDWHEEL (F, Figure 16)** manually moves carriage along the lathe bed.

**CROSS FEED AND TOOL POST SLIDE CRANKS (G)** move the cross slide and tool post slide in and out. Crank collars are graduated in thousandths of an inch.

**TOOL POST SLIDE** can be turned in a complete circle, by loosening the two socket set screws (E) and is graduated in degrees from 0° to 180° so that any angle can be cut.

**CARRIAGE LOCK SCREW (A)** locks carriage to bed for facing or cutoff operations.


**HALF-NUT LEVER (D)** engages half-nuts with lead screw for threading and longitudinal feeding. When lever is moved down, it engages half-nuts with lead screw — carriage travels along bed as lead screw turns. **CAUTION:** Always loosen carriage lock screw before engaging half-nuts.

**THREADING DIAL (C)** performs the important function of indicating the proper time to engage the half-nut lever so that tool will enter the same groove of the thread on each successive cut.

To avoid excessive wear of threading dial gear, loosen clamp screw (B) and swing gear away from lead screw when not threading.

Without the threading dial, it would be necessary to wind the tool out of the thread at the end of each cut. Then, without disengaging half-nuts, reverse the rotation of the motor to bring the carriage back to the starting point for each successive cut.

FIGURE 17



The tool post holds the tool rigidly in position for cutting operations — refer to Figure 17.




FIGURE 18

Tool bit holders permit the use of small, inexpensive and replaceable tool bits — refer to Figure 18.

In order to avoid undesirable overhang, tool bits should be clamped so the cutting end of the tool bit is as close to the holder as the work will permit, and, the tool holder should be as far back in the tool post as possible.

The cutting edge of the tool should be placed on lathe center line.

## TAILSTOCK

The tailstock supports long work, and holds tools for drilling and reaming operations.




FIGURE 19

**RAM LOCK LEVER (B, Figure 19)** locks ram in place. **NOTE:** Before attempting to move ram, loosen ram lock.

**HANDWHEEL (A)** moves the tailstock ram (C). To advance ram, turn handwheel clockwise, to retract ram or eject center, turn counterclockwise.

Lock tailstock to lathe bed by tightening nut (D).

The tailstock may be set over for taper turning by loosening the lock nut and adjusting the two setover screws (E).

## MOUNTING CHUCKS AND FACE PLATES

1. Carefully wipe face of hub and threads clean of dirt and chips.
2. Carefully clean spindle threads and shoulder.
3. Cover spindle threads with a light film of clean oil. Nicks, burrs, chips or dirt on the lathe spindle threads, pilot or shoulder — or on the chuck pilot, threads or

shoulder — will throw the chuck out of alignment and result in inaccurate work.

4. Place lathe in back gear to keep spindle from turning.
5. Screw chuck or face plate on spindle — do not force, it should thread on easily. Turn it rapidly as it nears spindle shoulder so hub will seat firmly against spindle shoulder face.

**CAUTION** — Do not turn power on with the spindle locked.

#### TO REMOVE CHUCK OR FACE PLATE

1. Place board under chuck to protect bed ways, rotate chuck until wrench hole is on top. Lock spindle by engaging back gears. Place chuck wrench in chuck and pull. If chuck doesn't release, tap **BASE OF WRENCH** lightly with a mallet. Remove chuck carefully so as not to damage spindle threads. Disengage back gears.
2. To remove face plate, lock spindle by engaging back gears and tap slot in face plate with a lead or brass hammer in a counterclockwise direction. Remove face plate carefully to prevent damaging spindle threads. Disengage back gears.

**CAUTION** — Never remove chuck or face plate while lathe is running.

#### CHUCK CARE

**INSPECT YOUR CHUCK PERIODICALLY.** If used properly, a chuck will give good service for a long period.

**OIL CHUCK FREQUENTLY.** Most wear is due to dirt and lack of proper lubrication. Oil chuck jaws and scroll at regular intervals with a light film of clean SAE No. 10 machine oil. **CAUTION:** Do not apply too much oil — it collects dust and chips.

**PROTECT CHUCK WHEN NOT IN USE.** Place chuck in a covered box — don't leave it exposed to dirt or chips. The accuracy of any chuck can be destroyed if dirt or chips collect in the scroll, threads, jaws or slots.




FIGURE 20

Use a tooth brush to clean spindle threads. A bent wire filed on ends to a V-shape should be used to remove dirt and chips from chuck threads — refer to Figure 20.

To maintain chuck accuracy, **NEVER** abuse your chuck.

**KEEP THE LATHE CLEAN.** Oil and dirt form an abrasive compound which can easily damage bearing surfaces. Wipe the bed and all machined surfaces with a clean oily cloth at frequent intervals. Use a brush to clean spindle, gear teeth, lead screw threads, etc.

#### SEQUENCE OF ENGAGING CONTROLS FOR OPERATING LATHE

After trying out each of the controls, do a practice setup, following these steps:

1. Engage back gears.
2. Shift belt to low speed position — see chart.
3. Move lead screw direction lever to neutral (center position).
4. Set gear train for a feed of .0024" (see chart).
5. Unlock carriage lock screw.
6. Move half-nut lever up (disengaged position).

**NOW TURN ON MOTOR** — only spindle should be turning.

To engage leadscrew: **STOP MOTOR**, move carriage to center of bed, move leadscrew direction lever to upper position and start motor — leadscrew should be turning very slowly. Now engage half-nut lever, causing carriage to travel toward headstock.

#### MOUNTING THE WORK

Common methods of holding the work in the lathe are — between centers, in a chuck, on the face plate, and on a mandrel.

Whenever practicable, the work is held between centers. There are two steps in mounting work between centers: Locating the center points at each end of the work, and countersinking and drilling the ends to accommodate the lathe centers.

On round work, centers are usually located with either the hermaphrodite caliper or the center head attachment for a steel square. On the centering of square, hexagon and other regular-sided stock, lines are scribed across the ends from corner to corner. The work is then center punched at the point of intersection.

After the ends have been countersunk, the work is mounted between centers. Be sure that the "tail" or bent portion of the lathe dog fits into the face plate slot without resting on the bottom of the face plate slot.

Bring the tailstock up close to the end of the stock and lock in place. Turn the tailstock center into the countersunk hole and lock in such a position that the play is taken up between centers but not so tight that the work will not freely rotate. **PLACE PLENTY OF WHITE LEAD AT POINT OF BEARING ON TAILSTOCK CENTER.**

## MACHINING

Cuts, especially heavy ones, should always be made toward the headstock. In this way most of the pressure is toward the live center which revolves with the work. Cutting toward the tailstock puts a heavy additional pressure on the tailstock center and is quite likely to damage the center.

The type of tool holder, and the way it is set into the work, should always be such that it tends to swing away from the work on heavy cuts. When cutting at an angle with the compound rest, the tool should be set at a right angle to the surface of the cut, not at a right angle to the center line of the lathe.

Facing cuts represent different cutting relations and tool angles, and tools should preferably be special ground, for that purpose. Smoother cutting and a finer finish can be obtained generally by cutting toward the outside — that is, feeding from the center of work out.

If the tool is ground properly, the point of the tool will not have to be set above or below the center line of the work, but should be set on the center line.

Boring operations require only slightly different tools and methods than those for external turning. With the round tool shank parallel to the lathe center line, set the boring tool into the work with the shank below the center line. Then by putting the cutting edge on exact center line, the correct amount of back rake is provided. The general rules for the use of the external tools apply to boring tools. For maximum rigidity, choose the largest possible boring tool. Take several light cuts rather than a heavy one when boring.

## PROPER POSITION OF TOOL POST SLIDE

For maximum tool support, the front edge of the tool post slide should be positioned flush with the front end of the upper swivel.




FIGURE 21

RIGHT — Tool post slide is flush with front end of the upper swivel, therefore provides maximum tool support — refer to Figure 21.




FIGURE 22

WRONG — Unnecessary overhang of tool post slide will result in tool chatter, and could cause the tool post slide to break — refer to Figure 22.




FIGURE 23

WRONG — Tool post slide is too far back — tool overhang is excessive — refer to Figure 23.

## THREADING

Only the operation connected with the cutting of the 60 degree thread will be described.

After the work has been properly prepared for threading, set the compound rest at a 29 degree angle so that the tool bit faces in the direction the carriage will travel. Mount the tool holder in the tool post so that the point of the tool is exactly on the lathe center line — tighten the tool post screw just enough to hold the tool holder. Then use a center or thread gauge to set the tool point at an exact right angle to the work. Tap lightly on the back of the tool holder when bringing into position. With the tool point at an exact right angle to the work, recheck center line position and tighten tool post screw.

Check the change gear assembly and the leadscrew direction lever so that the carriage will move in the proper direction. Adjust belts for a speed of 55 R.P.M.

Set the compound rest approximately in the center of its ways and advance the cross feed so that it is set at 0 with the tool close to the work. With the point of the tool about an inch to the right of the start of the thread, advance the tool with the compound rest so that the first cut will be about .003 inch.

Start the lathe and engage the half-nut lever on the carriage. Apply plenty of lubricant to the work. When the tool point has traveled the desired length along the work, raise the half-nut lever, back out the cross feed a turn or two, and return the carriage by hand to the starting point.

Advance the cross feed to its original position at 0, advance the compound rest for the desired depth of cut, and engage the half-nut lever for the second cut. All feeding is done with the compound rest. Follow the same routine on all succeeding cuts.

### THREADING DIAL

When cutting *even-numbered threads* (such as 12, 14, 16, 32, etc., per inch), engage the half-nut lever for the first cut when the stationary mark on the outside of the threading dial is in line with *any* of the marks on rotating portion of the dial. Any dial marking may be used for successive cuts.

When cutting *odd-numbered threads* (such as 7, 9, 11, 23,

27, etc., per inch), engage the half-nut lever for the first cut and all successive cuts when the stationary mark on the threading dial is in line with *any* of the numbered marks on the dial.

When cutting *half-numbered threads* (such as 7½, 11½, 12½, etc., per inch), engage the half-nut lever at the *same* number on the threading dial for *each* cut.

**PRECAUTIONS:** Never disengage the half-nut lever in the middle of the thread without first backing out the tool with the cross-feed.

The threading dial cannot be used for metric threads. For these, the half-nut is closed on the lead screw, and the machine reversed by means of the reversing switch. After each cut and tool withdrawal, the tool is brought back to starting point. The nut remains engaged until the thread is completed.

## GEAR SET-UPS FOR THREADS AND FEEDS AND METRIC THREADS NOT SHOWN ON CHART

### THREADS FROM 7 - 1/2 THROUGH 78

THREADS PER INCH	GEAR ON SCREW	POS. C B F	POS. B B F	POS. A B F	SPINDLE STUD GEAR
7.5	40F	24 64	— —	64I XXS	32
12.5	40F	— —	20 32	64I XXS	32
13.5	54F	— —	20 40	46I XXS	32
21	56F	36 48	— —	64I XXS	32
25	40F	— —	40 32	64I XXS	32
30	48F	— —	40 32	64I XXS	32
33	40B	32 48	— —	44 40	32
35	40F	XXS 54I	— —	56 32	32
39	54F	52 36	— —	56I XXS	32
42	48F	56 32	— —	54I XXS	32
45	40F	XXS 52I	— —	54 24	32
46	46F	— —	— —	XXS 64I	16
49	56F	56 32	— —	54I XXS	32
50	40B	— —	32 40	XXS 64I	16
52	52F	— —	— —	XXS 64I	16
54	54F	— —	— —	XXS 64I	16
60	48B	— —	32 40	XXS 64I	16
65	48B	32 52	— —	40 24	32
69	54B	36 46	— —	XXS 64I	16
70	40B	— —	48I XXS	32 56	16
75	40F	36 24	32 40	XXS 44I	16
77	44B	32 56	— —	XXS 54I	16
78	54B	36 52	— —	XXS 64I	16

### FEEDS FROM .0021 THROUGH .008

FEED INCHES	GEAR ON SCREW	POS. C B F	POS. B B F	POS. A B F	SPINDLE STUD GEAR
.0021	64F	64 20	— —	24 56	16
.005	64F	64 32	— —	36 56	16
.006	64B	20 52	— —	XXS 56I	16
.007	64B	20 54	— —	40 24	32
.008	64B	20 52	— —	54 36	32

### METRIC THREADS

PITCH MM	GEAR ON SCREW	POS. C B F	POS. B B F	POS. A B F	SPINDLE STUD GEAR
.5	54B	44 46	20 40I	36 20	32
.6	56B	36 64	— —	44 52	32
.7	64B	24 32	— —	44 52	32
.75	64B	32 40	— —	44 52	32
.8	54B	46 64	— —	44 52	32
.9	46B	36 52	— —	44 52	32
1.0	40B	32 48	— —	44 52	32
1.25	44F	48 52	— —	40I 20	32
1.50	44F	40 52I	— —	46I 20	32
1.75	64B	46 20	XXS 48I	48 46	32
2.0	56B	46 24	XXS 44I	40 46	32
2.5	44F	24 52	— —	64I 20	32
3.0	44F	20 52	— —	64I 20	32

## MAINTENANCE AND ADJUSTMENTS

### PREVENTIVE MAINTENANCE

Keep lathe clean and properly lubricated.

Don't use lathe for a work bench or leave tools on the bed ways.

Always shut off power before leaving lathe.

Recheck level of the bed frequently.

Lock tailstock to bed ways before turning between centers.

Keep lead screw threads clean, and oil lightly.

Securely lock cutting tool in position before taking a cut.

### CROSS AND TOOL POST SLIDE CRANK ADJUSTMENT

1. Hold crank and loosen outer nut on end of screw.
2. Hold crank and tighten the inner nut to remove end play in cross feed or compound handle assembly.
3. Hold crank and *securely tighten* outer nut against crank.

### CROSS AND TOOL POST SLIDE GIB ADJUSTMENT

1. Loosen Gib Screw Lock Nuts.
2. Adjust Gib Screws evenly until slide moves with a slight drag.
3. Tighten the Gib Screw Lock Nuts — hold Gib Screw with screw driver while tightening nuts.

### CARRIAGE GIB ADJUSTMENT

If horizontal play develops between carriage and bed, tighten the four gib screws at rear of carriage.

To adjust:

1. Loosen gib screw lock nuts.
2. Turn gib screws evenly until carriage moves with a slight drag.
3. Hold screws with screw driver and tighten the lock nuts.

### CARRIAGE BEARING PLATE ADJUSTMENT

Carriage bearing plates, which bear on underside of front and back ways, hold the carriage firmly to the bed. Plates have shims of varying thickness for wear adjustment.

### TAILSTOCK GIB ADJUSTMENT

Two gib screws, one on each end of the tailstock gib, regulate the tightness of tailstock between the bed ways.

To adjust:

Tighten both gib screws until both ends of the gib bear evenly against bed way with equal pressure, and tailstock slides smoothly.

### BACK GEAR ADJUSTMENT

1. Shift back gear lever upward to engage back gears.
2. Loosen socket set screw (A figure 24).




FIGURE 24

3. Rotate back gear assembly until gears are in proper mesh.
4. Retighten set screw.


### SPINDLE BEARING ADJUSTMENT

Spindle bearings have been preloaded at factory and seldom require adjusting. If spindle play is noticeable when spindle is pushed back and forth, follow these instructions:

1. Remove belt-pulley guard and loosen belt.
2. Loosen set screws in collar next to back gear.
3. Push nose end of spindle firmly and force collar against back gear by tapping **lightly** on the small step of the spindle pulley. **CAUTION** — DO NOT tap directly on pulley — use a block of wood or metal recessed to clear the coupling.
4. When end play has been removed, lock collar in this position.  
  
Rotate spindle by hand to make sure it turns freely. If adjustment is too tight, tap **lightly** on left end of spindle.
5. Replace belt and belt-pulley guard.

# CRAFTSMAN 6" METAL TURNING LATHE, MODEL No. 101.21200

## COMPOUND REST ASSEMBLY 3950-27



### M6-39X TOOL POST ASSEMBLY

### 3950-18 THREADING DIAL ASSEMBLY

ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------

#### M6-39X TOOL POST ASSEMBLY

- |     |        |                      |
|-----|--------|----------------------|
| 1.  | M6-39  | Post, Tool           |
| 2.  | M6-136 | Tool Post Anchor     |
| 3.  | M6-40  | Washer, Tool Post    |
| 4.  | 9-41   | Rocker, Tool Post    |
| 5.  | M6-148 | Screw, Tool Post Set |
| *6. | M6-115 | Wrench               |

#### 3950-27 COMPOUND REST ASSEMBLY

- |       |         |  |
|-------|---------|--|
| 7.    | 981-116 | Screw, H'dless Set Screw #10-32 x 5/8 (Dog Pt., 2 Req'd) |
| 8.    | 10-226  | Nut, Gib Screw (3 Req'd)                                 |
| 9.    | 345-076 | Gib, Combination (Comp. Rest)                            |
| 10.   | M6-301  | Compound Rest Swivel (Lower)                             |
| **11. | 120680  | Screw, Soc. Set Screw 1/4-20 x 1/2 (Cup Pt., 3 Req'd)    |
| 12.   | M6-309  | Pin, Compound Lock Plunger (2 Req'd)                     |
| 13.   | 345-076 | Gib, Combination (Tool Post Slide)                       |
| 14.   | M6-223  | Gib, Lock Nut (4 Req'd)                                  |
| 15.   | 141025  | Screw, H'dless Set Screw #8-32 x 1/2 (Dog Pt., 4 Req'd)  |
| 16.   | W30-16  | Oiler  |
| 17.   | M6-303  | Compound Rest Tool Post Slide                            |
| 18.   | M6-302  | Swivel, Tool Post (Upper)                                |
| 19.   | M6-306  | Nut, Tool Post Slide                                     |
| 20.   | 3950-19 | Compound Rest Screw & Collar Assembly                    |

ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------


- |       |         |   |
|-------|---------|---|
| **21. | 106958  | #204 Woodruff Key                                 |
| **22. | 110499  | Screw, Rd. Hd. Mach. Screw #10-24 x 3/8           |
| 23.   | 342-148 | Guard, Carriage Slide                             |
| **24. | 127555  | Screw, H'dless Set Screw #8-32 x 3/16 (Cup Pt.)   |
| 25.   | M6-48   | Graduated Collar                                  |
| **26. | 114501  | Nut, Hex Jam Nut 1/4-20                           |
| 27.   | M6-263  | Compound Ball Crank Nut                           |
| 28.   | M6-104  | Handle, Ball Crank (2 Req'd)                      |
| 29.   | 3950-23 | Compound Rest Crank & Handle Assembly             |
| **30. | 110500  | Screw, Rd. Hd. Mach. Screw #10-24 x 1/2 (2 Req'd) |
| 31.   | M6-307  | Compound Rest Thrust Plate                        |
| *32.  | M6-19A  | Nut   |
| 33.   | 981-117 | Screw, H'dless Set Screw #10-32 x 3/4 (Dog Pt.)   |

#### 3950-18 THREADING DIAL ASSEMBLY

- |        |        |                                     |
|--------|--------|-------------------------------------|
| 34.    | M6-62  | Dial, Threading                     |
| 35.    | M6-65  | Shaft, Threading Dial               |
| ***36. | 446142 | 3/16 Washer, Plain                  |
| ***37. | 106321 | Screw, Hex Cap Screw 1/4-20 x 1-1/8 |
| 38.    | M6-63  | Body, Threading Dial                |
| 39.    | M6-64A | Pinion, Threading Dial              |

\*Not Part of the Assembly  
\*\*Standard hardware item - may be purchased locally.

# CRAFTSMAN 6" METAL TURNING LATHE, MODEL No. 101.2120



ITEM NO. PART NO. DESCRIPTION

## 3950-28 CARRIAGE ASSEMBLY

- 1. M6-262 Nut, Cross Feed Ball Crank
- 2. M6-104 Ball, Crank Handle - Large
- 3. 3950-22 Cross Feed Crank & Handle Assembly (Includes Item 2)
- 4. 114493 Hex. Jam Nut, 5/16-24
- 5. 127555 Screw, Hd/less Set (Cup Pt.), #8-32 x 3/16
- 6. M6-17 Carriage Graduated Collar
- 7. M6-46 Bearing, Carriage Slide Screw
- 8. 127554 Screw, Hd/less Set (Cup Pt.) #8-32 x 1/8
- 9. M6-74 Washer, Carriage Screw Thrust
- 10. 106958 #1 Woodruff Key, #204
- 11. M6-36A Carriage Slide Screw
- 12. 981-116 Screw, Hd/less Set (Dog Pt.), (4 Req'd), #10-32 x 5/8
- 13. 10-226 Nut, Gib Screw (4 Req'd)
- 14. 147-002 Carriage
- 15. M6-38 Cam, Split Nut
- 16. 9-210 Ball, 3/16 Dia.
- 17. 697-031 Spring
- 18. 456813 Screw, Hd/less Set (Cup Pt.), 1/4-20 x 3/16
- 19. M6-29 Lever, Split Nut
- 20. Screw, Fil. Hd. Mach., 1/4-20 x 3/4 (2 Req'd)
- 21. 711-017 Shim, Carriage - Front (.002")
- 22. 711-018 Shim, Carriage - Front (.003")


ITEM NO. PART NO. DESCRIPTION

- 23. 106321 Screw, Hex. Hd. Cap, 1/4-20 x 1-1/8
- 24. M6-57 Gib, Carriage
- 25. 110486 Screw, Fil. Hd. Mach., #10-24 x 3/8 (6 Req'd)
- 26. M6-55 Plate, Carriage Bearing
- 27. 711-015 Shim, Carriage - Rear (.002")
- 28. 711-016 Shim, Carriage - Rear (.003")
- 29. M6-12A Nut, Split (2 Req'd)
- 30. M6-13A Guide
- 31. M6-14 Clamp, Carriage
- 32. 446142 Washer, Plain 3/16
- 33. 437302 Screw, Fil. Hd. Mach., 1/4-20 x 11/16 (2 Req'd)
- 34. M6-54 Plate, Carrier Bearing
- 35. M6-68 Pinion, Shaft
- 36. M6-11 Gearcase
- 37. 142485 Groove Pin, 1/8 x 5/8 (2 Req'd)
- 38. M6-102 Gear
- 39. M6-67 Pinion, Carriage Handwheel
- 40. 106749 Woodruff Key #404
- 41. 9-104 Handle
- 42. 113955 Screw, Rd. Hd. Mach., 1/4-20 x 1/2
- 43. M6-93 Washer, Change Gear
- 44. 3950-20 Handwheel & Handle Assembly (Includes Item 40)
- 45. 3950-21 Carriage Travel Gear Bearing & Gear Assembly (W/Out Pins)
- 46. M6-12AX Half Nut Assembly






# CRAFTSMAN 6" METAL TURNING LATHE, MODEL No. 101.21200

## HEADSTOCK ASSEMBLY



## TUMBLER GEAR BRACKET ASSEMBLY 3950-25



ITEM NO. PART NO. DESCRIPTION

### HEADSTOCK ASSEMBLY

1.	M6-101-16	Gear, Change (32-T) (Small 16-T)
2.	641-082	Retainer, Ring
**3.	102581	Screw, Soc. Set, 5/16-18 x 3/8 (Cup Pt.) (2 Req'd)
4.	064-017	Bearing, Ball (2 Req'd)
5.	341-374	Gear, Spindle Back (Large) (62-T) (Small 32-T)
**6.	140867	Screw, Set Screw, #10-24 x 3/16 (Cup Pt.) (2 Req'd)
7.	123-140	Collar, Spindle
8.	560-194	Pulley, Spindle
9.	049-196	Bushing, Spindle Pulley (2 Req'd)
10.	141-023	Coupling, Direct Drive
11.	M6-257	Spring
12.	M6-214	Ball, 1/8 Dia.
13.	641-025	Retainer, Ring (2 Req'd)
14.	641-107	Retainer, Ring
15.	049-107	Bushing (2 Req'd)
16.	W30-16	Oiler, Ball (2 Req'd)
17.	341-375	Gears, Back (58-T)
18.	641-080	Retainer, Ring (3 Req'd)
19.	700-333	Shaft, Belt Tension Pulley
20.	10-264	Bushing
21.	560-196	Pulley, Belt Tensioner
22.	9414320	Washer, 1/4 Plain
23.	932-155	Washer, Belt Tension Shaft
**24.	109084	Hex. Nut, 1/4-20
25.	383-017	Headstock
26.	700-332	Shaft, Backgear Eccentric
27.	702-162	Sleeve, B. G. Eccentric Shaft


ITEM NO. PART NO. DESCRIPTION

28.	102570	Screw, Soc. Set, 1/4-20 x 3/8 (Cup Pt.)
29.	452-063	Lever, Backgear Shift
30.	9-61	Spring (2 Req'd)
31.	9-210	Ball, 3/16 Steel (2 Req'd)
**32.	106749	Woodruff Key, #404 (2 Req'd)
33.	9-88	Center #2 MT
34.	701-083	Spindle, Headstock
35.	536-049	Nameplate, Craftsman-Sears
**36.	145366	P. K. Drive Screw, Type "U", #2 x 3/16 (2 Req'd)
37.	130-065	Chart, Threading & Speed
38.	051-075	Belt, Spindle
39.	560-195	Pulley, Drive
**40.	426311	Groove Pin, 3/32 x 7/16
41.	441-072	Knob
42.	702-163	Sleeve, Tumbler Index
43.	58-63	Spring
44.	L3-23	Plunger, Rev. Tumbler
45.	700-331	Shaft, Tumbler Gear Bracket
**46.	109084	Nut, Hex., 1/4-20 (2 Req'd)
47.		Screw, HD/Less Set, 1/4-20 x 3-1/4 (Cup Point)
48.	041-463	Bracket, Tumbler Gear
49.	114604	1/4 External Shakeproof Washer
50.	3950-11	Tumbler Gear Studs & Plate Assembly
51.	102764	Screw, Flat Hd. Cap, 1/4-20 x 3/4 (hex. soc. type)
52.	M6-101-20	Gear, Change (20-T)
53.	M6-101-24	Gear, Change (24-T)
54.	3950-10	Guard & Knobs Assembly
55.	3950-25	Tumbler Gear Bracket Assembly

••Standard hardware item - may be purchased locally.

# CRAFTSMAN 6" METAL TURNING LATHE, MODEL No. 101.21200

## BED ASSEMBLY



ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------

### BED ASSEMBLY

- |       |         |  |
|-------|---------|--|
| ** 1. | 106320  | Screw, Hex. Hd. Cap., 1/4-20 x 7/8 (4 Req'd)             |
| 2.    | 294-016 | Foot (2 Req'd)   |
| ** 3. | 153978  | Screw, Phillips Fill. Hd. Mach., 5/16-18 x 7/8 (4 Req'd) |
| 4.    | 058-039 | Bed, Lathe   |
| 5.    | 536-024 | Nameplate, Model Number                                  |
| ** 6. | 145366  | Screw, P. K. Drive (Type "U"), #2 x 3/16 (2 Req'd)       |


ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------

- |        |        |  |
|--------|--------|--|
| 7.     | M6-328 | Screw, Spec. Flat. Hd. Mach. (5 Req'd)         |
| ** 8.  | 142484 | Groove Pin, 1/8 x 1/2 (2 Req'd)                |
| 9.     | L9-86  | Carriage Traverse Rack                         |
| 10.    | M6-16  | Feed Screw Bearing                             |
| ** 11. | 114353 | Screw, Fill. Hd. Mach., 1/4-20 x 1/2 (2 Req'd) |
| ** 12. | 103319 | 1/4 Spring Lock Washer (4 Req'd)               |

\*\* Standard hardware item - may be purchased locally.

# CRAFTSMAN 6" METAL TURNING LATHE, MODEL No. 101.21200

## LEAD SCREW & FEED GEAR ASSEMBLY 3950-26



ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------

### 3950-26 LEAD SCREW & FEED GEAR ASSEMBLY

**1.	109084	1/4-20 Hex. Nut (3 Req'd)
2.	M6-93	Washer, Change Gear (3 Req'd)
**3.	102711	1/4-20 x 1 Screw, Headless Set (Cup Pt.)
4.	3950-16	Feed Screw & Collar Assembly
**5.	106749	#404 Woodruff Key
**6.	109090	1/4-20 x 1 Bolt, Carriage
7.	M6-165	Spacer, Gear (3 Req'd)
8.	M6-101-64	Gear, Change (64-T) (2 Req'd)
**9.	106962	1/4-20 x 3/8 Screw, Hex. Hd. Cap
10.	M6-70	Bushing, Compound Gear (2 Req'd)
11.	M6-101-20	Gear, Change (20-T)
12.	M6-73	Sleeve, Change Gear (2 Req'd)
13.	M6-101-48	Gear, Change (48-T)
14.	M6-101-24	Gear, Change (24-T)
15.	041-464	Bracket, Change Gear


ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------

**16.	109092	1/4-20 x 1-1/2 Bolt, Carriage (2 Req'd)
17.	046-045	Bearing, Feed Screw-Left
**18.	221183	1/4-20 x 3/16 Screw, Soc. Set (Cup Pt.)
19.	L2-682	Collar
**20.	114353	1/4-20 x 1/2 Screw, Fill. Hd. Mach. (2 Req'd)
21.	M6-101X	Change Gear Assembly
22.	M6-101-32	Gear, Change (32-T) (2 Req'd)
23.	M6-101-36	Gear, Change (36-T)
24.	M6-101-40	Gear, Change (40-T)
25.	M6-101-44	Gear, Change (44-T)
26.	M6-101-46	Gear, Change (46-T)
27.	M6-101-52	Gear, Change (52-T)
28.	M6-101-54	Gear, Change (54-T)
29.	M6-101-56	Gear, Change (56-T)

\*\* Standard hardware item - may be purchased locally.

# CRAFTSMAN 6" METAL TURNING LATHE, MODEL No. 101.21200

## TAILSTOCK ASSEMBLY 3950-24



### 3950-30 TAILSTOCK & BASE ASSEMBLY

#### CONSISTS OF:

- 831-013 Tailstock (1)
- 10D-60 Tailstock Base
- Gib Adjusting Screw (2)
- M6-6 Tailstock Base
- M6-129 Tailstock Gib
- \*\*110500 Screw, Rd. Hd., #10-24 x 1/2 (2)

ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------

#### 3950-24 TAILSTOCK ASSEMBLY

** 1.	109189	Screw, Square Hd. Mach., 3/8-16 x 2-1/2
** 2.	110500	Screw, Rd. Hd. Mach., #10-24 x 1/2 (2 Req'd)
3.	M6-7	Tailstock Clamp
4.	M6-129	Tailstock Gib
5.	10D-60	Tailstock Base Gib Adjusting Screw (2 Req'd)
6.	M6-6	Tailstock Base (Must order 3950-30)
7.	9422797	Roll Pin, 1/8 x 5/16
8.	L2-80	Center, #1 M. T.
9.	M6-8	Tailstock Ram
10.	M6-45	Tailstock Ram Lock Sleeve
11.	M1-47	Arbor Support Lock Handle
12.	831-013	Tailstock (Must order 3950-30)
** 13.	106749	Woodruff Key, #404
14.	9-104	Handle
** 15.	9414201	Nut, Hex. Conelock, 3/8-16

ITEM NO.	PART NO.	DESCRIPTION
----------	----------	-------------

16.	3950-20	Handwheel W/Handle
17.	M6-30	Tailstock Screw Bearing
18.	3950-17	Screw Tailstock Ram W/Collar
** 19.	102635	Hex. Nut, 3/8-16
** 20.	9414321	Washer, 5/16 Plain
21.	M6-44	Tailstock Ram Lock Sleeve
22.	102384	Screw, Hd./Less Set, 1/4-20 x 1-3/4 (Oval Pt.) (2 Req'd)
23.	109151	Screw, Square Hd. Mach., 1/4-20 x 1-3/4

#### MISCELLANEOUS PARTS

Not Part Of This Assembly

24.	937-018	Wrench
25.	937-020	Wrench
* 26.	M6-312	Wrench

\*\* Standard hardware item - may be purchased locally.

**Sears**

# **6" METAL TURNING LATHE**

**MODEL NO.  
101.21200**

**Sears  
SERVICE  
is at  
YOUR  
SERVICE  
wherever YOU  
live or move  
in the U.S.A.**

**CAUTION:  
READ RULES FOR SAFE  
OPERATION AND  
INSTRUCTIONS  
CAREFULLY**

## **How to ORDER Repair Parts**

The Model Number will be found on a plate attached to your Lathe at the right end of the bed. Always mention the Model Number when requesting service or repair parts for your Craftsman 6" Metal Turning Lathe.

All parts listed herein may be ordered from any SEARS, ROEBUCK AND CO. or SIMPSONS-SEARS LIMITED retail or catalog store. If the parts you need are not stocked locally, your order will be electronically transmitted to a Sears Repair Parts Distribution Center for expedited handling.

**WHEN ORDERING REPAIR PARTS, ALWAYS GIVE THE  
FOLLOWING INFORMATION:**

- |                     |                 |
|---------------------|-----------------|
| 1. PART NUMBER      | 3. MODEL NUMBER |
| 2. PART DESCRIPTION | 4. NAME OF ITEM |

### **CRAFTSMAN PRODUCTS:**

**CRAFTSMAN 6" METAL TURNING LATHE FULL ONE YEAR  
WARRANTY**

If, within one year from the date of purchase, this Craftsman 6" Metal Turning Lathe fails due to a defect in material or workmanship, we will repair it free of charge.

This warranty service is available by simply contacting any Sears store or Service Center throughout the United States.

Sears, Roebuck and Co.

---

**Sold by SEARS, ROEBUCK AND CO., Chicago, IL. 60684 U.S.A.  
and SIMPSONS-SEARS LIMITED, Toronto, Ontario, Canada.**

---