

GISHOLT TURRET LATHE GUIDE

CARE AND TOOLING



THE
JOHN CRERAR
LIBRARY

GISHOLT TURRET LATHE GUIDE

for
CARE AND TOOLING

GISHOLT TOOLS

TURRET LATHES
AUTOMATIC TURRET LATHES
VERTICAL BORING MILLS
UNIVERSAL TOOL GRINDERS
HORIZONTAL BORING AND DRILLING
MACHINES
DOUBLE EMERY GRINDERS

TOOL POST TOOL HOLDERS
REAMERS (SOLID ADJUSTABLE)
Shell, Hand, Chucking
BORING BARS (ADJUSTABLE CUTTER)
CHUCKS

SPECIAL TOOLS, JIGS AND FIXTURES

PERIODOGRAPH
Workman's Time on Job Recorder

Gisholt Machine Company

General Offices

MADISON, WIS., U. S. A.

BRANCH OFFICES

50 Church St., New York City
208 S. LaSalle St., Chicago Ill.

WORKS

Madison, Wisconsin
Warren, Pennsylvania

387
RAGBRO 380L
V8A88L

Copyright, 1917, by
GISHOLT MACHINE COMPANY

Preface.

This book has been compiled for the use of operators and those who are in touch with Gisholt Turret Lathe work.

Our intention has been to arrange the suggestions in a way most beneficial to all those interested in the operation and care of Gisholt Turret Lathes and tools.

Tooling, which is an almost inexhaustible subject, is treated quite thoroly; there are illustrations of standard and special tools for rough and finish turning, facing, boring and reaming, giving proper allowances between rough and finish cuts so as best to maintain uniformity of sizes and quality of finish.

All of the articles illustrated have been successfully worked out in practice and many of them are being used today.

Possibly very few of the tools shown will exactly fill your requirements without some modification; therefore, the book must be accepted as a *guide* only, and we hope it will prove a satisfactory reference in selecting tool equipment for Gisholt Turret Lathes.

We want to co-operate with you in getting the very best results from our lathes and ask you to feel free at all times to confer with us personally or by mail.


21.94
R701

414248


337

Page 6
GISHOLT MACHINE COMPANY
MADISON, WIS.


Gisholt Machine Company



Gisholt Main Works, Madison, Wis.




Pattern Shop and Foundry, Madison, Wis.



Gisholt Northern Works, Madison, Wis.



Gisholt Warren Works, Warren, Pa.




Interior View—Main Works




Interior View—Main Works



Locker Room



Gisholt Club Room



- A8. Chuck Scroll Pinions.
- B1. Carriage Apron Hand Wheel.
- B12. Cross Feed Tumbler Lever.
- B26. Carriage Apron Feed, Friction Dog Handle.
- B31. Carriage Apron, Thread Cutting Pull Pin Lever.
- B35. Carriage Apron Feed Trip Lever.
- B36. Cross Feed Friction Star Nut.
- B60. Cross Feed Screw Hand Wheel.
- B64. Drill Support.
- B71. Tool Post Elevating Handle.
- B76. Carriage Right Front Gib Clamping Screw.
- B112. Carriage Stop Bar Stop Carrier.
- B118. Carriage Stop Bar on Bed.
- C4. Turret Clamp Ring Bracket Handle.
- C6. Turret Apron Pilot Wheel.
- C27. Rapid Traverse Friction Operating Lever.
- C34. Turret Slide Front Gib Clamp Screw (Left).
- C47. Turret Stop Bar Positive Stop Adjusting Nut.
- C51. Turret Apron, Feed Trip Link.
- C57. Turret Apron, Feed Change Lever.
- C60. Turret Apron, Feed Friction Dog Handle.
- C97. Turret Locating Pin Pinion Tappet.
- C99. Turret Stop Bar Stop Screw Carrier.
- C100. Turret Stop Bar.
- E19. Feed Reverse Lever.
- E83. Feed Change Lever.
- H29. Back Gear Shaft Lever.
- H38. Headstock Friction Lever.

The Gisholt Turret Lathe.

USES AND ADVANTAGES.

The tool post carriage has a four sided turret tool post, drill support, and taper attachment. The turret slide carries a hexagonal or six sided turret head.

This construction permits the use of multiple tools and doing any combination of the three operations, boring, turning, and facing at the same time.

Bearing this in mind, the necessity of securely chucking the work is easily appreciated. Many methods of chucking, using specially fitted jaws, bonnets and face plate fixtures are shown in the chapter on chuck equipment.

The four sided tool post and six sided turret head facilitate the carrying of a number of tools at a positive setting, which insures uniformity in the work done. This eliminates the necessity of constantly calipering and measuring to get the sizes wanted.

In the four sides of the tool post, may be clamped tools to properly break the scale and remove enough stock to prepare the casting or forging for the finishing tools. When the conditions warrant, finishing tools also may be carried in the tool post.

With the aid of the carriage stops and the graduated dial on the cross feed screw, an accurate degree of uniformity may be maintained in boring, turning and facing.

On the six sides of the turret head, may be mounted drills, boring bars, reamers, tap and dies: Also facing heads, which, when properly supported, may be arranged with arms and cutters for boring, turning and facing various diameters and shapes. A screw adjustment in these arms makes it possible to obtain very accurate settings.

Automatic adjustable stops are provided for each face of the turret. By the use of these stops and those provided for the tool post, *the mental strain on the operator is reduced to a minimum*, because the care and attention necessary is so much less than that required when single tools are used, and changed to obtain each accurate dimension.

When the machines are arranged in groups or batteries, a tool setter can take care of a number of machines, the exact number being governed by the frequency of changing of jobs. After setting the machines up, men of absolutely no experience may be taught in a reasonable length of time to operate and do just as much, and as good work as the tool setter.

In summing up the uses of the turret lathe, the foremost considerations would be to securely chuck the work, properly break the scale with suitable roughing cutters and tools, and afford ample support for all tools, especially boring bars and facing heads.

Care and Operation of Machines.

INSTALLATION.

The floor on which the lathe is placed should be firm enough so that it will not vibrate excessively. This will insure the machine running more smoothly and working more satisfactorily, especially when doing extra heavy duty or running at a high speed.

The lathe should be set perfectly level, and, when belt driven, parallel with the countershaft.

When installing a group or battery of lathes, sufficient room should be allowed between the machines for the operator and for placing rough and finished work. Sometimes this is over-looked until it is too late, and results in a crowded department, also, unquestionably, it lowers production.

Before putting the belts on a new machine, all the grease or rust preventive should be removed from all surfaces with kerosene and the working parts well oiled.

OILING.

Proper oiling of machinery is *Most Essential*.

It is always a good thing to remember that wherever there is a revolving, sliding or moving bearing of any kind, provision for lubrication of some kind should be made; and these bearings are more readily found by one familiar with the machine.


When the demonstrator is called upon to "break in" or instruct a new operator, usually he will begin by showing the operator where to find the oil holes and how to reach them. This is done without thinking how much previous experience the operator may have had on other machinery. Some resentment may be shown occasionally but this should not be, as the sole intention of the demonstrator is to assist.

The oiling of the machine always should be given the most careful attention of the operator. It is unnecessary to flood a bearing with so much oil that it will run down over the outside of the machine and onto the floor, but the oiling should be done at regular intervals. Always bear in mind that oil is cheaper than repairs.

The time lost during the repairing of a machine is very often of more consequence than the cost of new parts or the repairing of the old ones.

When oiling turret, the oil hole in top of the turret head should be towards front of machine or the operator's position. When oiled in this position, the oil runs down to turret spindle, lubricating it.

Moral: *Good care of machinery saves money, time and trouble.*



SECTION OF HEADSTOCK
FOR GISHOLT TURRET LATHE
GISHOLT MACHINE Co.

MADISON, WIS

SHEET No. 10250^A

SKETCH No. 16

ADJUSTMENT.

When a machine is shipped from the factory, it is properly adjusted for running, but, as many uncalled for and unforeseen things may happen between the time it leaves the factory and its installation in the customers plant, it is always advisable to try all adjustments before starting the machine.

HEADSTOCK.

The spindle bearings should be adjusted differently for various classes of work; for instance, if small work is being done or work that requires high speed, the bearings should be loose enough so as not to become hot to the touch of the hand.

An ideal adjustment is to have the bearings slightly warm and still have the spindle revolve freely. If the bearings run a little warm and maintain an even temperature it is an indication that the bearings are properly adjusted.

Then, when heavy, large diameter work is being done, the bearings should be pulled up a little tighter, as less clearance is required at the slower speed. By careful attention along this line, the bearings will wear a great deal longer and produce much better work.

The adjustments of headstock friction clutches are made as follows:

By turning H7 adjusting nut (right hand thread) toward the cone, the high speed friction clutch is tightened, and turning H46 adjusting nut towards gear will tighten intermediate speed friction clutch.



For adjusting headstock bearings and clutches see sketch No. 16, page 12A.

FEED BOX.

The change gears in feed box, as shown in figure 1868, page 14, should be thoroly cleaned and readjusted.

To change the gears in feed box proceed as follows: First loosen stud "A" and swing quadrant "B" back as far as it will go thus throwing gears "X" and "Y" out of mesh. Second loosen stud "C" and raise gear "Y" up as far as it will go and slightly tighten stud "C". Third loosen nut "D" and remove open washer "E". The change gear "Z" may now be removed and the one selected put in its place. After which replace washer and nut and tighten. Next properly mesh gears "Y" and "Z" and tighten stud "C". Next swing quadrant up until gears "X" and "Y" mesh properly and securely tighten stud "A". The changes are always made with the gear "Z" to get the threads and feeds as shown on the chart. The gear "X" may be changed for special pitch threads not shown on chart.


The use of the change gears and threading is further explained under head of "Thread Cutting and Feed Changes", page 176.



TURRET.

See figure 1869, page 14. C89 turret slide gib (rear) can be properly adjusted by pulling up all the adjusting screws C35, until the turret slide is tight, then loosening up the adjusting screws, a little at a time until slide works freely. The clamp screws C37, on the back of the slide should then be tightened, in order to hold the adjustment.




The turret feed friction adjustment is made with C21 catch screw in C51 trip link. (See figure 1870, page 15.)



POWER TRAVERSE

The type of power traverse as shown in view 1266 contains two nuts, one right and one left hand—C70 and C71, which run on F1 rapid traverse screw (Shown in view 1280), page 225. The clutches on these nuts are simple split ring frictions and are adjusted by set screws on the underside of C79 rapid traverse friction housing. (See figure 1871, page 16.)

The screw, indicated by "C", will adjust the clutch which drives the turret back from the chuck and the one indicated by "E" drives forward. This is the order in which the power traverse is assembled but as these traverse nuts are interchangeable it is possible to get them assembled wrong if the housing "C79" is dismantled at any time. This would reverse the movement of the turret slide when the traverse clutches are engaged.



Care should be taken to get the proper adjustment. These clutches should not be set up too tight.


TOOL POST CARRIAGE.

B86 carriage gib (rear) should be adjusted the same as the turret slide gib, as described in a preceding paragraph, under "turret adjustments."

B84 cross slide gib can be adjusted by pulling the adjusting screws "A" up until B85 cross slide works hard. Then they should be released until the proper adjustment is obtained. Tighten adjusting lock screws "B". (See figure 1872, page 16.)

The carriage feed friction adjustment is similar to that of the turret feed friction, the adjustment being made with B79 lever catch, in 835 trip lever. (See figure 1873, page 16.)

By adjusting screws "B" and "C" in yoke of B35 carriage feed trip lever (See figure 1873, page 16) the power feed on tool post carriage can be automatically tripped at various distances from the positive stop.



COUNTERSHAFT.



The countershaft clutches are adjusted by the set screw J15 in J13 friction ring expanding pin dog. (See figure 1874, page 17.)

OPERATING.

Figure 1783, page 10, is a cut of a standard Gisholt Turret Lathe. The operating levers are indicated by arrows which are numbered; the names will be found at bottom of picture.

Three spindle speeds may be obtained without shifting the belt or changing the motor speed. They are called, high speed, intermediate speed, and slow speed.

At the high speed, the spindle is driven thru a friction clutch in the cone. This clutch is engaged by moving the operating lever H38 to the left as is shown in figure 1875, page 18.




At the intermediate speed, the spindle is driven thru a friction clutch in the clutch gear at the large end of the cone. This speed is obtained by moving the operating lever H38 to the right as is shown in figure 1876, page 18.

At the slow speed the spindle is driven by a ring gear on the back of the chuck. This speed is obtained by sliding the back gear shaft, (which has pinion cut on the end) to the right, with the lever H29. The other lever H38 being in a neutral, which is a vertical, position as is shown in figure 1877, page 19. The pinion on the back gear shaft will mesh more freely with ring gear on back of chuck, if the spindle is revolving slowly. For this reason it is advisable to start the spindle at the intermediate speed, returning the operating lever to a neutral position before attempting to engage the slow speed.

The operator should never leave the machine for any length of time while it is running. Nor should he leave the machine with the chuck wrench in the chuck.

Carriage feed is engaged by raising the handle B26 up until the set screw in the trip lever B35 catches under the catch pin in the B26 handle, as shown in figure 1878, page 20.

Both the carriage and turret feeds may be released by hand as well as automatically.



The carriage feed may be released by hand by moving B35 trip lever to the left, allowing the B26 handle to drop as shown in figure 1873, page 16. The tool post cross feed is engaged by turning the star nut B36 to the right, and disengaged by turning it to the left. Star nut B36 is shown in figure 1880, page 20. Between the cross feed hand wheel and this star nut, is located a tumbler lever B12 by which the cross feed is reversed. There also is a neutral position for this lever.


The turret feed is engaged by lifting up handle C60 until the screw in trip link C51 catches under the catch pin in the C60 handle, as shown in figure 1870, page 15.

The turret feed may be released by hand by pressing down on trip link C51 until the handle C60 drops, as shown in figure 1879, page 20.

TOOL POST CARRIAGE AND TURRET STOPS.

The question of stops is most vital as the turret lathe loses much of its effectiveness and usefulness in duplicate production, if adequate stops for the tools are not provided and used.

The stops provided on the Gisholt lathe are easily set, in fact it takes very little more time to set a stop than to scale or caliper a dimension. Time will be



saved (if the stops are used) if there are so few as six pieces in a lot to be machined.

Sometimes the castings or forgings to be machined cannot be chucked and located by any definite point, making it impossible to use the same stops for the carriage and turret on piece after piece. To take care of this condition, an adjusting screw with a knurled head is put in the end of carriage stop bar B118 (See figure 1880) page 20. By the use of this adjustment, it is possible to set all four carriage stop screws for the tool post tools, and move them all forward or back as required without changing their relations.

When this adjustment is being used, the regulation of the turret stops can be taken care of by a rod "A" (shown in figure 1881) page 22, bolted to the carriage and running back under the turret, serving as a turret stop. In figure 1881 it is clearly shown how this plan works out. Before this rod is made, it is best to get the tools for the job partly set up in order to get the correct length.



When this arrangement is used, it is necessary, of course, to use one carriage stop to adjust carriage to proper position in order to have the turret stops the same for each piece.

On jobs requiring considerable power to feed the turret tools into the work, it has at times been found easier to get the proper depth if a feeler is used in connection with the turret stops. The feeler is used between the turret stop adjusting nut C47 on stop bar C100, and the bridge on the turret slide. The positive stop is of course very reliable, but chances for error (which always exist everywhere) are reduced to a minimum if a feeler is used as shown in figures 1881 and 1882, page 22.

This is a very sensitive feeler and is put on our latest machines. You can easily make one of either cold rolled steel or drill rod and quickly apply to any machine.

All the stops for the turret may be changed without altering their relative positions one to another, simply by screwing the knurled nut "C47" forward or back, and being careful to allow enough space between the nut and the turret slide for the feed to trip automatically.

Occasionally you may want to use more than four stops for the tool post tools, especially if you have a job with several different surfaces to be faced. Suppose for example two faces are to be machined, one $\frac{3}{4}$ " nearer the face of chuck than the other, with only one stop available. Set the stop for the face nearest the chuck and then make a gage $\frac{3}{4}$ " thick and use between the stop screw and the stop bar. In figure 1880 is shown a gage at "A" illustrating the principle of this idea. You can also judge from this illustration how easy it would be to work out and use many combinations of these gages.



Meaning of the Terms "Cutting Speed" and "Feed"

Cutting speed is expressed usually in feet per minute and is the speed at which the material passes the point of the cutting tool. To find cutting speed multiply the diameter of the work in inches by 3.1416. This gives the circumference, which should be multiplied by the revolutions per minute and the product divided by 12 giving the result in feet per minute. For example, if the piece being turned is 18 inches in diameter and the spindle speed is 9 revolutions per minute $18 \times 3.1416 \times 9 \div 12 =$ feet per minute, as is shown in left hand margin.

$$\begin{array}{r}
 3.1416 \\
 18 \text{ inches} \\
 \hline
 251328 \\
 31416 \\
 \hline
 56.5488 \text{ circumference} \\
 9 \text{ revolutions per minute} \\
 12 \overline{) 508.9392} \quad 42.41 \text{ feet per minute} \\
 48 \\
 \hline
 28 \\
 24 \\
 \hline
 49 \\
 48 \\
 \hline
 13 \\
 12 \\
 \hline
 1
 \end{array}$$

A very easy way to obtain the approximate cutting speed is to leave off the fraction of 3.1416 and simply multiply the diameter in inches by $3 \times R. P. M.$ divided by 12. It is understood that this only gives an approximate cutting speed, but it is very easily figured.

The feed of the tools is the rate at which the tool advances in the work per revolution, and is expressed as .008" or $1/32''$, or $1/8''$ (or any amount) per revolution.

The proper feeds and speeds on any class of work can be determined by observing the life of the tool.

Roughing tools, generally speaking, when used anywhere near the limit, should be ground about twice a day, especially where it is necessary that they be set to

stops. If they are ground more than two or three times a day, a great amount of time will be lost in grinding and resetting. On the other hand, if it is not necessary to grind at least once or twice a day, they are not being used at the proper feeds and speeds and are not working up to their capacity.

The variations in feed will be governed by the following:

- 1st. The design of the piece being machined.
- 2nd. The chucking hold on the piece.
- 3rd. The amount of stock to be removed.
- 4th. The amount of scale on the casting or forging and the kind of material.

If too heavy a feed is used on castings or forgings of frail construction, the work will spring away from the tool causing a variation in size. An example of this is in the turning and boring of piston rings from a pot casting made long enough for several rings.

The chucking hold on the piece also has a great deal to do with the amount of feed used. A piece chucked in a way such that it is impossible to move it, makes it possible to use a feed limited only by the strength of the tool.

The cutting speed also helps to determine the amount of feed; furthermore, the amount of feed helps to determine the cutting speed.

If the tool is working near its capacity and the speed is increased, it will be found necessary to reduce the feed or grind the tools more often. If the cutting speed is decreased, the feed may be increased within reasonable limits the best results being obtained with heaviest feeds possible and cutting speed to suit so that it will not be necessary to grind the roughing tools more than two or three times a day.

Tooling

STANDARD TOOL EQUIPMENT.

Tooling is one of the most important factors in turret lathe practice. In fact, the success of turret lathes depends almost entirely on the proper tooling of the machines to meet the exacting requirements for duplicating parts and maintaining the required accuracy under actual working shop conditions.

For your convenience and assistance in selecting or designing tools for your Gisholt Turret Lathes, we have gone thru our drawing files and selected typical fixtures and tools (covering a large variety of work) that have been successfully used. Any modifications necessary to suit your particular work will undoubtedly suggest themselves to you.

The tools have been grouped together and arranged in the order in which they should be considered in making up an equipment for any piece to be machined.

First is shown a standard equipment which is recommended for chuck work, and second a standard equipment for work from bar stock. These tools will cover a large variety of work which does not require special tools and fixtures.

Then in order come:

Special chuck jaws, and chucking fixtures.

Tool post tools, tool holders, etc.

Special drill supports.

Drills, drill holders, etc.

Boring bars, standard and special; end bars; taper and radius boring bars; boring bar cutters and cutter heads.

Reamers, and reamer arbors, standard and special.

Facing heads with standard and special arms.

Facing head cutters and special heads.

Taps and dies with holders.

TIME AND TOOL ESTIMATES.

To accurately make time and tool estimates for turret lathe work, a certain amount of information is necessary that is not usually shown on the drawings.

The points most necessary, relative to this information, are taken up in the following questions and are fully illustrated in figure 30ZZ, page 26, particularly questions 1, 2 and 3.

When sending prints for time and tool estimates kindly follow these suggestions:

If possible make notes on the prints, with red or yellow pencil, outlining where each piece is to be machined. See example of guidance, page 26.

1. Question: How many pieces are to be made per lot per year?

5. Question: What limit either way from a given dimension will be allowed? Also, within what limits must the piece run?

Note: Sometimes the drawings do not have the limits shown.

6. Question: Are any surfaces finished before coming to the Gisholt? If so, indicate them by F. P.

7. Question: Is there any surface or point from which the customer wishes to locate? If so, indicate by "Loc."

8. Question: Are your taps standard thread, "V" thread or special size?

9. Question: Are pieces machined or ground to finished size?

10. Question: Is customer willing to make change in patterns for ease of chucking?

Note: For surfaces to be machined use the following symbols:

For "Finished Previously" use "F. P.", referring to question 6.

For "Locate" use "Loc."

For "Looks" use "Lks.", meaning 2 cuts but no size.

For "Balance" use "Bal.", meaning 1 cut but no size.

For "Fit" use "Fit", meaning 3 cuts .001 to .002 limit.

For "Polish" use "Pol.", meaning 2 cuts and polish.

For "File" use "File", meaning 2 cuts and file.

For "Clearance" use "Clr.", meaning 1 cut.

For "Grinding" use "Gr.", meaning 2 cuts with .006 to .01 limit.


Note: If cross-pin holes on pistons are to be bored on Gisholt, state whether bored before or after grinding.

STANDARD BORING AND TURNING TOOLS FOR GISHOLT LATHES.

Figure 1540, page 28, shows the standard set of tools for boring and turning plain, circular or cylindrical pieces such as gear blanks, sleeves or collars, and for general work within the range of the machine. When the variety of work requires it, this standard set forms an excellent basis for an outfit of special tools. The addition of a few cutters and reamers will adapt this set to a large range of special work. Reamers are not included in the set as a great many sizes would be required to provide any considerable range. The boring bar cutters furnished provide for ample variation in standard sizes.

The Gisholt Solid Adjustable Reamers are fully described beginning on page 148 and the Gisholt Boring Bars with adjustable and solid cutters are described beginning on page 124.

STANDARD BORING AND TURNING TOOLS FOR GISHOLT LATHES (continued)



TOOLS IN SET.


(Figures refer to Cut Numbers.)

- 1—2—3—Three Tool Post Tool Holders.
- 4—One Set 6 Tool Bits Formed and Ground.
- 5—One Set 6 Tool Bits Blank.
- 6—One Set 3 Universal Chuck Jacks.
- 7—One Set Hex Head Turret Screws.
- 8—One Set 3 Drill Holders.
- 9—Two Drill Sockets No. 4 Morse Taper.
- 10—One Drill Socket No. 5 Morse Taper.
- 11—One Drift.
- 12—Seven Pairs Expansion Boring Bar Cutters.
- 13—One Pair No. 4 Boring Bars.
- 14—One Lubricating Chuck Bushing.
- 16—One Reamer Arbor No. 4 Morse Taper.
- 17—One Reamer Arbor Support.

Boring Bar Cutters furnished in the set give the following range of holes for the various sizes of lathes:

13" Lathe ----- $1\frac{9}{16}"$ — $3\frac{1}{16}"$	28" Lathe ----- $2\frac{3}{8}"$ — $4\frac{1}{2}"$
21" and 24" Lathes ----- $2"$ — $3\frac{3}{4}"$	34" and 41" Lathes ----- $2\frac{7}{8}"$ — $5\frac{1}{2}"$

BAR TOOLS FOR GISHOLT LATHES



This illustration shows the Standard Set of Tools for Bar Work on Gisholt Lathes. This set is the result of our study of the requirements of many customers covering a large variety of work. Consequently it is so designed as to be easily adjustable and of great range.

TOOLS IN SET.


(Figures refer to Cut Numbers.)

- 1—One Rod Stand.
- 2—One Centering Sleeve.
- 3—One Bar Stock Feeder.
- 4—Five Tool Post Tools.
- 5—One Roughing Box Tool with Cutters.
- 6—One Finishing Box Tool with Cutters.
- 7—One Taper Forming Box Tool with Cutters.
- 8—One Die Head Holder.
- 9—One Drill Socket No. 5 Morse Taper.
- 10—One Drill Holder.
- 11—One Tap Holder.
- 12—One Cut Off Tool.
- 13—One Cut Off Tool Support.

Box Tools will take work as follows: (outside diameters)

21"—3½" Lathe	-----3⅞" x 13"	24"—6¼" Lathe	-----5⅞" x 16"
24"—4¼" Lathe	-----4⅞" x 15"	28"—6¼" Lathe	-----5⅞" x 17"

FACING HEADS AND ACCESSORIES



This illustration shows the Gisholt Universal Facing Heads and Accessories that may be used on a great variety of work, and serve as an aid in maintaining standard diameters, etc., on the work being finished.

TOOLS IN SET.

(Figures refer to cut numbers.)

20—Facing Heads located on the turret by a pilot and held by screws. All three arms have adjustment for length while the top and back arms have screw adjustments for setting diameters and top arm also has a removable tool block which may be set in different positions.

21—Cutters—one set of four blank facing head cutters.

22—Cutters—one set of four roughers, and four finishers. The shapes shown are those frequently used in facing heads and may be made from blank cutters.

23—Supporting arbors with bushing retaining collars, used for supporting facing heads, the best results being obtained when bushing and arbor bear directly in bore of work.

24—Supporting bushings held on supporting arbor by retaining collars, the outside made a slip fit in the bore of work.

26—Face plate arbor occasionally used; is held in chuck and is sometimes used to center work which cannot be conveniently chucked with jaws. Arbor runs in bushing held in facing head.

25—Taper bushings are used in facing heads to support face plate arbor.

27—Chuck bushing used in chuck to hold face plate arbors.

SETTING UP THE TOOLS ON THE MACHINE.

No matter how simple or how intricate may be the sequence of operations on any turret lathe job, the following plan will reduce to a minimum the chance for error as well as the labor.

To begin with, ascertain the number of pieces to be machined at a time, also the estimated total number. This will govern the outlay to be made for special equipment. Some work can be done better and more quickly with a few special tools in addition to the standard tools; consequently, special tools are desirable when a large number of the same piece is required. But when the standard tools will do the work and, the number of pieces is rather small, it is not advisable to make special tools as their cost would probably over-balance the saving in time of machining.

The chucking equipment is considered first, because, before cutting can be done, the piece must be chucked. We furnish with the machine a regular standard jaw shown on page 42 but frequently jaws especially fitted to the work will give the most satisfactory results. The standard jaw was adopted as it proved more applicable, generally, than any other shape. By referring to Chuck Equipment chapter, wherein are shown numerous types of jaws and several face plate fixtures, practical ideas may be formed as to how best to hold any particular piece. We want to impress on your mind very clearly the necessity of securely holding the work as this particular phase of tooling must be considered as an absolutely necessary foundation for every tool equipment. Points along this line which must not be overlooked, are the required size limits, and the points against which the piece must be located when chucked. As, when the size limits are close, the work must not be distorted by the pressure of the chuck jaws if true work is expected. Very often an inexpensive change in the pattern, which does not materially change the design of the piece, will greatly simplify the chucking.

After definitely deciding on the chucking method, the roughing tools for turning and facing must be considered. These are almost always held in the tool post. Tools for rough boring diameters too large to be bored with boring bar heads are also held in the tool post. A number of these tools of various shapes are shown.

When planning the turret tools, drills are the first in order, and to decide about this, one must know if the hole in the work is cast or forged solid or if it is cored. If solid, a two lip twist drill or something that will do the same work, is necessary. But if cored, a suitable core drill should be used, supported in the regular drill support. The core drill, however, is only needed for cored holes that are too small to allow a fairly rigid boring bar pilot to enter. The question of proper grinding of drills is discussed in "Drill" chapter, and a few special drills are shown in "Drill Support" chapter.

Next in order come boring bars. The nature of the work and quantity of pieces required will determine whether or not special bars are needed. In either case, we would, if possible, use the type shown in Boring Bar chapter. A few special bars are illustrated in this chapter from which ideas may be formed as to the bars best suited for the work. If the size limits of the hole are close, a roughing and finishing bar should be used with correct allowance between the roughing and finishing cutters. Allowances are noted in "Boring Bar" chapter.


Reamers are an important part of the turret tool equipment and should follow the finishing bars in holes requiring accurate dimensions. This subject is thoroly discussed in "Reamer" chapter, several special reamers being shown.

The facing heads are generally used in pairs, especially if the size limits are close. One, used to true the surfaces roughed with tool post tools and the other, for sizing the most accurate dimensions, and, if necessary, three can be used, altho often times only one is necessary to properly finish the work when a liberal tolerance in size is allowed. At all times they should be rigidly supported and set up as described in "Facing Head" chapter.

A very convenient way of setting the tools in the facing head when setting up a job, is to have a sample piece correctly finished, which will fit over the supporting arbor in the head, and serve as a gauge for setting the tools. In this way the tools may be set so only a minimum of adjustment will be necessary to obtain the sizes wanted.

This sample piece may sometimes be a help in other ways. For instance it may be put in the jaws and used as a gauge for setting stops, both for the turret and tool post tools, near enough so that very little adjustment is required for final setting.

Chucking



THREE JAW UNIVERSAL GEARED SCROLL CHUCK.

This chuck is very rigidly constructed and is used on nearly all Gisholt Turret Lathes. Changes have been made from time to time which have added to its life, rigidity and adaptability.

It may be used as a two jaw chuck by removing false jaw A22 and inserting either the number one or number three jaw bases.

Special shaped jaws may be made for irregular work which cannot be held in three jaws.

Various types of these jaws are shown in figures 86Z page 44, 88Z page 48, and 136Z page 52.


You will note (see figure 1856, page 33) the jaw base which we call the "dust proof jaw base" almost completely fills the slots in the body. At each end is a small felt block which fills the opening necessary to start the rack teeth of the jaw base in the scroll.

The bases are provided with cross slots and corresponding screw holes so that the top jaws may be set at different diameters. With this arrangement it is only necessary to move the bases a short distance in or out, thus keeping a majority of the base rack teeth in mesh with the scroll teeth at all times, and undoubtedly greatly increasing the life and strength of the whole chuck.


As the rack teeth and scroll are never exposed, chips cannot work in and cause the trouble which we know follows when foreign substance works into running bearings.

The regular equipment of these chucks includes one set each of standard reversible hard and soft top jaws, with the necessary wrench and screw driver.

DIMENSIONS AND WEIGHTS



Diameter Inches	Weight Pounds	"A" Inches	"B" Inches	"C" Inches	"D" Inches	"E" Inches
13 $\frac{1}{2}$	150	7	3	4 $\frac{1}{2}$	11 $\frac{5}{8}$	4 $\frac{1}{8}$
18	315	9	4 $\frac{3}{8}$	5 $\frac{3}{8}$	2 $\frac{3}{8}$	5 $\frac{1}{2}$
24	570	10 $\frac{1}{2}$	5	5 $\frac{11}{16}$	2 $\frac{3}{8}$	5 $\frac{1}{8}$
24	565	12 $\frac{1}{4}$	6 $\frac{3}{8}$	5 $\frac{11}{16}$	2 $\frac{3}{8}$	5 $\frac{1}{8}$
28	815	10 $\frac{1}{2}$	5	6 $\frac{1}{2}$	2 $\frac{1}{8}$	7
28	810	12 $\frac{1}{4}$	6 $\frac{3}{8}$	6 $\frac{1}{2}$	2 $\frac{1}{8}$	7
32	1180	13 $\frac{1}{8}$	6	6 $\frac{9}{16}$	2 $\frac{1}{8}$	7




FOUR JAW INDEPENDENT CHUCK.

This chuck is of very heavy, rigid construction, and is sometimes used in connection with the Gisholt turret lathe, but should only be used when the work cannot be handled with the regular three jaw chuck.

Its design embodies the "dust proof" feature same as is found in the three jaw scroll chuck. The jaw base practically fills the slot in the chuck and the top jaw may be adjusted to different positions, necessitating only a small movement of the jaw base.


Hard top jaws are almost always used with this chuck altho soft ones could be applied if necessary, and could be fitted readily to the work.

DIMENSIONS AND WEIGHTS



Diameter Inches	Weight Pounds	"A" Inches	"B" Inches	"C" Inches	"D" Inches	"E" Inches
13½	150	7	3	4½	1⅞	3⅞
18	310	9	3½	5½	2⅝	5½
24	490	10½	5	5½	2⅝	5½
24	485	12¼	6⅝	5½	2⅝	5½
28	720	10½	5	5¾	3⅝	7
28	715	12¼	6⅝	5¾	3⅝	7
32	900	13½	6	6	3⅝	7

DRILL SUPPORT CHUCK.



The chuck shown above is 6" outside diameter and has a 2" hole thru the center.

It is a three jaw, universal, scroll type, very rigidly constructed, and is generally used in the drill support, on the Gisholt Turret Lathe.

The jaw equipment usually consists of plain steel jaws, hardened and ground, altho soft jaws of any desirable shape may be used.

BORING AND FITTING JAWS.

The first subject to consider in selecting or designing an equipment of tools is that of chucking, and it is just as necessary to start at this point when planning subsequent operations of machining a casting or forging as it is necessary to lay a foundation when erecting a large building.

Very often the piece to be machined is of frail construction and must be held in a way to prevent distortion and insure a good true job after piece has been removed from chuck. To accomplish this result in some cases it is necessary to add a chucking ring to the casting and bore the jaws especially to fit. Again, the chucking problem is quickly solved by providing in the casting three holes of proper dimension in which to insert the jaws.

In connection with the chucking problem comes the order of operations, which sometimes influences the method of chucking. Some castings, if properly chucked, may be finished at one setting, while others will require as many as three or four chuckings before the piece can be finished, especially when the size limits are very close.


The first and most important point is to hold the work securely, and to accomplish this end, special jaws are often absolutely necessary.

Surfaces on which the jaws bear are usually tapered, caused by the draft on the pattern or in the forging dies, and this makes chucking difficult with the ordinary standard chuck jaw. However, by boring or turning the jaws to conform to this taper, the work may be held for very heavy cuts.

Jaws for rough castings and forgings should be corrugated and hardened, making what might be called the teeth, from $\frac{1}{32}$ " to $\frac{3}{64}$ " wide on top and from $\frac{1}{8}$ " to $\frac{3}{16}$ " wide at the bottom, and from $\frac{1}{16}$ " to $\frac{3}{32}$ " high. This type is almost always made of machine steel, carbonized and hardened, altho tool steel may be used with equally good results if properly hardened and drawn.

The teeth of the corrugated jaw sink into the work, and for this reason should not be used on finished work, altho it will hold a great deal better than a smooth one. An illustration of how the teeth leave their impression in the work is shown in figure 1570, page 38. This piece is about 7" long and a little less than 5" bore where chucked.

When this type of jaw is used under extra heavy duty, the pressure of the tool will cause the teeth to sink far enough into the work to loosen it slightly, necessitating a second tightening, altho the jaws may have been as tight as possible, at the start. In order to set the chuck jaws as tightly as possible, the wrench should be applied to all three pinions successively. Do not overlook this point. The standard wrench furnished should not be changed in any way.




The main object in boring or turning jaws is to have them conform to shape of the surface on which they are to bear. There are no doubt several ways in which this may be done satisfactorily. We shall, however, describe the method which has proved most practical and produced the best results.


An object of some kind should be gripped in the jaws as near as possible to the point where the jaws will take their bearings on the piece to be machined. As a standard equipment for this work we call your attention to figure 1883. Here we have a set of three studs and a steel ring. The studs are placed in the counterbored holes, one in each jaw, as shown, and the ring chucked in them. This sets the jaws in the proper position for boring. They should be tightened up on the ring with about the same pressure as will be used when chucking the work.

A greater accuracy is necessary when preparing jaws for chucking on finished work especially when it is desirable to have the chucked surface run true. The jaws should not be bored the exact diameter of the piece to be chucked but an allowance made for spring. This allowance will approximate .0015" to each inch of diameter on the chucking circle for finished surfaces and the allowance should be doubled for rough castings. For example, suppose the piece to be chucked is 4" diameter, the jaws should be left about .006" small when boring and .006" large when turning. If the jaws are being prepared for a rough casting, the allowance should be about .012" or $\frac{1}{64}$ ".

When the jaws are bored or turned on a large circle, the measuring must, of course, be done from the tool to the jaw, as is shown in figures No. 1883 and No. 1884.



It must be understood that these allowances are only approximate and cannot be depended on absolutely. To be sure of good results, the chuck pinion used to tighten the jaws should be marked when in the tightened position. And when




the jaws are tightened on the work the pinion should be in exactly the same position as when boring. If not, the jaws should be rebored or turned as the case may be and more or less stock left to take up the spring as required.

For chucking on finished surfaces, or second operation work, the same pinion should always be used to tighten the jaws on the work as was used to tighten

them on the ring when they were bored or turned. This will bring the scroll to the same position on the rack of the jaw base and the work will run true within .001", providing this method is carefully followed and the chucked surface is round and uniform in size. It may be necessary occasionally to rebore the jaws if large numbers of pieces are being machined at a time.

Figure 1884, page 39, shows the operator caliper the size of the jaws he is turning for the piece shown. Note the ring and stud plan is used for turning as well as boring, only the ring is chucked *on* the studs which is just the reverse of the boring operation. If a ring cannot be found suitable for the job, heavy, soft wire may be used to hold tension on the jaws.




When it is necessary to resort to the wire the jaws should be run in a half an inch or so from the circle on which they will be turned and the wire wound around and securely fastened. Then return the jaws to proper position being sure wire is tight and proceed to turn to proper size.

If jaws are taper bored or turned, use taper attachment. (See "Taper Attachment" Chapter, page 115.)


CHUCK JACKS.

We have found the use of chuck jacks very valuable on a large variety of chucked work. Figure 1885 shows a flanged hub chucked with soft jaws and with the flange supported by standard chuck jacks. These not only help support the flange against the tool pressure but serve to true the flange when chucking.


Figure No. 1887, page 41, shows a piece chucked internally and located by standard chuck jacks. The screws in the jacks are soft steel and are faced off true and square as is shown in figure No. 1886. The ring and studs which were used in boring the jaws are also shown in this figure.




In figure No. 90Z, page 58, at CK52a is shown a spring chuck jack stud. When only three chuck jacks are required the solid ones serve the purpose very well, but sometimes it is advantageous to use more than three. The spring studs are indispensable for this work as they automatically adjust themselves.




For example suppose we wanted to use 6 chuck jacks on the piece shown chucked in figure No. 1885, page 40. We would use 3 solid screw studs, which would remain stationary and three spring studs which would adjust themselves against the work and be tightened in place.




CK 1




CK 2




CK 3




CK 4




CK 5




CK 6




CK 7




CK 8




CK 9




CK 10




CK 11




CK 12




CK 13




CK 14



CK 15




CK 16



CK 17


85 Z




CK 18

Symbol and number refer to figures on page 42.


- CK1. Standard hard jaw furnished with machine.
- CK2. Soft jaw, one end bored thru, the other end bored to a shoulder.
- CK3. Jaw for large diameter work, used either hard or soft.
- CK4. Jaw for bevel gears, large and small, used either hard or soft.
- CK5. Jaw for work having chucking flange, such as piston ring pots, etc., large and small. Used either hard or soft.
- CK6. Hard jaw for chucking two diameters, set screw bears on larger diameter.
- CK7. Hard jaw used on taper surface, pointed set screw shown helps to hold work in jaws.
- CK8. Hard jaw for chucking in holes in web of gear or fly wheel.
- CK9. Hard jaw for chucking inside work and supporting flange.
- CK10. Hard jaw for chucking on hub between spokes.
- CK11. Hard jaw used in pairs for holding "T" shaped pieces.
- CK12. Hard jaw for chucking inside rim. One jaw of the set made wide to straddle spoke.
- CK13. Hard jaw with heel cut out to clear flange on work or for work that is to be back faced thru spindle.
- CK14. Hard jaw used in pairs for holding square work.
- CK15. Hard jaw for thin pieces, work is centered with jaws and clamped with set screws, preventing distortion.
- CK16. Hard jaw for inside taper surface.
- CK17. Hard jaw for long work.
- CK18. Hard jaw for holding inside of rim, setting work far enough away from chuck to back face rim with tool post.




CK 19




CK 20




CK 21




CK 22




CK 23




CK 24




CK 25



CK 26









CK 27



86Z


Symbol and number refer to figures on page 44.

- CK19. Hard jaw for long work, set screw used to center end next to chuck.
- CK20. Hard jaw for holding on flange. One jaw extra wide to straddle boss on flange.
- CK21. Hard jaw for holding gas engine cylinder with flanged end.
- CK22. Hard jaw used in pairs for holding irregular pieces with projection on one side.
- CK23. Hard jaws for gas engine bearing plate of irregular shape.
- CK24. Hard jaw for inside of pipe couplings, making six point bearing.
- CK25. Hard jaw for heavy chucking, gives better bearing in chuck slot when using old style short jaw base.
- CK26. Soft jaw for chucking on outside of thin work. A set of these jaws almost encircles piece.
- CK27. Hard and soft jaw combined, used when one set up of tools will do both operations, by reversing work in jaws.




Symbol and number refer to figures on page 46.


- CK28. Hard jaw for holding spherical shapes.
- CK29. Pair of jaws and blocks for rectangular work. The two jaw arrangement is used, giving universal movement to jaws. Screws in blocks are then adjusted to suit.
- CK30. Hard jaws for holding inside, large diameters. Two of cross blocks oscillate on the jaw and adjust themselves to work, while the third is solid and serves as driver.
- CK31. Hard jaws for irregular shape.
- CK32. Hard jaws for irregular shape.
- CK33. Hard jaws for taper surfaces. Two jaws cut away for clearance.




CK 34




CK 35



CK 36



CK 38




CK 37


882

Symbol and number refer to figures on page 48.


- CK34. Hard jaws used in pairs for rectangular shapes.
- CK35. Pair of hard jaws and blocks for holding cross-heads.
- CK36. Jaws either hard or soft, one end bored for handwheels, the other for wormwheels.
- CK37. Hard jaws for chucking on hub, one split to straddle rib.
- CK38. Pair of jaws slotted to straddle rib and arranged with set screws to hold on rib.




CK 39




CK 40




CK 41



CK 42




CK 43




CK 44




CK 45




CK 46




CK 47




CK 48




CK 49



CK 50




CK 51





CK 52

Symbol and number refer to figures on page 50.


- CK39. Reversible top jaw on which may be used the small slip jaws that were furnished with the solid type of jaw.
- CK40. Small slip jaw, used either hard or soft.
- CK41. Small slip jaw for holding thin work.
- CK42. Dust proof jaw base.
- CK43. Solid type jaw for chucking on outside diameter.
- CK44. Solid type jaw for chucking on inside diameter.
- CK45. Solid type jaw for long work, outside holding.
- CK46. Solid type jaw for long work, inside holding.
- CK47. Solid type jaw with hardened steel shoe for small diameter work.
- CK48. Small slip jaw for bevel gears, either hard or soft.
- CK49. Solid type jaw for holding in holes in gear web.
- CK50. Small slip jaw with driver.



CK-85



CK-86



136-Z

In figure CK85 is shown an auxiliary jaw held in a bonnet which is bolted to the face of the chuck.

The jaw oscillates on a cross pin in the bonnet and is actuated by the regular jaw as shown. A spring is used to keep the auxiliary against the standard jaw.

This equipment was made to hold a rear axle differential carrier. The flange on which the piece is chucked is approximately fourteen inches from the face of the chuck; the hub end is centered by a cone centering sleeve in the bore of the chuck.

It would be impossible to hold this piece securely in this manner with a standard jaw, as it would necessarily extend fourteen inches from the chuck, which would interfere with the free sliding action the jaw bases should have.

Figure CK86 shows a special set of two jaws used to hold a very irregular shaped automobile brake band support, held against very heavy cuts, and with the aid of a centering spider, the work was properly located for boring.

CENTERING SPIDERS.

The centering spider is a wonderful help in rapid chucking of a great many parts.

An irregularly shaped piece or extremely long work is more quickly and accurately chucked if a spider is used.






Figure Z—180 shows a long piece which is held at one end with jaws that are practically standard and at the other with set screws in a supporting bonnet bolted to the face of chuck. An external centering spider is used to center the outer end before setting the screws. Centering spider shown at "A".

First, the piece is put into the jaws, which are closed up to just touch the work. Second, the spider, which should be a snug fit, on the boring bar pilot is slipped into place and centered around the work as shown. Third, the screws in bonnet are set up tight with an even pressure on each screw. Of course, to do this, all



three screws must be set lightly against the work before any of them are pulled tight. Fourth, pull jaws up as tight as may be necessary to hold work.

Figure Z—181 is a very good illustration of how the same plan is used on the inside instead of outside. The nature of the work at hand will determine which way would work to the best advantage.

SUPPORTING SPIDERS.

Occasionally work is brought to the Gisholt lathe which is not only very irregular in shape but fragile in nature, so much so that when chucked, the jaws spring the work out of shape resulting in an untrue piece of work when finished.


Figure 182Z illustrates a casting such as mentioned. A supporting spider is shown at A which makes possible the rigid chucking necessary to hold this piece successfully, so as to prevent distortion.

Before the piece is put in the jaws it is laid on the floor or bench and the spider placed on the hub.


The three screws are tightened just enough to hold the spider in place.

Then the work is chucked with one screw of the spider under each jaw.

FACE PLATE JAWS.



SINGLE TONGUE TYPE




DOUBLE TONGUE TYPE







The face plate jaws shown above are most commonly used in connection with vertical boring mills and with face plate work on large engine lathes. Occasionally, however, they work in very nicely with the larger scroll chucks when the "two jaw" arrangement is used, thus forming a four jaw chuck, two jaws being controlled and operated by the scroll and the two independent jaws, each operated by its own screw.

The two shown are popular types from which ideas may be gathered in designing jaws to meet any particular requirement.

AUXILIARY JAWS.


We have found that heavy bar work requires more driving power than can be had from a scroll chuck. In recognition of this fact auxiliary jaws, shown in cut 1857, are often used with excellent results. The work is chucked and centered in the regular way by the standard jaws and then further clamped by tightening the screws in the auxiliary jaws.








Symbol and number refer to figures on page 58.


- CK51. Block used in jaw slot for bolting fixtures to chuck face.
- CK52. Chuck jacks used to locate and support work between jaws.
- CK52A. Spring chuck jack stud, see page 40 for description.
- CK53. Solid chuck bushing.
- CK54. Lubricated chuck bushing.
- CK55. Face plate arbor and bushing.




CK 56



CK 57




CK 58




91Z

Symbol and number refer to figures on page 60.

- CK56. Face plate blocks, used in bar work to assist jaws in holding bar.
- CK57. Scroll block, used with angle plate on chuck to adjust for center distance.
- CK58. Chuck plate and arbor for turning eccentric work after it has been bored.



CK 59




CK 60

92Z



Symbol and number refer to figures on page 62.

CK59. Chuck fixture for boring cross pin holes in pistons.


CK60. Chuck plate with square arbor.



CK 61



CK 62




93Z


Symbol and number refer to figures on page 64.

CK61. Chuck plate and clamps for holding long work for second operation.

CK62. Open chuck bonnet for long, irregular shaped work.



CK 63





CK 64

94Z

Symbol and number refer to figures on page 66.

CK63. Angle plate with counterweight for finishing automobile steering knuckles.


CK64. Angle plate for flanges.





Symbol and number refer to figures on page 68.

CK65. Chuck plate for turning engine eccentrics.


CK66. Fixtures, used in pairs for holding motor bonnets.



CK 67





CK 68



96 Z

Symbol and number refer to figures on page 70.




- CK67.** Chuck plate, arbor, and clamps for holding differential housings, brake drums, etc.
- CK68.** Chuck plate and taper arbor for steam pistons.



Symbol and number refer to figures on page 12.



CK69. Closed chuck bonnet for long work.

CK70. Angle plate and cradle for finishing valve bodies at one chucking.





Symbol and number refer to figures on page 74.

- CK71. Floating chucking fixture for holding rough shells while finishing inside.
- CK72. Internal chucking fixture or expanding mandrel for shells.
- CK73. Collet chuck for shells.



Symbol and number refer to figures on page 76.




- CK74. Swivel chuck plate for finishing eccentric piston rings. Plate is held in one position while pot is turned then swiveled to eccentric position and pot is bored and rings cut off. Stops for proper throw or eccentricity provided.
- CK75. Swivel chuck plate for boring valve seats in gas engine cylinder.



Symbol and number refer to figures on page 78.


CK76. Angle plate for boring 7 sided aeroplane crank cases.

CK77. Valve chuck.



Symbol and number refer to figures on page 80.

- CK78. Chuck plate with threaded arbor. After piece is screwed to proper position it is tightened by means of taper cross key.
- CK79. Revolving male cone center used in turret.
- CK80. Cone center used in drill holder.
- CK81. Female center used in drill holder.
- CK82. Male center used for centering outer end of work while chucking.
- CK83. Revolving male center used in drill holder.
- CK84. Female center used in turret.




STEADY REST

Steady Rests.

When chuck fixtures are made for extremely long pieces, it is generally advisable to provide a suitable steady rest to support the outer ends of the pieces.

Figure 247Z shows a substantial steady rest, made to support a long bonnet bolted to face of chuck. The part to be machined is shown at "M" and is approximately 36" long.

The work for which the bonnet was made, varied considerably in length and the bonnet was made in two pieces. Piece "A" is bolted to the chuck and remains fixed while piece "B" is made in different lengths to accommodate the length of the work. Piece "A" has three hand holes "C" equally spaced, thru which a rod may be inserted to lift the piece into the jaws.



The steady rest "D" supports on the outer end of the bonnet at "E"; the length of the bearing is approximately 6". This bearing of course could be changed to suit the requirements. The steady rest is bolted to the V's as shown at "H" and is moved back and forth according to the length of the work.


The bonnet and steady rest are made of cast iron and the bearing lubricated with grease thru the force feed grease cup shown at "K".

A felt washer is used at "L" to prevent dust working into the bearing and is held in place by a split steel washer.

This type steady rest has proved superior to all others we have used or seen used.

Figure 1433 shows a chucking fixture for a large valve approximately 30" long and a steady rest with a valve in place.

Figure 1434 shows the fixture with a clearer view of the steady rest. The rest is arranged with three rollers with sight feed oilers for lubrication.



On extremely heavy work we have found better results may be obtained if the rollers are omitted and a steady rest with a full circular bearing used, as previously shown in cut 247Z page 82 and described on page 83.





Figure 1685 shows still another steady rest used in practically the same way. The rollers are about four inches in diameter and run on pins two inches in diameter and are also lubricated with sight feed oilers.

SELF-LUBRICATING CHUCK BUSHINGS.



53Z

Prior to the development of the self-lubricating chuck bushing as shown in detailed cross section above, pilot bushings were a never ending source of annoyance.

The outside diameter of the Master Bushing which is of cast iron is ground to fit the bore of the chuck. The Master Bushing is bored to receive interchangeable *Pilot Bushings* as the boring bars have pilots of different sizes.

The *Pilot Bushing* which is usually made of cast iron is ground to a snug sliding fit on pilot of boring bar and remains practically stationary with the boring bar, while the Master Bushing revolves around it. An oil chamber in the Master Bushing keeps the bearing properly lubricated.

A felt plug in pilot bushing feeds the oil from reservoir in Master Bushing to pilot of boring bar.

A retaining washer is used to keep the *Pilot Bushing* in place. When *lubrication* is *not* used on the work a Leather Washer is supplied to remove chips or grit from the bar before it enters the bushing.

The self-lubricating chuck bushing is superior to the old style in several ways.

If the old style bushing is used, a full size bushing is required for each size of boring bar pilot. The bushings must be driven in and out the chuck when changing from one size to another.

With the self-lubricating type this change is more easily and quickly made. Simply remove retainer plate, change the pilot bushings and replace plate.

The constant wear on the boring bar pilot by the old style bushing soon causes a loose fit, resulting in a variance in the size of the work. This trouble is overcome by the self-lubricating type as the bearing is not on the bar, but between the outside diameter of Pilot Bushing and the bore of Master Bushing which is a well protected, well lubricated bearing.

The wear in the old style chuck bushing is often due to lack of proper lubrication, while, with a reasonable amount of attention, the Oil Chamber in the Master Bushing of the self-lubricating type will dispense with the troublesome question of oiling. The chamber may be filled readily without removing *Pilot Bushing* simply by removing either one of the Retaining Washer Screws.

The first cost of the self-lubricating style is more than that of the old style bushing, but as no oil is wasted in the self-lubricating type, the saving in oil alone will very soon pay for the extra initial cost.



Self-Lubricated Bushing

	Inches	Inches	Inches	Inches	Inches	Inches
Size Master Bushing. outside diameter*	3 $\frac{3}{8}$ +	3 $\frac{5}{8}$ +	4 $\frac{1}{8}$ +	5 +	6 +	6 $\frac{3}{8}$ +
Outside diameter of Pilot Bushing	2 $\frac{1}{4}$	2 $\frac{1}{2}$	3 $\frac{1}{8}$	3 $\frac{3}{4}$	4 $\frac{1}{2}$	4 $\frac{3}{4}$
Maximum size bore of Pilot Bushing	1 $\frac{7}{8}$	2 $\frac{1}{8}$	2 $\frac{3}{8}$	3 $\frac{3}{8}$	4	4 $\frac{1}{4}$

We are prepared to furnish the old style solid type chuck bushings as shown below. Some of these have a hardened steel core bushing pressed into the cast iron body. The others are plain cast iron bushings ground to size.



Regular C. I. Bushing




Hardened Steel Core

	Inches	Inches	Inches	Inches	Inches	Inches	Inches
Size Bushing, outside diam.**	3 +	3 $\frac{3}{8}$ +	3 $\frac{5}{8}$ +	4 $\frac{1}{8}$ +	5 +	6 +	6 $\frac{3}{8}$ +

* ** The outside diameters given are approximate only. When ordering, care should be used to specify the EXACT diameter of the hole or bore in the chuck and the bushing will be ground to suit.

Tool Post and Tool Post Tools.



THE WING REST.

Occasionally it is necessary to turn a piece of work so large in diameter that an auxiliary tool post, placed on the front side of the tool post carriage proves advantageous as it affords a support for the cutting tool, very close to the work.

The wing rest equipment includes a four sided, turret tool post similar in appearance to the regular cross slide tool post. See figure 1731.

As this arrangement was made primarily for turning large diameters, no power cross feed is furnished. The regular cross slide tool post is used for the general run of facing work, altho the wing rest tool post may be used for facing in short distances from the outside.

Turning tools for large diameters may be set a little above or below center without affecting their cutting qualities in the least. Therefore, no adjustment for height of tools is provided in the wing rest tool post.

CROSS SLIDE TOOL POST.

The regular cross slide tool post has an independent adjustment for height for each side as, on turning, boring and facing small diameters, it is quite essential that the tools be set to the correct height.

The tool post is used primarily to carry tools for rough turning and facing, and for boring diameters too large to be bored with boring bar cutters and cutter heads. It is also often used for finish turning, boring, facing, and forming various diameters and shapes.

TOOLS.

(For use in Cross Slide Tool Post.)

Some work will require that more than four tool post tools be used in the tool post. To meet this condition properly, the following suggestions are offered:

If specially shaped short tools can be used, as many as seven or eight may be held adequately. However, if the nature of the tool will not permit of its being shortened, it is necessary to change the tools in the tool post. In this case it is better, if possible, to confine the changing to one side only.

This idea may be carried out with any number of tools and still use the tool post carriage stops and index dial on the cross feed screw.

Tool post tools should be ground so that, when they are pressed against the back of the tool post slot, they will be in correct cutting position. An adjusting screw should be put in the butt end of each tool for locating the tool for length. The adjusting screw bears against a block set in the corner of the tool post or against another tool. See figure B45b, page 187.

Great care should be exercised in setting these tools so that they will not overhang their supports more than is absolutely necessary.

An over-hang of more than $1\frac{1}{2}$ times the height of the tool will cause undue strain.

When tools, such as cut off tools, extend far from the tool post, a suitable support should be provided. In figure 139Z, page 105 is shown an ideal support for cut off tools, and with slight modification this would serve very well for other over-hanging tools.


The clearance and top rake angles (see figure 174Z, page 89) have quite a bearing on the life of these tools. Valuable tables have been compiled by practical men, giving what might be called standard angles of clearance and top rake for different kinds of material, but many times the prevailing conditions make it necessary to deviate from these rules to get the best results.

FEEDS, SPEEDS AND GRINDING.

Feeds and speeds, are governed by the depth of cut, the amount of scale, the kind and hardness of material and the angles of clearance and top rake on the cutting tool. As all these conditions must be considered, the best place to obtain the correct cutting speed and feed is "right on the job."

For cutting cast iron, soft or medium steel, or aluminum, the cutting point of the tool should always be the highest, the top of the tool sloping down in both directions from this point. The exact angles depend on the kind and hardness of material; also the depth of cut and the feed used.

For examples of ideal cutting tools for cast iron, we shall start with the very hardest iron which is commercially used, and can be worked at a cutting speed of about twenty to twenty-five feet per minute. These tools should have from 5° to 10° side and end clearance (shown at "C" and "D" in figure 174Z) with a top rake of 2° to 5° .



A—Back Slope or Rake.

B—Side Slope or Rake.

C—End Clearance.

D—Side Clearance.

On some of the harder irons, the tool will work longer between grindings if used perfectly flat on top, but more power is required to feed this shaped tool into the work.

The angles of top slope or rake should increase as the hardness of the cast iron decreases. Tools with a top rake of 15° or 20° are often used with very good results on the softer grades of iron.

The clearance angles on tools for steel cutting are practically the same as for cast iron, while the top rake varies a great deal more.

Cutting tools for very hard steel should have little or no top rake. And in some cases, when turning extremely hard steel, the cutting point of the tools is ground lower than the back. This shape is called a negative rake and is never resorted to except for extremely hard material and brass, bronze and other metals of this nature.

As the steel decreases in hardness the top rake should be increased the same as with the cast iron cutting tools. A top rake of as much as 30° is often used on tools for cutting very soft steel.

By watching the location of the little pit which the chip forms on the top of the tool, the correct rake angle may be determined.

As soon as, or very shortly after, this pit wears thru to the cutting edge the tool will break down. The pit should start $\frac{1}{16}$ " or $\frac{1}{8}$ " back from the cutting edge. If it starts nearer than this, reduce the rake angle or round the point to a larger radius, which will throw the contact point of the chip farther back on the tool and the tool will wear much longer between grindings.

Metal cutting tools should not be used with square corners unless absolutely necessary; this condition is seldom, if ever, necessary in a roughing tool.

The relation between the side and back slope of the top rake is governed to some extent by the depth of cut and the feed used.

For instance, if a cut $\frac{1}{2}$ " deep were taken in cast iron or steel, the feed per revolution would be comparatively less than the depth of cut. A tool that would cut freely under these conditions would have more side slope (shown at "B" figure 174Z, page 89) than back slope (see "A" figure 174Z), and would allow the chip to roll away with less friction on the tool.

If a reversed condition is found, that is, a cut of only a few thousandths deep and the feed a great deal more, the best results would be obtained by using a tool with a greater back slope and very little or no side slope.


The back and side slope should be about the same when the depth of cut and the feed per revolution are the same.

The grinding of all tool post tools should be done accurately, and it should also be done quickly. The combination of these two essentials almost eliminates the use of the old style emery wheel.

You may know just the angle of the clearance and top rake the tool should have and, with the use of a bevel protractor or degree gauge, you may do this grinding by hand. Grinding tool post tools by hand is a time consuming operation and, when you have finished, you are not absolutely sure each face is just right or each cutting edge as straight as you would like to have it.


The Gisholt Universal Tool Grinder was designed especially for grinding tools to proper cutting angles, quickly and accurately.

Gisholt Universal Tool Grinder.



Belt Driven Gisholt Universal Tool Grinder

SPINDLE ADJUSTMENT OF UNIVERSAL TOOL GRINDER.



249-Z

The spindle boxes "A" and "B" are tapered on the outside to permit adjustment.

To adjust front spindle box "A," release adjusting nut "C" and tighten adjusting nut "D," both of which have right-hand thread.

To adjust rear spindle box "B," release adjusting nut "E" and tighten adjusting nut "F," both of which have right-hand thread.

The end thrust adjustment is made with adjusting nut "G," (right-hand thread), and when proper adjustment is obtained, retaining screw "H" should be securely tightened. The end thrust is contained in the adjusting nut "F" and adjustment of spindle boxes can be made without interfering with the end thrust adjustment.


The steel collar shown at "I" is keyed to the spindle and clamped against a shoulder on the spindle by retaining nut "J." On each side of steel collar "I" is fitted a fibre collar shown at "K" and "L" serving as an end thrust washer.

The packing shown at "M" is held in place by packing nut "N" (left-hand thread). The object of this packing is to prevent oil leakage, as well as make the bearing dust proof.

Felt washers shown at "O," "P" and "Q" serve to keep dust and grit from entering the main spindle bearings.

Care should be taken to see that the oil reservoirs "R" and "S" are kept full enough, so that the oil rings "T" and "U" always run in oil.

The oil rings "T" and "U" should always be in position on the spindle, so that they are revolving with the spindle and lift the oil for lubricating these bearings. The action of these oil rings may be observed if the screw plugs "V" and "W" are removed.




432 Z

Cross section showing Construction Details of Belt Driven Machine

TOOL GRINDING BY THE GISHOLT METHOD

In the first place we have a cup emery wheel (A) mounted directly on the spindle of the machine.

Just below this is a large pan (B). Mounted in the pan is a Universal adjustable tool holder (C) in which the tool-post tool to be ground is clamped the same as it would be in the lathe. This pan has two movements—one to and from the main column of the machine and actuated by a hand wheel (D)—the other, an



Rear View of Tool Grinder

oscillating motion of the pan about the axis of the hand wheel, for traversing the tool across the face of the wheel. This motion is obtained by an up and down movement of the handle shown to the right of the pan at (E).


Suppose we grind a tool—the one known as number thirteen on the chart—an ordinary square nose lathe tool, just to show the simplicity of grinding by the Gisholt Method.

We shall grind in the order of faces A, B, C and D, as shown on the chart.

The tool is held in the Universal Head shown in the cut opposite. This Universal Head has four graduated circles by means of which the tool may be set in any desired position for grinding. The chart gives the setting for each circle.

Under the heading "Tool Holder" we have the setting for the circle shown in cut at top of page 95. By it the tool may be swiveled through an angle of 30° on each side of center graduation, (stamped 30°).

Under the heading "Vertical" we have the setting for the circle by means of which the tool may be turned through 360° . This circle moves around a horizontal axis. The setting indicated denotes the angle through which the tool is turned around its horizontal axis, showing 2° clearance.



Showing Graduations on Grinder


Under the heading "Horizontal" we have the circle by means of which the tool may be turned through 150° in a horizontal plane. This circle moves around a vertical axis, and serves for grinding the faces and sides, also round nose tools. The settings show that the opposite sides of the tool are parallel.

KIND OF TOOL	FACE	ANGLES			
		TOOL HOLDER	VERTICAL	HORIZONTAL	CLEARANCE
CAST IRON	SIDE A	30	182	0	18
	SIDE B	30	338	0	15
	END C	30	90	100	15
	TOP D	30	90	330	15
	SIDE A	30	182	0	18
	SIDE B	30	338	0	15
	END C	30	90	100	15
	TOP D	30	90	330	15
STEEL	SIDE A	30	182	0	18
	SIDE B	30	338	0	15
	END C	30	90	100	15
	TOP D	30	90	330	15

Under the heading "Clearance" we have the setting of the circle that has a horizontal axis parallel to the face of the wheel. By means of this circle, the Universal Head may be swiveled in the base around a horizontal axis (always at right angles to the spindle) through an angle of 15° on either side of the horizontal plane (stamped 15°). This setting is for the purpose of obtaining clearance on thread tools without distorting the angle of the point, making it unnecessary to calculate fractional settings.

We shall now clamp the tool in the holder, and proceed to grind side A.

First, we set the Tool Holder at 30, as called for on chart. Second, we




First Operation—Side A



set the Vertical at 182, to get the side clearance. Third, the Horizontal, we leave at Zero and fourth, we get the proper Clearance by setting clearance circle at 15.

This sets the machine for grinding side "A" of the tool.

Next we take hold of the hand wheel with the left hand, and traverse the tool holder up to the wheel. As we grind, the tool is traversed across the face of the wheel by means of the lever operated by the right hand.



Second Operation—Side B

**Third Operation—End C****Fourth Operation—Top D**


Faces B, C and D are then ground in similar manner. The tool is not removed from the holder until all faces are ground. Both the setting and grinding of the tools are very simple operations.

The tools are always clamped in the same way.

Sometimes there is a number of tools of the same kind to be ground at the same time. In such cases it will be found advantageous first to grind the same side of each tool of the lot; then set the Grinder for second side, grinding all on that side and so on.

BENT TOOLS.

When grinding a bent tool, you simply move the tool holder either side of the 30° center line to bring the face to be ground parallel to the face of the wheel. This is the only change required for bent tools. They are then ground at the same settings as the straight tools, the tool being moved the same amount as it is bent.



Grinding Round Nose Tools

ROUND NOSE TOOLS.

Grind top D first on tools Nos. 16, 17, 18, 19, 21, 59, 60, 64 and 66; then center by the use of centering device shown by the illustration on this page, the adjustment being made by turning Tool Holder circle. The tool is then ground by swinging on a vertical axis. In this way a uniform clearance is produced on the end of the face of the tool. The matter of correct angles has been worked out by us to cover quite a variety of tools. Take, for instance, those shown by the chart on page 99. This sample set of 27 correctly ground tools is sent with each Grinder if desired.

The chart shows exactly how to reproduce the angles in the tools and will be of much assistance to the operator in setting up his machine and also to the smith in forging new tools. Chart has been revised and now gives angles best adapted for lathe tools made of high speed steel for working steel or cast iron. Full size chart, of miniature shown on page 99, will be mailed free to users of our Grinder.

A larger size of Chart is furnished with each Gisholt Grinder, showing the correct setting of the Universal head for grinding these tools

The chart gives grinding angles for 44 tools, but only 27 tools are necessary, as samples for forging, for some of the tools vary only slightly in grinding angles.

GRINDING HIGH SPEED AND SELF HARDENING STEELS ON GISHOLT GRINDER.

If users of Gisholt Tool Grinders have trouble with the cracking or checking of High Speed Steel Tools, it is invariably because the operator undertakes to keep the tools cool by using water while taking the *heavy roughing cuts*. This can be obviated as follows:

Have tools rough forged to approximate shape.

Grind tool slowly at first, until tool becomes warmed through, then grinding can be forced without injury to the tool, but *do not use water on a roughing cut*, as the water will not overcome the heat and will check the steel. Getting the tool hot will not hurt it if kept dry.

After rough grinding, return tool to blacksmith and have it tempered. Then return tool to Grinder for finish grinding and *use plenty of water*, as with these light cuts, water will keep it amply cool. As tool becomes dull, regrind, using water. When necessary to re-forged, proceed *from forging* as before.

If the above be followed, no trouble should be encountered from the checking or cracking of High Speed Steel.

GISHOLT TOOL GRINDER—EMERY WHEEL.

To secure satisfactory results from a Grinding Machine, one of the most important features is to have a satisfactory wheel. Primary features are the Grain and Hardness.

GRAIN.

We recommend nothing finer than a No. 20 grain emery, although a mixture of No. 20 and No. 30 gives satisfactory results in some cases. There is a tendency to specify a finer grain by some users, but it is undesirable on this machine. The standard emery wheel furnished with the machine is No. 24 grain, grade L.

HARDNESS.

The wheel should be as soft as possible, yet not so soft as to crumble. A hard wheel will fill or clog up, then cut slowly and produce undue heating unless dressed very frequently. Most emery wheel manufacturers have their individual grading standards, varying with the different makes. We have experimented considerably with different makes, grades, etc., and are prepared to fill orders with a wheel we can thoroughly recommend.

TOOL HOLDER TOOLS

KIND OF TOOL	FACE	ANGLES			KIND OF TOOL	FACE	ANGLES			
		TOOL ANGLE	VERTICAL	HORIZONTAL CLEARANCE			TOOL ANGLE	VERTICAL	HORIZONTAL CLEARANCE	
 0142	TOP A	30	90	350	 0146	TOP A	30	90	0	
	SIDE B	30	158	0		15	SIDE B	30	0	30
	SIDE C	30	162	0		15	SIDE C	30	180	60
	END D	30	90	98		15				
When used for steel horizontal circle is set at 350 while grinding top (A)					 0144					
 0145	TOP A	30	80	0	 0143	TOP A	30	90	0	
	SIDE B	30	188	0		15	SIDE B	30	180	30
	SIDE C	30	0	-		23	SIDE C	30	0	90
	END C	30	0	-		23				
When used for steel horizontal circle is set at 350 while grinding top (A)					 0143					
 0143	TOP A	30	100	0	 0143	TOP A	30	90	0	
	SIDE B	30	352	0		15	SIDE B	30	180	30
	SIDE C	30	180	-		7	SIDE C	30	0	90
	END C	30	180	-		7				
When used for steel horizontal circle is set at 350 while grinding top (A)					 0143					

GISHOLT MACH.CO
MADISON WIS. U.S.A.
GRINDING CHART FOR TOOL HOLDER BITS.

THE DASH (-) Means to swing vertical circle stand on horizontal circle.
THE STAR (*) Means to grind (B) first. Then set radius to groups and slope tool holder.

The Gisholt Tool Post Tool Holders shown above were developed to meet a demand for a heavy tool holder that would give the maximum support to the cutting tool. The inserted cutters for these holders can be ground on the Gisholt Universal Tool Grinder as well as any solid forged tools. Six cutters are included in this set, (2 of No. 0142). Inserted cutters for other type of tool holders can also be ground.

CORRECT FORGING—USE OF FORMER BLOCK

The matter of correct forging of tools is also important. The nearer the tool is forged to the proper shape, the less the grinding required.

In order to assist the smith in getting the correct shapes we furnish with each Grinder a Former Block shown on this page. By the use of these nearly all of the usual shapes of tool-post-tools may be obtained.

Referring to chart on page 99.



Former Block to Aid in Correct Forging



Tools numbered 1, 19, 55 and 64 are shaped to the left side of the top of the Former Block.

Tools numbered 4, 21, 56 and 66 are shaped to the right side of the top of the Former Block.

Tools numbered 2, 17, 24, 29, 31, 37, 39 and 59 are shaped to the lower right side of the Former Block.

Tools numbered 5, 16 and 60 are shaped to the lower left side of the Former Block.

Tools numbered 8, 11, 14, 33 and 35 are shaped to the upper right side of the Former Block.


Tools numbered 9, 12 and 15 are shaped to the upper left side of the Former Block.

Tools should be forged with somewhat more clearance than shown in the tables so as to reduce the area to be ground.

Great economy, both in forging and in grinding, results from the use of the

Former Block. We suggest that the set of 27 standard tools be mounted on a board and kept in the smith shop for reference when forging.

When two numbers are stamped on sample tool (for instance 1 and 55), it indicates the sample can be used for forging either number. The tool forged should be stamped with the number shown on chart to which it is ground.



**Sample Tools showing some of the Styles ground on Gisholt Grinder
Suggested method of mounting Tools on board for Smith shop**





PRINCIPAL DIMENSIONS

Will grind stock up to $1\frac{3}{4}$ " or flat stock up to $1\frac{3}{4}$ "x $2\frac{3}{4}$ ".

By taking the small tool holder out, stock up to 2 "x $3\frac{1}{2}$ " may be ground.

A special holder is furnished for grinding small tools used in standard tool holders, such as Gisholt, Armstrong, and a special holder can be furnished for O. K. tools.

Will grind broad cutters up to $3\frac{1}{2}$ " in length, or 7" by reversing.



102Z

Symbol and number refer to figures on page 104.

TP1 to TP27. See grinder chart, page 99.

TP28. Finishing bevel.


TP29 to TP31. Forming tools.

TP32. Corner rounding tool.


TP33. For cutting out clearance between double gears.

TP34 to TP36. Forming tools.

TP37. Bent roughing tool. Used in side of tool post with another tool in regular position for facing or turning.



TP5A. Support for cut off tool. This support or one similar may often be used to good advantage with any overhanging tool post tool.




TP38

TP39

TP40

TP41



TP44


TP45

TP46

TP47

TP42

TP43



TP48

TP49

TP50

TP51

TP52

TP53

TP54

TP55

TP56

TP57


TP58

TP59

TP60

TP61

TP61



TP62

TP64

TP65

TP66

TP67

TP68

TP69


TP70

TP71

TP72

TP73

TP74



TP75

TP76

TP77

TP78

TP79


TP80

TP81


103 Z

Symbol and number refer to figures on page 106.


- TP38, 39. Holders for flat forming cutters. See cutters TP75 to TP81 below.
- TP40. Holder for two tools used for straddle facing.
- TP41, to TP43. Standard tool holders. See standard tool equipment, pages 28 and 101.
- TP44. Holder from round stock, set screw on top of cutter.
- TP45. Holder from round stock cutter on angle for turning and facing.
- TP46. Holder from round stock cutter on angle for boring and facing.
- TP47. Holder from round stock—set screw in end.
- TP48, to TP53. Cutters supplied with standard tool equipment, see pages 28 and 101.
- TP54, TP55. Cutters for forming sprocket teeth.
- TP56. Corner rounding cutter.
- TP57. Forming cutter.
- TP58. Grooving cutter for angle tool holder.
- TP59, TP60. Square thread tools for right and left hand tool holders.
- TP61. Tool for finishing, turning or facing and rounding corner.
- TP62. Grooving tool for straight tool holder.
- TP63. Forming tool for pulley flange.
- TP64. Finishing tool.
- TP65. Thread tool—outside threading.
- TP66. Thread tool—inside threading.
- TP67, TP68. Tools for finishing bevel surfaces.
- TP69. Spring tool.
- TP70, to TP74. Forming tools.
- TP75, to TP78. Flat forming tools for crowned pulleys.
- TP79. Flat forming cutter for ball on steering knuckle.
- TP80. Flat forming cutter for worm gear.
- TP81. Flat forming cutter for bevel.





TP82




TP83




TP84




TP85




TP86




TP87



TP88



TP89




TP90


104 Z

Symbol and number refer to figures on page 108.

- TP82. Tool holder for grooving tools.
- TP83. Tool holder for gang tools for facing flywheel web and rim.
- TP84. Tool holder used in cutting off piston rings.
- TP85. Tool holder for piston grooving tools.
- TP86. Roller support on tool post for small bar work.
- TP87. Thread chaser for pipe flanges.
- TP88. Outside thread chaser.
- TP89. Inside thread chaser.
- TP90. Special outside thread chaser.



- TP91. Steady rest carrying finishing cutter, used on tool post carriage for turning long work. The roughing cut is carried by a tool in the turret tool post and set about $\frac{1}{8}$ " ahead of finishing cutter.
- TP92. Adjustable tool holder employed when taper attachment is used for bevel facing or turning. See page 115 for further description.
- TP93. Tool holder for turning. Used with regular tools in tool post.
- TP94. Taper attachment forming block for crown pulleys.



TP95. Forming block on cross slide for facing convex surfaces.



TP96. Forming block for concave surfaces.

TP97. Guide roller on ways. Used with TP95 and TP96.

Note: Forming blocks are bolted securely to cross slide on side toward turret, and the guide roller is clamped tight to front "V" way. The carriage then will follow shape of forming block.

TP98. Special tool holder for boring.

TP99 to TP101. Special tool holders for turning and forming.



107 Z

TP 102


Symbol and number refer to figures on page 112.

TP102. Special tool post for rough and finish turning cone pulleys.

Figure 1767 shows a rather unusual job for a turret lathe.

It consists of rough and finish boring and reaming a hole the entire length of piece. Also the boss "A" is faced on both sides while the piece is being bored. The unusual feature of this job lies in the fact that the faces of the boss "A" are at two different angles to the axis of the cylindrical part or the bore.

To obtain these two different angles the cam plate "B" was made and bolted to face of chuck. The plate tapers in, getting thinner toward center of chuck; this gives one angle. Plate is also thinner at one end than at the other, which gives the second angle.



Tool Holder "C" is a sliding fit on the base "D" with a gib for adjustment, and carries two tools which are shown in position for facing both sides of boss "A". In one end of the holder "C" is arranged a hardened steel crowned roller "H", which is held against the cam plate "B" by compression spring "E." As the tools are fed in, the roller follows the shape of the cam, thereby causing the tools to follow the angles required on the face of the boss "A".


This same idea has been used for other work. In some cases the cam plate forms a complete circle, while in others it may be either more or less than the one shown which is approximately a half circle.

Taper Attachment.

ADJUSTMENT AND CONNECTION.

Before attempting to use the taper attachment the gibs should be correctly adjusted and well oiled. This is done by adjusting the gib screws "A" (shown in fig. 1993) in taper attachment slide so that gibs will move with a snug sliding


fit, but not be too tight. Then adjust gib screws "B" in the swivel slide to about the same tension. The tail block "B2" should be adjusted to move freely with adjusting screws "C", after removing taper pin "D". Remove taper pin "D", by turning to the right, the hex head nut which is on the end of it.



Having removed the taper pin "D", the tail block "B2" should be lined up and the stud "E" screwed in place.


Set the tool post carriage so the cutting tool will be an inch or two from the point where it is to begin cutting and tighten the set screws "H" on the rod. Then loosen the clamp screws "K" and set the swivel "M" as near as possible to the taper desired. Gage taper after first cut and, if not correct, readjust the swivel "M" to suit. Always move tool post carriage back far enough to carry the cutting tool past the starting point. This is to take up any lost motion that may exist in the attachment. This lost motion is found in all taper attachments and is unavoidable.

The cutting tool should be set exactly on center. If height of tool is changed taper will also change, that is, if proper taper is obtained with tool set on center and tool is raised or lowered, the taper will change.



USE.

The most common use of the taper attachment is that of boring or turning tapers with tool post tools. The taper attachment may be set to turn straight, or taper up to $4\frac{1}{4}$ " per foot. It is frequently used and proves very convenient for boring or turning jaws.



We have successfully used the taper attachment in facing bevel gears where the angle is near forty-five degrees. This is done by setting the attachment to one side or the other, according to the angle required and engaging both the cross feed and the carriage feed at the same time. Very accurate results may be expected thru this combination if the tool post carriage stops are used, or some other means of accurately locating the carriage, and observing the index dial on the cross feed screw. Both feeds should be engaged with the spindle not in motion.

Figure 1992 is an illustration of bevel facing with the taper attachment. The machine was stopped in the middle of the cut and this view taken.

Angles that do not come within the range of the standard taper attachment may be obtained by making a special guide block as shown in figure 1994, page 116. Almost any desired shape may be had thru the use of special blocks, such as the crowning of pulleys, etc. One of the blocks used for crowning pulleys is shown at TP94, page 110.

Taper turning and boring is further discussed in Facing Head Chapter, pages 172, 174 and 175.

The Drill Support.


The foremost consideration in the design of the drill support was its adaptability to the general run of turret lathe work.

It is quickly lowered into position and when not in use may be swung back out of the way of other tools and to clear the chuck. A 6" universal scroll chuck is provided and may be used in a number of ways. One of these is in starting drills true in solid material, such as forgings and work from bar stock. A center drill is sometimes held in the chuck in drill support when a center is required in the work being done.

The drill support affords an ideal support close to the work for three or four lip drills, commonly used for opening up cored and other rough holes. This support is most valuable as usually these holes do not run true, and if not supported, the drill has a tendency to follow the rough hole.


Occasionally work will come to the turret lathe with what is commonly called a "blind hole" or a hole that does not extend all the way thru the piece. This, of course, prohibits the use of the piloted bars which are usually supported in a bushing held in the bore of the chuck. Here we find the drill support almost indispensable as a support for end boring bars used on this class of work. When used in this way, the drill support chuck is replaced with a bushing. The bushing should be a sliding fit on the boring bar. See illustration on sheet 108Z, page 118, also figure 2005 and 2006, page 122.

When the amount of work to be performed warrants doing so, special drill supports may be made that will give an advantage over the standard support. Some of these are made to carry turning and facing tools for sizing and facing the end of the work. See sheets 108Z and 109Z, pages 118 and 120.



Symbol and number refer to figures on page 118.

- DH1. Special drill support carrying a tool to size end of work.
- DH2. Standard drill holder.
- DH3. Drill socket for using taper shank drills with drill holder.
- DH4. Drill socket fitting turret.
- DH5. Twist drill, straight shank, with bushing for standard drill holder.
- DH6. Twist drill, taper shank.
- DH7. 4 lipped drill, straight shank, with bushing for standard drill holder.
- DH8. 3 grooved chuck reamer, straight shank, with bushing, etc.
- DH9. Special taper shank drill.
- DH10. Twist drill, two diameters.
- DH11. Oil tube twist drill, straight shank.
- DH12. Oil tube twist drill, taper shank.
- DH13 & DH15. Special drills.
- DH14. Center drill.
- DH16. Bushing for supporting drills in chuck DH17.
- DH17. 6" chuck used in drill support.
- DH18. Bushing in drill support used for supporting end bars larger than can be supported by 6" chuck DH17.



Symbol and number refer to figures on page 120.

- DH19. Special drill support.
- DH20. Bushing on end bar for supporting close to the cutter in long work.
- DH21. Special drill suport allowing tool post to be used while boring with end bar.
- DH22. Flanged bushing for drill support.

An actual application of the standard drill support is shown in figures 2005 and 2006. The tools on the machines in these cuts were used to bore a high explosive shell approximately 20" deep. The drill support is fitted with a bushing and supports bars No. 1 and No. 3 which bore to a depth of 16". These bars carry a sliding bushing which is a slip fit in the drill support bushing.




Figure 2005 shows support lowered in place with bar No. 1 ready to begin boring.

Figure 2006 shows support thrown back out of way, with bar No. 2 in position to enter work.

Turret Tools.

DRILLS

As drills are often a part of turret lathe tool equipment, we offer a few suggestions in regard to drill grinding.

The twist drill will cut fairly free when new, but, as it is ground and reground, the web or center part becomes heavier or thicker and makes the point wider. This condition requires an excessive amount of power to feed the drill thru the material.

Often-times the attempt to relieve the point results in its being weakened which causes undue breakage, therefore, nothing has been gained.




Figure 2430 shows a drill which has been ground only a few times, but has a web of considerable thickness. However, in this case, the cutting edges *do not* extend to the center.

Figures 2375 and 2376 show the same type drill with this web or center part ground to give a cutting edge right in to the center of the drill. Note again the cutting edges of both lips *extend* to the center and have a strong web connecting them. The point is not weakened in the least as the *heel* of the lip is *not* ground away.

Great care, however, must be exercised in grinding, because, if the relief is ground past center into the heel of the opposite lip, a weakness results. In relieving the point, the grinding may be done on almost any emery wheel for tool grinding but the best results will be obtained on a wheel about 4" in diameter by $\frac{1}{2}$ " thick with square corners.


This shape of lip may be ground with equally good results on flat drill bits, which are sometimes used instead of the twist drill.

The regular grinding should, of course, be done on a drill grinder, not by hand.

The three or four lip drill is used to open up cored and other rough holes before using boring cars. For this work the drill should be carefully ground to accomplish the desired result, which is, not only to open up or enlarge the hole, but also to help true it.

It is quite customary to chamfer the ends of the lips, but experience has taught us that a drill ground in this way has a tendency to follow the rough hole.

If the end of the drill is ground square, or better still slightly concave and the corners beveled about $\frac{1}{16}$ " wide, it will invariably make a truer hole than the chamfered drill and it will cut faster, which means that a heavier feed may be used.




1889

Figure 1889 shows how a three or four lip drill may be ground as we recommend. Grinding should always be done by machine, because the best results are obtained if all lips cut exactly alike.

Cutting speeds and feeds are governed by the work at hand depending on material being drilled, size of drill and amount of stock removed.

A few special drills are shown on sheet 108Z, page 118.

BORING BARS.




1462

There are in use a great number of differently designed boring bars, some of which are exceedingly well constructed and very serviceable.

Two of the most essential requisites of a boring bar are rigidity and chip clearance. The latter perhaps is of as much, if not more, importance than the former. Cutters are frequently broken by chips clogging between the work, the cutter, and the bar due to insufficient chip clearance.

While the question of chip clearance must not be over-looked, the bar should be made as rigid as possible.

The Gisholt Standard Boring Bar as shown below has been developed to a very high point of efficiency. Note the spiral groove which leads back from each cutting lip of the cutter. The spiral lead is right hand which helps to work the chips out of the hole the same as they work out along the flutes of an ordinary twist drill.



Twelve sizes of this bar form a complete standard set, boring any desired size of hole from 1" to 9 1/8" diameter. This bar has a long pilot and is supported in a bushing held in the bore of the chuck.

The type shown in figure 1460 is held in the turret head proper by a very snug sliding fit, and clamped with a clamp screw, while the smaller sizes are held in our standard drill holders, which are shown on page 118.

At least two bars should be used to produce a true hole with a close size limit—one for roughing and the second for finishing. The finisher, of course, is usually followed by a reamer as a final finisher and sizer.

There should be very little stock left for the finishing bar, because the less the finishing cutter removes the truer the job will be when finished, providing enough stock is left for the finisher to cut all the way around or "clean up."

The amount usually allowed between the roughing and finishing cutters is from .015" to .020" for both cast iron and steel, governed to a great extent by the condition of the work as it comes to the machine. For reaming allowances see page 151.

Sometimes the work may be handled more rapidly if special bars are made. A few special bars are shown on some of the following pages. Note some of these carry cutter heads slotted for cutters. Others are made with steps having cutters in each step for different sized holes in the same piece which may be bored simultaneously.

Always bear in mind that to get the best results and highest production, your boring bars *must be rigidly supported*. End bars which have the cutter in the extreme end and no pilot should be supported in the drill support provided for that purpose. See illustrations in drill support chapter.

Trouble is occasionally experienced thru miscalculating the length of boring bars. The pilot must necessarily be long enough to extend thru the work and enter the supporting bushing in the chuck and the shank of the bar must be long enough to reach over the cross carriage and permit boring and turning at the same time.

Taking all this into consideration, we insert for your convenience the table on page 127, which probably will assist in determining the length of bars, also the location of the cutter slots so as best to take care of the work at hand or under consideration.


You will note that the table is in two sections; the first, relating to that work which will not swing over the tool post carriage cross slide, the second to that work which will swing over the tool post carriage cross slide.

Whenever a No. 1, No. 2 or No. 3 bar is used with our 21" or larger Lathe, it is carried in the drill holder on the turret, in a split bushing, and the regular stock 29" bar will care for any work in length up to 10", (subject to chucking diagram below) which will cover most requirements.


The "lengths of work" given in table opposite are conservative, and any given size of bar is intended to bore occasional slight extra lengths which exist because of variations in castings.

The allowance on the pilot, between the length of work and the "A" dimension, permits the pilot to have not less than a 2" bearing in the chuck bushing; permits the chuck bushing being set back from $1\frac{1}{2}$ " to 2" in the bore of the chuck; it also assumes that the work itself will be held 1" out from the face of the chuck.

In case the work is to be held at a greater distance than 1" from the face of the chuck, the *additional* distance should be *added* to the length of work.



LENGTH OF BARS FOR USE WITH GISHOLT TURRET LATHES



GISHOLT TURRET LATHES	NOT OVER CARRIAGE			OVER CARRIAGE		
	The Boring Bar Dimensions for Chucked Work that will NOT Swing Over the Tool Post Carriage Cross Slide.			The Boring Bar Dimensions for Chucked Work that WILL Swing Over the Tool Post Carriage Cross Slide.		
Size	Length of Work	"A"	"B"	Length of Work	"A"	"B"
	Inches	Inches	Inches	Inches	Inches	Inches
"G" or 13½ inch.....	..	..	..	6	10	24
	4	8	26	8	12	26
	6	10	29	11	15	29*
"H" or 21 inch.....	6	11	34	10	15	34
	8	13	38*	12	17	36
	10	15	42	14	19	40
	11	16	44	16	21	44
"I" or 24 inch.....	8	13	40	14	19	42
	10	15	44*	16	21	46
	12	17	48	18	23	48
"J" or 28 inch.....	8	13	44	14	19	44
	10	15	48*	16	21	48
	12	17	52	18	23	52
	14	19	56	20	25	56
	16	21	60	23	28	60
"K" and "L"..... 34 in. and 41 in.....	8	14	48	14	20	48
	10	16	52	16	22	50
	12	18	56*	18	24	54
	14	20	60	22	28	60
	15	21	62	24	30	62

* Stock Bar usually recommended for ordinary use.

GISHOLT BORING BARS.




This description of the Gisholt Boring Bar is given to illustrate the importance and superiority of this type of bar.

The bars are made of special steel, heat treated to give toughness and increase the tensile strength and then hardened on the pilot only.

The cutter slot is so located that the cutter leads the large diameter of the bar, which, having spiral grooves for the chips to pass thru, permits boring of diameters only slightly larger than the bar. The cutter key is placed in front of the cutter whose backing is thus the bar itself. The maximum rigidity is insured by this arrangement and the fact that the cutter has the extra support of the larger diameter of the Bar. As the chip groove does not cut thru the bottom of the cutter slot it does not reduce the backing of the cutter.

Jigs are used in machining these bars to secure interchangeability of cutters, and uniformity of bars.




Expansion or Adjustable and Solid Cutters are regularly furnished with these bars. At 1 in figure 134Z is shown the principle of the Adjustable Cutter.

The cutter is made in halves with the inner ends beveled. The adjustment is made with a fine pitch screw which has a 90° point and works against the beveled ends of the cutter, expanding it.


The Adjusting Screw (1891A) is carefully made, hardened and accurately ground. A square hole is broached in the end to receive the Adjusting Wrench (1891B) which is graduated, making possible adjustments in thousandths. An Adjustment Lock Screw (1891C) is used to hold the Adjusting Screw in place when the proper setting has been made.

The front of the cutter blade (see 55Z, page 131) is beveled to a $3\frac{1}{2}^\circ$ angle, same being widest at the inner end. A shim is used between the cutter and the cutter Key which we call Expanding Cutter Shim (1891D). It is made of Chrome Nickel Steel, heat treated and is milled with a 4° bevel as shown. The

bevel side of the shim is set against the cutter. As the cutter is milled to a $3\frac{1}{2}^\circ$ angle and the shim to 4° , when the Cutter Key is set up tight, the shim bears heaviest at the ends, locking the cutter so as to prevent shifting under heavy cuts.



The Cutter Key (1891E) is made of regular drill rod, heat treated. It is flattened on one side at a 3° angle. The key hole in the bar is drilled at this same angle so that the key has a flat bearing against the Cutter Shim, or against



Adjustment of the expansion cutters finer than $.001''$ is readily made by dividing the graduations on the Adjusting Wrench.

The correct procedure for obtaining a predetermined diameter of the cutter, when setting it in the Bar, is as follows:

First Be sure to remove any chips and thoroly clean the slot in the bar, the cutter, cutter shim, and adjusting screw.

- Second Place cutter in slot and screw adjusting screw down until cutter has no end motion.
- Third Put cutter shim in place and tighten cutter key slightly.
- Fourth Take measurements and determine how much the cutter must be expanded to reach the required diameter.



1891 F

- Fifth Slightly loosen cutter key using punch (1891F) as shown, (but do not remove it), then expand cutter by running adjusting screw down with adjusting wrench which, being graduated in thousandths, makes possible very accurate adjustments.
- Sixth Check measurement and, if not correct, slightly loosen cutter key again; then make any fine adjustment necessary and drive cutter key tight.
- Seventh Be sure to tighten the adjusting lock screw when proper setting is made, after which the cutter can be removed for grinding and replaced without removing the adjusting screw or materially changing the size.

Note: Remember when making fine adjustments, cutter key should not be removed, but slightly loosened. This keeps the cutter in place while adjustment is being made.



1891 G

With the solid cutter as shown in figure 2-134Z, page 128, the key fits against the cutter. The cutter is centered by a fine pitch centering screw (1891G) as shown. The head of this screw is similar to that used for the Adjustable Cutter; the same wrench will fit both. These screws are hardened and accurately ground.

An advantage of this type of solid cutter lies in the fact that it may be shifted to one side, thus boring holes over its size. The Centering Screw is not used to hold

the cutter, but simply to center it quickly and accurately, the holding of the cutter is done entirely by the key.

Following are a few of the different types of cutters, which may be very successfully used with the Gisholt Boring Bars.




Figure 55Z. Standard Expansion Cutters have adjustment of from $\frac{3}{16}$ " to $\frac{7}{16}$ " (depending on size) by .001" graduations, and finer if graduations are divided.




Figure 56Z. Standard Solid Cutters are centered in bar with accurate centering screw and held in place by standard cutter key. In emergency cases they may be set off center, and larger holes bored. See figure 58Z.




Figure 57Z. Floating Cutter which is sometimes used with favorable results when reamers are not available. Float is obtained by slightly loosening the Centering Screw and Cutter Key, thus allowing the Cutter a slight free movement in the bar.




Figure 59Z. Swedge Expansion Cutters of this type permit a slight adjustment, but are not so reliable as the Standard Expansion Cutter.





Figure 60Z. Single End Cutters used in emergency. Cutters are quickly and easily made from proper size stock.




Figure 61Z. Another emergency Cutter, which may be made of square stock when proper size for single end cutters is not available. It may be shimmed by a piece of flat stock.


The Gisholt Boring Bars as listed on page 132 cover the ordinary sizes and lengths suitable for use with the various sizes of Gisholt Standard Turret Lathes.

Bars No. 1, No. 2 and No. 3 in the 29" length as given, when used in combination with a drill holder on the turret, are of suitable length for use with any of our Standard Turret Lathes. A split bushing is used to fit the bars to the holder which permits of adjustment for length and also affords a more rigid support for small diameter bars.

No. 4 and larger bars are carried directly in the Turret. When ordering, the exact size of the hole in the Turret must be given.

All Boring Bars are complete with parts necessary to carry either the Expansion or solid cutters, as may be desired, except the No. 1 and No. 2 bars which do not carry the Expansion Cutter.

The list covers the ordinary stock sizes of Bars only, with the single cutter slot, regular diameters and base lengths. (Continued top of next page.)



LIST OF GISHOLT STANDARD BORING BARS.

Bar Number	Range of Bore	Diameter of Pilot	Length of Pilot in Front of Cutter Slot	Diameter of Bar Back of Cutter Slot	Length of Bar Over All
	Inches	Inches	Inches	Inches	Inches
H-1	1 to 1 $\frac{3}{4}$	5	10	7 $\frac{3}{4}$	29
H-2	1 $\frac{3}{8}$ to 2 $\frac{1}{4}$	7	10	1 $\frac{1}{2}$	29
H-3	1 $\frac{9}{16}$ to 3 $\frac{1}{4}$	1 $\frac{1}{4}$	10	1 $\frac{1}{2}$	29
H-4	2 to 3 $\frac{3}{4}$	1 $\frac{3}{8}$	14 $\frac{1}{2}$	1 $\frac{1}{2}$	38
I-4	2 to 3 $\frac{3}{4}$	1 $\frac{3}{8}$	15	1 $\frac{1}{2}$	44
J-4	2 to 3 $\frac{3}{4}$	1 $\frac{3}{8}$	16	1 $\frac{1}{2}$	48
K-4	2 to 3 $\frac{3}{4}$	1 $\frac{3}{8}$	18	1 $\frac{1}{2}$	56
H-5	2 $\frac{3}{8}$ to 4 $\frac{9}{8}$	1 $\frac{3}{8}$	14 $\frac{1}{2}$	2 $\frac{1}{4}$	38
I-5	2 to 4 $\frac{9}{8}$	1 $\frac{3}{8}$	15	2 $\frac{1}{4}$	44
J-5	2 to 4 $\frac{9}{8}$	1 $\frac{3}{8}$	16	2 $\frac{1}{4}$	48
K-5	2 to 4 $\frac{9}{8}$	1 $\frac{3}{8}$	18	2 $\frac{1}{4}$	56
H-6	2 to 5 $\frac{1}{2}$	1 $\frac{7}{8}$	13 $\frac{3}{4}$	2 $\frac{3}{4}$	38
I-6	2 to 5 $\frac{1}{2}$	1 $\frac{7}{8}$	15	2 $\frac{3}{4}$	44
J-6	2 to 5 $\frac{1}{2}$	1 $\frac{7}{8}$	16	2 $\frac{3}{4}$	48
K-6	2 to 5 $\frac{1}{2}$	1 $\frac{7}{8}$	18	2 $\frac{3}{4}$	56
I-7	3 to 6 $\frac{1}{4}$	2 $\frac{1}{4}$	15	3	44
J-7	3 to 6 $\frac{1}{4}$	2 $\frac{1}{4}$	16	3	48
K-7	3 to 6 $\frac{1}{4}$	2 $\frac{1}{4}$	18	3	56
I-8	3 to 6 $\frac{5}{8}$	2 $\frac{3}{8}$	15	3 $\frac{1}{4}$	44
J-8	3 to 6 $\frac{5}{8}$	2 $\frac{3}{8}$	16	3 $\frac{1}{4}$	48
K-8	3 to 6 $\frac{5}{8}$	2 $\frac{3}{8}$	18	3 $\frac{1}{4}$	56
J-9	3 to 7 $\frac{3}{8}$	2 $\frac{5}{8}$	16	3 $\frac{3}{4}$	48
K-9	3 to 7 $\frac{3}{8}$	2 $\frac{5}{8}$	18	3 $\frac{3}{4}$	56
K-10	4 to 7 $\frac{3}{8}$	2 $\frac{5}{8}$	18	4	56
K-11	4 $\frac{5}{8}$ to 8 $\frac{1}{4}$	3 $\frac{1}{4}$	18	4 $\frac{1}{2}$	56
K-12	4 $\frac{3}{4}$ to 9 $\frac{1}{8}$	3 $\frac{3}{8}$	18	4 $\frac{1}{2}$	56

For convenience in ordering, please use our cutter number followed by the number of the Bar in which it is to be used.

Example: One cutter No. 32-3 means one $1\frac{3}{4}$ " to $1\frac{15}{16}$ " cutter for No. 3 Bar

Two Cutters No. 32-5 means two 3" to $3\frac{15}{16}$ " cutters for No. 5 Bar


Four Cutters No. 33-7 means four 4" to $4\frac{3}{8}$ " cutters for No. 7 Bar

One cutter is understood to be the two halves or *one complete cutter*. A pair of cutters would be understood to be four halves or two complete cutters, which could be used for roughing and finishing.

BORING BAR SOLID CUTTERS.

The Solid Cutters listed below are all hardened and finished ready for use, except, perhaps, for grinding to suit local conditions. Each cutter has a central locating spot on the side with which the centering screw engages to center cutters in the bar.

Unless specified, we usually furnish the cutters ground, which, of course, would not interfere with the user regrinding it to meet his particular requirements. A cutter ground standard will usually cut .001" to .002" over its size.




LIST OF BORING BAR SOLID CUTTERS.

The Several Sizes of Bars will Carry Cutters for Boring the Following Diameters

Bar	Will Bore	Bar	Will Bore
	Inches		Inches
No. 1	From 1 to $1\frac{3}{8}$	No. 7	From $3\frac{1}{8}$ to 6
No. 2	From $1\frac{3}{8}$ to $2\frac{1}{2}$	No. 8	From $3\frac{3}{8}$ to $6\frac{1}{2}$
No. 3	From $1\frac{5}{8}$ to 3	No. 9	From $3\frac{7}{8}$ to $7\frac{1}{2}$
No. 4	From 2 to $3\frac{3}{4}$	No. 10	From $4\frac{1}{8}$ to 8
No. 5	From $2\frac{3}{8}$ to $4\frac{1}{2}$	No. 11	From $4\frac{3}{8}$ to $8\frac{1}{2}$
No. 6	From $2\frac{7}{8}$ to $5\frac{1}{2}$	No. 12	From $4\frac{7}{8}$ to 9

In producing accurate work, as before stated, it is customary to rough bore, finish bore and then ream. In this case the cutters should be ordered in pairs, one Rougher (marked "R") and one Finisher (marked "F").

When these cutters are ordered in pairs, "R" and "F," we will assume that a Reamer is to follow the finishing cutter in the work unless otherwise instructed, and will supply cutters marked accordingly. The rougher would be ground in master bar from .015" to .020" undersize, and the Finisher ground from .005" to .007" undersize to leave stock for reaming.




MASTER GRINDING ARBORS

The grinding and sharpening of cutters can be done in the usual manner in the bars themselves. However, it is inconvenient and also takes the boring bars out of service, oftentimes delaying production.

We can furnish Master Grinding Arbors which, for the purpose intended, are an exact reproduction of a short section of the bar itself. These Arbors will carry either the Expansion or Solid cutters, have hardened tool steel center, and a screw action is substituted for cutter key to avoid any jar while on centers.

These Arbors are a great convenience because of their shorter length, also a great economy, as the grinding and sharpening of cutters can be done at the convenience of the tool room without taking the boring bars out of service.


Master Grinding Arbor	Length of Arbor	Will Carry All Cutters for Boring Bars
No. 1	7 inches	No. 1
No. 2	7½ inches	Nos. 2 and 3
No. 4	8 inches	No. 4
No. 5	8 inches	No. 5
No. 6	8 inches	Nos. 6, 7 and 8
No. 9	8½ inches	Nos. 9, 10, 11 and 12



TURRET ADAPTERS.

Perhaps your Gisholt Turret Lathe department consists of several sizes of lathes. And frequently you find it necessary, in emergency cases, to shift the tools for some work to a different size of machine than that for which they were made.


To facilitate this change, the Turret Adapters will prove very satisfactory for the boring bar and reamer equipment. They are made to fit the hole in the turret and bored to fit the boring bar. (See list next page.)



TURRET EXTENSIONS.

Occasionally a case arises where the regular Boring Bars on hand are not of sufficient length to do some unusually long work. This is sometimes nicely handled by the use of Turret Extensions of proper length.

These Extensions bolt onto the face of the Turret (the bore being the same as that of the holes in the Turret), forming a rigid and substantial support, and, in fact, are preferable to an extremely long Bar. (See list next page.)



TURRET ADAPTERS

With Necessary Screws

Number	Will Carry Bars for Machine Next Size	A	B	C
		Inches	Inches	Inches
G-58	Larger*	1½	2¼	4
H-58	"	2¼	3	5
I-58	"	3	3½	5½
J-58	"	3½	4	6
H-59	Smaller	2¼	1½	5
I-59	"	3	2¼	5½
J-59	"	3½	3	6
K-59	"	4	3½	6


* If planning to use a long bar on machine requiring the use of a Number 58 Adapter, use care in checking the total length to see that it will swing.

TURRET EXTENSIONS

With Necessary Screws


Number	A	B	C**
	Inches	Inches	Inches
G-60	1½	1½	4
H-60	2¼	2¼	5
I-60	3	3	5½
J-60	3½	3½	6
K-60	4	4	6

** Any desired length can be supplied.



Symbol and number refer to figures on page 138.


- BB1. Standard boring bar for adjustable or solid cutters.
- BB2. Bar for two solid cutters.
- BB3. Bar for a number of different diameters. Two cutters in each slot of bar.
- BB4. Bar with oil tubes. The forward slot arranged so cutter may be readily slipped into place for facing.
- BB5. Bar with two slots for cutters for boring large diameters where only a small pilot can be used.
- BB6. Bar for rough boring hole and roughing counterbore in flywheel.
- BB7. Bar for two or more boring heads. Set screws thru bar to adjust cutters in first head.
- BB8. Oil tube bar for one boring head.




111Z

Symbol and number refer to figures on page 140.


- BB9. Short end bar with extra slot.
- BB10. End bar to fit drill holder.
- BB11. End bar to fit turret.
- BB12. End bar with one extra slot.
- BB13. End bar with two extra slots.
- BB14. End bar for small holes.
- BB15. Counterbore with inserted cutter.
- BB16. Counterbore solid.
- BB17. Bar for boring taper holes.
- BB17a. Stop in spindle. Used with No. 17.
- BB18. Bar for spherical part of differential gear case.
- BB19. Head with supporting arbor for finishing annular groove in face of work, such as ball races.



BB 20




BB 21




BB 22




BB 23




BB 24




BB 25




BB 26




BB 27



BB 28




BB 29




BB 30




BB 31




BB 32




BB 33




BB 34




BB 35




BB 36




BB 37




BB 38




BB 39




BB 40




BB 41



BB 42




BB 43



BB 44



BB 45




BB 46


112Z

Symbol and number refer to figures on page 142.


- BB20. Boring bar solid cutter.
- BB21. Boring bar expansion cutter.
- BB22. Solid cutter for valve seats.
- BB23. Solid cutter for boring to size and finishing valve seat.
- BB24. Expanding cutter for two different diameters.
- BB25. Expanding cutter for boring and facing bottom of hole.
- BB26. Single end cutter for boring hole, turning boss, and facing bottom.
- BB27. Facing cutter, cutting edge on front only.
- BB28. Solid cutter for rough and finish boring with one cutter.
- BB29. Expansion cutter same as BB28.
- BB30. Solid cutter for boring two diameters and facing end.
- BB31. Solid cutter to be inserted in bar next to chuck and bore toward turret.
See BB4.
- BB32. Facing cutter, cutting edge front and back.
- BB33. Expansion cutters with inserted tools.
- BB34. to BB46. End bar cutters of various shapes.




BB 47




BB 48




BB 49




BB 50



BB 51




BB 52



BB 53









113Z



BB 54

Symbol and number refer to figures on page 144.

- BB47. Boring head with flat cutters.
- BB48. Adjustable boring head for motor frames.
- BB49. Boring head with flat cutters. Body of head cut away to clear hub.
- BB50. Head for spherical bores.
- BB51. Head with square cutters, adjustable.
- BB52. Head for boring and facing.
- BB53. Head with four flat cutters.
- BB54. Head with square cutters and oil tube.



114 Z

Symbol and number refer to figures on page 146.


- BB55. Boring head with cutters set on angle to give top rake.
- BB56. Head for taper bore with cutter in body of head for chamfering corner.
- BB57. Head with adjustable tool slides.
- BB58. Flexible steel tube used with oil tube drills and bars.
- BB59. Oil pipe connections.
- BB60. Boring bar extension (See page 136).
- BB61. Boring bar with cutters for automobile hub.
- BB62. End bar with four cutters.

Reamers

The right hand spiral reamer with not too many blades and with ample chip clearance is recommended as the reamer most adaptable for commercial use in cast iron, aluminum and especially steel.

Its advantage over the straight fluted reamer is that the chips will work out along the spiral flute about the same as they do with a twist drill.

If the reamer has an excessive amount of stock to remove or if the steel being reamed is soft and mushy with a tendency to tear, the spiral fluted type will prove far superior to the straight fluted type.



The straight fluted reamer is very satisfactory for cast iron and for short holes in some other materials, when the length of the hole does not exceed the diameter of the reamer.

The blades of the spiral fluted reamer are inserted in a high carbon steel body. The blade slot is straight and the spiral cutting edge is milled on the blade; each blade having only one cutting edge. See figure 1822.


Two types of spiral fluted reamers with arbors are shown on page 155.

The straight shank reamer shown in figure 1828, page 150, is made for holes from 1" to 2¼". The shank is hollow and has a small hole leading (from this central cavity) to each blade. This makes it possible to flood the reamer with oil or cutting compound.


The shell reamer shown on page 149 is made for holes from 2¼" to 4½". For sizes larger than 4½" diameter, the blades are set into a special body as is shown in figure 177Z, page 157.

Reamers are very important tools. If a hole requires reaming, it indicates that an accuracy is required not readily obtained otherwise.

REAMERS



1824



1823



1825

The accuracy of such work is absolutely dependent on the maintenance of accuracy in the tools producing it.

Then the first consideration in selecting reamers should be to secure a style and type which, under practical working conditions, may be held up to a desired standard with the least expense and care.

Experience has taught the dependability of the old solid type reamer. But with the soild type reamer there is no adjustment and, as soon as it has worn down below the low limit of the required size, it is useless.

The solid type high speed steel reamer was unpractical because of the first cost, the hardening difficulties and the absence of adjustment.

Many of the renewable blade or adjustable reamers were too frail in construction to withstand successfully actual working conditions. Some of them were too readily adjusted outside of the tool room to insure the maintenance of the desired standard of accuracy.



1828

The Gisholt reamer was developed by practical men of many years experience and has all the dependable features of the old solid type reamer, the desirable features of the adjustable reamer and has overcome the above mentioned objections.

The blades are of high speed steel and are set into the body as shown in figures 175Z and 176Z, page 151.

The adjustment is made by underlaying the blades with thin paper or tin foil. A hard surfaced insoluble paper about .001" thick is recommended. The tin foil can be obtained as thin as .0005" and is used for the finer adjustments.

It is only necessary to loosen the screws a turn on two and lift the blade enough to insert the underlay to the first screw, altho the screws and blade may be taken out and the underlay made the full length of the blade.

It may only be necessary at times to underlay the blades on one side of the reamer. If so, when the next adjustment is made, underlay the remaining blades.


If the reamer does not get dull, underlaying may be repeated more than once; but should the reamer get dull, re-grinding is in order and should be done as follows:

Remove paper or tin foil underlay, and replace with metal underlay thick enough to expand the reamer sufficiently to permit grinding to the desired size.

The underlay strips should be cut $\frac{1}{16}$ " or $\frac{1}{32}$ " narrower than the blade slot with clearance holes for the screw.

The grinding should be done on an absolutely true arbor, between dead centers

on a universal grinder to the required diameter plus .0005". This seeming over-size will eliminate undersize results. The reamers should be slightly larger in front, but taper should not exceed .00025" to each inch of length. The heel of the blade should then be backed off with a cup shaped emery wheel leaving a land from .006" to .010" wide. As the blades are spaced unevenly, the one being backed off should be on the locating rest.



Satisfactory clearance results may be obtained by setting the blade rest below dead center for the different sized reamers.

For reamers 1" to 1 $\frac{7}{16}$ " diameter; set rest $\frac{1}{16}$ " below center.

For reamers 1 $\frac{1}{2}$ " to 2 $\frac{1}{2}$ " diameter; set rest $\frac{3}{32}$ " below center.

For reamers 2 $\frac{9}{16}$ " to 4" diameter; set rest $\frac{1}{8}$ " below center.

For reamers 4" to 6 $\frac{1}{2}$ " diameter; set rest $\frac{5}{32}$ " below center.

A reamer is a finishing and sizing tool and must be kept sharp and true to insure first class work.

As the purpose of a reamer is not to remove a bulk of stock (as a boring tool), but to finish and size a hole, as little stock as possible should be left for the reamer to remove.

In general practice, it is found that better results will follow the use of slow cutting speeds and comparatively coarse feeds.

The customary allowance for reaming holes in cast iron, and malleable iron is from .004" to .008". For brass and bronze .003" to .006". The cutting speed should be about one-third to one-half of the highest cutting speed, at which the roughing tools would stand up. For instance, if a grade of iron is being machined that will permit a cutting speed of 40 ft. per minute, the approximate reamer speed would be from 15 to 20 ft. per minute.

In reaming cylinders or work where a high finish is required, it may be necessary to run slower than the speed above mentioned, and the feed under these conditions should be about $\frac{1}{4}$ " per revolution.

The allowance for steel ranges from .003" to .005"; the cutting speed being about one half the highest cutting speed which the roughing tools will stand.

The feed will vary a great deal more in steel reaming than in cast iron, owing to the difference in hardness. Soft mushy steel or the kind commonly used in hot or cold pressed steel work, such as automobile brake drums, etc., will not stand as coarse a feed as steel with a higher carbon content. The feeds vary from $\frac{1}{24}$ " to $\frac{1}{8}$ " per revolution.

For reaming steel the reamer should be flooded with lard oil, or a cutting compound of some kind. The oil is given the preference as it has been found that the reamers will hold to a standard size longer when working in oil.

A mixture of one part kerosene to three or four parts lard oil will sometimes add to the quality of finish, as will also a mixture of one part powdered sulphur to about forty parts lard oil.

Trouble is sometimes experienced in a reamer cutting oversize. This may be caused by the turret being out of line or the reamer on an arbor that is bent, or by removing excessive stock.

REAMER GRINDING MANDRELS.


Very often reamers are ground on the arbors on which they are to be used. This is a good plan, but may cause delays which could be avoided, if more than one reamer of proper size were supplied for the job, and these ground on a Reamer Grinding Mandrel. This would not take the arbor out of service. All reamer arbors should be checked up occasionally and straightened if necessary.

We are prepared to furnish Mandrels (as shown below) which are hardened and accurately ground and centered for reamers having standard taper holes, tapering $\frac{1}{8}$ inch to one foot.



REAMER GRINDING MANDRELS


Symbol No.	A Large Diameter Inches	Used for Shell Reamers Inches	Length Over All Inches
3465.....	1	$2\frac{1}{8}$ to $2\frac{1}{2}$	$7\frac{1}{4}$
3466.....	$1\frac{1}{2}$	$2\frac{9}{16}$ to $3\frac{1}{8}$	$7\frac{3}{4}$
3467.....	$1\frac{1}{2}$	$3\frac{3}{8}$ to 4	$8\frac{1}{4}$
3468.....	2	$4\frac{1}{4}$ to $6\frac{3}{4}$	$9\frac{3}{4}$
3469.....	$2\frac{1}{2}$	$6\frac{1}{4}$ and larger	$10\frac{3}{8}$



1823

Diameter Inches	Length Over all Inches	Hole* Inches	Blades		Number of Blades
			Full Length Inches	Cutter Length Inches	
2 $\frac{1}{4}$	3 $\frac{1}{2}$	1	2	1 $\frac{1}{2}$	6
2 $\frac{5}{8}$	3 $\frac{1}{2}$	1	2	1 $\frac{1}{8}$	6
2 $\frac{3}{4}$	3 $\frac{1}{2}$	1	2	1 $\frac{1}{4}$	6
2 $\frac{7}{8}$	3 $\frac{1}{2}$	1	2	1 $\frac{1}{2}$	6
2 $\frac{9}{8}$	3 $\frac{1}{2}$	1	2	1 $\frac{1}{2}$	6
2 $\frac{5}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2	1 $\frac{1}{2}$	6
2 $\frac{5}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2	1 $\frac{1}{2}$	6
2 $\frac{1}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2	1 $\frac{1}{2}$	6
2 $\frac{1}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2	1 $\frac{1}{2}$	6
2 $\frac{1}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2	1 $\frac{1}{2}$	6
2 $\frac{1}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2 $\frac{1}{4}$	1 $\frac{1}{2}$	6
2 $\frac{1}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2 $\frac{1}{4}$	1 $\frac{1}{2}$	6
3	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2 $\frac{1}{4}$	1 $\frac{1}{2}$	6
3 $\frac{1}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2 $\frac{1}{4}$	1 $\frac{1}{2}$	6
3 $\frac{1}{8}$	3 $\frac{3}{4}$	1 $\frac{1}{4}$	2 $\frac{1}{4}$	1 $\frac{1}{2}$	6
3 $\frac{3}{8}$	4	1 $\frac{1}{2}$	2 $\frac{1}{4}$	1 $\frac{1}{2}$	6
3 $\frac{1}{8}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
3 $\frac{5}{8}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
3 $\frac{3}{4}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
3 $\frac{7}{8}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
3 $\frac{1}{4}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
3 $\frac{5}{8}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
3 $\frac{3}{4}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
3 $\frac{1}{2}$	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
4	4	1 $\frac{1}{2}$	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
4 $\frac{1}{8}$	5	2	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
4 $\frac{1}{4}$	5	2	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
4 $\frac{3}{8}$	5	2	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6
4 $\frac{1}{2}$	5	2	2 $\frac{1}{2}$	1 $\frac{1}{2}$	6


* Hole standard taper $\frac{1}{8}$ " to 12" fitting standard arbors. Straight hole can be supplied when so specified.



1828

SPIRAL FLUTED—STRAIGHT SHANK REAMERS.


Diam. Inches	Length Over All Inches	Blades		No. of Blades	Straight Shank Size Inches
		Full Length Inches	Cutting Length Inches		
1	10 $\frac{1}{2}$	1 $\frac{3}{8}$	1	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{1}{8}$	10 $\frac{1}{2}$	1 $\frac{3}{8}$	1	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{1}{4}$	11	1 $\frac{3}{8}$	1	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{3}{8}$	11	1 $\frac{3}{8}$	1	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{1}{2}$	11 $\frac{1}{2}$	1 $\frac{3}{8}$	1	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{5}{8}$	11 $\frac{1}{2}$	1 $\frac{3}{8}$	1	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{3}{4}$	12	1 $\frac{3}{8}$	1 $\frac{1}{4}$	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{7}{8}$	12	1 $\frac{3}{8}$	1 $\frac{1}{4}$	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{1}{2}$	12 $\frac{1}{2}$	1 $\frac{3}{8}$	1 $\frac{1}{4}$	4	1 $\times$ 2 $\frac{1}{2}$
1 $\frac{5}{8}$	12 $\frac{1}{2}$	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{3}{4}$	13	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{7}{8}$	13	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{1}{2}$	13 $\frac{1}{2}$	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{5}{8}$	13 $\frac{1}{2}$	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{3}{4}$	13 $\frac{1}{2}$	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{7}{8}$	13 $\frac{1}{2}$	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{1}{2}$	14	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{5}{8}$	14	1 $\frac{3}{8}$	1 $\frac{1}{4}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{3}{4}$	14	2	1 $\frac{1}{2}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{7}{8}$	14 $\frac{1}{2}$	2	1 $\frac{1}{2}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{1}{2}$	14 $\frac{1}{2}$	2	1 $\frac{1}{2}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{5}{8}$	14 $\frac{1}{2}$	2	1 $\frac{1}{2}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$
1 $\frac{3}{4}$	14 $\frac{1}{2}$	2	1 $\frac{1}{2}$	6	1 $\frac{3}{8}$ $\times$ 2 $\frac{1}{2}$




1847



1827



1846




1847 A

SHELL REAMER ARBORS

A Floating Arbor, Especially Adapted for Use on Gisholt Turret Lathes

Symbol Number	Length Over All	Suitable for Use With Gisholt	For Holding Gisholt Shell Reamers
G-8	20"	13½" Lathe	2¼" to 2½"
H-8	26"	21" Lathe	2¼" to 2½"
H-9	30"	21" Lathe	2½" to 3½"
H-10	30"	21" Lathe	3½" to 4"
H-12	30"	21" Lathe	4½" to 6½"
I-8	30"	24" Lathe	2¼" to 2½"
I-9	30"	24" Lathe	2½" to 3½"
I-10	30"	24" Lathe	3½" to 4"
I-12	30"	24" Lathe	4½" to 6½"
I-14	30"	24" Lathe	6½" and larger
J-8	36"	28" Lathe	2¼" to 2½"
J-9	36"	28" Lathe	2½" to 3½"
J-10	36"	28" Lathe	3½" to 4"
J-12	36"	28" Lathe	4½" to 6½"
J-14	36"	28" Lathe	6½" and larger
K-8	44"	32" Lathe	2¼" to 2½"
K-9	44"	32" Lathe	2½" to 3½"
K-10	44"	32" Lathe	3½" to 4"
K-12	44"	32" Lathe	4½" to 6½"
K-14	44"	32" Lathe	6½" and larger




STRAIGHT SHANK REAMER ARBORS

A Floating Arbor, Especially Adapted for Use on Gisholt Turret Lathes

Symbol Number	Length Over All	Socket Bore	Suitable for Use with Gisholt
	Inches	Inches	
G-2A	14	1	13½ in. Lathe
G-3A	14	1⅝	13½ in. Lathe
G-4A	14	1⅞	13½ in. Lathe
H-2A	18	1	21 in. Lathe
H-3A	18	1⅝	21 in. Lathe
H-4A	18	1⅞	21 in. Lathe
I-2A	22	1	24 in. Lathe
I-3A	22	1⅝	24 in. Lathe
I-4A	22	1⅞	24 in. Lathe
J-2A	26	1	28 in. Lathe
J-3A	26	1⅝	28 in. Lathe
J-4A	26	1⅞	28 in. Lathe
K-2A	30	1	32 in. Lathe
K-3A	30	1⅝	32 in. Lathe
K-4A	30	1⅞	32 in. Lathe


LARGE SHELL REAMERS.



Large holes (above 6" diameter) are very often finished with boring tools, resulting in much greater cost and in lower quality (which means variation in size) than can be produced with the proper kind of reamer.












The chief objection to these large reamers seems to be the weight, which objection is removed if the type shown above in figure 177Z is used.

These reamer bodies may be made of cast iron and have been successfully used in diameters as large as 14".




An actual application of a very large reamer is shown in view 1971 above. This reamer is about 10" diameter. However, as before stated, we have used reamers of this type as large as 14" with excellent results.

The reamer arbor support, shown under the reamer, holds it up in line to enter the hole and still allows enough "float" to produce satisfactory results.



Symbol and number refer to figures on page 158.

- RA1. Standard shell reamer arbor.
- RA2. Shell reamer arbor for large reamers.
- RA3. Standard taper shank reamer arbor.
- RA4. Shell reamer arbor for two reamers.
- RA5. Shell reamer arbor with distance piece between reamers. Arranged with oil chamber for flooding reamers.
- RA6. Reamer arbor support.
- RA7. Taper shank reamer, two diameters.
- RA8. Taper reamer with pilot, and depth gauge RA12.
- RA9. & RA10. Shell reamers with oil tubes. Used on arbor RA5.
- RA11. Shell reamers for cylinders. Each blade has only one cutting edge.
- RA12. Depth gage on taper reamer RA8.




Symbol and number refer to figures on page 160.

- RA14. Shell reamer.
- RA15. Taper shank reamer.
- RA16. Taper shank reamer, R. H. spiral.
- RA17. Taper shank reamer, L. H. spiral.
- RA18. Roughing taper reamer for steel.
- RA19. Shell reamer, R. H. spiral.
- RA20. Shell reamer, L. H. spiral.
- RA21. Taper reamer without pilot.
- RA22. Taper reamer with pilot and inserted blades.
- RA23. Taper reamer with pilot, and inserted blades, and collar on body to take end thrust on blades. Back ends of blades ream straight hole.

Facing Heads.

Facing heads should always be kept as nearly as possible in perfect alignment with the spindle. Before clamping to turret, the base end, or that part which fits against the face of the turret, should be inspected carefully, and all burrs or dirt of any kind removed.

All the adjustable arms should be dismantled and thoroly cleaned and oiled occasionally. This should be done on all new heads before mounting any tools as when they are packed at the factory all machined surfaces are coated with a rust preventive. The gibs in these arms should be pulled up tight as adjustments of the cutters in the arms are easily made after the gibs are tightened.



A support of some kind should always be provided when heads are used. The most common method of support employed is that of holding a pilot bar in the head itself, the other end getting its support in a bushing held in the chuck bore or supported directly in the work. The latter is by far the better and is easily managed as the bore of the work can in many cases be finished at the same time that the rough facing and turning are done. The heads should not be used for *first* roughing cuts. It is sometimes done, but can only result in lowered production.

It is good practice to use a revolving bushing on these supporting arbors whenever possible, that is, when the hole in the work is large enough to permit the use of a bushing with about $\frac{1}{4}$ " wall or more and yet have the arbor of sufficient strength to withstand the strain that is thrown on it from the cutters in the head.

The bushings may be made of steel, hardened and ground providing the arbor is hardened and ground and both surfaces are *glass hard*. Cast iron bushings serve very well, altho they wear out sooner than the hardened steel, but they are very easily replaced and cost much less than steel bushings. Either kind should be well lubricated.

The right hand cut in figure 124Z above shows an ideal application of facing head arbor support. The arbor is held in the facing head and carries a revolving bushing which contains an oil chamber.

The left hand cut shows another method of support. Here the arbor is held in the chuck bore and the work is slipped over a bushing, the bore of which fits the arbor. This method illustrates one use of the face plate arbor.






Figure B10a shows method of chucking for second operation on a countergear. In this case the arbor was held in bore of chuck and the work placed on the arbor and chucked or held with soft jaws bored to fit. The clamps shown in this illustration were added to hold the work back in the jaws, as the amount of stock to be removed on the inside face was so large that it had a tendency to pull the work out of the jaws; the material was very hard.

Occasionally a job will come up that can be handled very nicely on a stub ar-



bor, driven into the bore of the chuck and held with the jaw bases or made with a flange and bolted to face of chuck. A very good illustration of this is shown in figures B51 & B51a. This is an automobile hub, which has previously been finished and the brake drums riveted in place ready for finish turning, which operation is to be done at this time.

Both the outside and inside of the larger drum and the inside of the smaller drum, as well as the faces of both, are finished in this operation. The width of the larger drum made it necessary to have a long, narrow tool for boring. This tool had a tendency to chatter and leave a rough finish.



The cuts referred to (B51 and B51A) show one method of correcting this difficulty after the tools were made up and the job started, also show how this tool is supported to overcome the chatter. A piece of flat stock was bolted to facing head arm and a block of steel clamped between the flat stock and the cutter.

The arbor for this piece was made with an extra long pilot which fitted a bushing in the bore of the facing head, thus supporting it.

ARRANGEMENT OF CUTTERS.

Cutters that are to be used in the bottom arms of the facing head should always be set first, as no adjustment is provided there.

Another very important point for consideration is the arrangement of cutters to prevent interference, one with another.

When the facing heads are used with a heavy supporting arbor, they are as strong and rigid as it is possible to have them; still those tools doing the heaviest


work, such as broad facing, will slightly influence the others. Therefore, it is advisable to arrange the cutters so that those doing the heavy work will tend to pull the turning or boring tools away from the work. This works all right as the facing tools usually do not begin to work until the boring and turning is practically done. And as the head is held up against the work for the facing tools to clean up, the boring and turning tools will return to their original position. In most cases, although not always, the tool carrying the heaviest facing cut can be held in the back arm.

When the size limits on the piece to be machined are very close, it is advisable to use more than two cuts over each surface; the tool post is used for removing the scale as well as most of the stock, then a facing head set up to true those surfaces roughed by the tool post and the finishing head used only to size the most accurate dimensions, removing as little stock as possible. By following this method, the finishing cutters will require a minimum of attention and hold size much longer than if they are required to remove a large amount of stock.

The angles of clearance and top rake on these cutters are the same in principle as those described for tool post tools.



The tools, that are set for broad facing or shaving cast iron, should have from 5 to 7 degrees clearance and from 5 to 10 degrees backslope. If too much clearance is allowed on these broad forming cutters, they will be very apt to chatter. To overcome chatter, either reduce clearance angle or run the work slower.

Forming cutters for steel usually require more back slope or top rake, and less clearance than those used on cast iron. A very satisfactory way of grinding the top rake is shown in figure 173Z below.





In forming steel, it is often found that the chips will adhere to the tool, and leave a rough surface. This can be very nicely overcome by polishing or burnishing the tool on top. This seems to let the chips slide off the tool freely enough so that they will not stick to the cutting edge.



If thread cutting oil is used as a lubricant on steel work, a mixture of about one part kerosene to three or four parts oil will greatly help to overcome this trouble. Also one part powdered sulphur to about forty parts lard oil will help produce better finish than will the oil alone.




FH 1



FH 2





FH 3




FH 4



FH 5



FH 6



FH 7




FH 8




FH 9




FH 10





FH 11




FH 12





FH 13



FH 14




115Z




FH 15

Symbol and number refer to figures on page 166.




- FH1. Facing head body.
- FH2. Facing head front arm.
- FH3. Facing head top and rear arm.
- FH4. Facing head top arm slide.
- FH5. Facing head slider stud.
- FH6. Facing head rear arm slide.
- FH7. Facing head block used on FH4.
- FH8. Facing head arm stud.
- FH9. Facing head block to hold square steel for turning.
- FH10. Facing head block to hold square steel for boring.
- FH11. Special facing head block for wide cutter.
- FH12. Drift pin.
- FH13. Special facing head block for boring tapers.
- FH14. Special facing head block for boring.
- FH15. Special rear arms slide for boring.



FH 16



FH 17



FH 18



FH 19



FH 20



FH 21



FH 22



FH 23



FH 24




FH 25



FH 26




FH 27




FH 28



FH 29



FH 30



FH 31



FH 32



FH 33




FH 34



FH 35



FH 36



FH 37



FH 38



FH 39



FH 40




FH 41



FH 42



FH 43




FH 44


116Z

Symbol and number refer to figures on page 168.

- FH16. Special facing head arm for turning long work.
- FH17. Special front arm.
- FH18. Special facing head block.
- FH19. to FH44. Facing head cutters of various shapes.



FH 45




FH 46




FH 47




FH 48




FH 49




FH 50




FH 51



FH 52



FH 53



FH 54



FH 55



FH 56



FH 57




FH 58




FH 59




FH 60




FH 61




FH 62




FH 63




FH 64



FH 65




FH 66



FH 67



FH 68



FH 69





FH 70

117Z

Symbol and number refer to figures on page 170.

- FH45. to FH60. Facing head cutters of various shapes.
- FH61. Facing head bushing. Used in facing head body when work is held on face plate arbor.
- FH62. Facing head supporting arbor, bushing shrunk on.
- FH63. Facing head supporting arbor with bushing and slot for facing cutter.
- FH64. Supporting bushing.
- FH65. Facing head supporting arbor with bushing to adjust arbor for length.
- FH66. Facing head supporting arbor with bushing to adjust arbor for length.
- FH67. to FH70. Facing head supporting arbors with bushings.




Symbol and number refer to figures on page 172.

- FH71. Boring bar and arm for boring and turning concentric piston rings.
- FH72. Facing head for boring taper frictions.

Figure 1575 shows pair of taper boring heads as used for boring taper seat in clutch gear shown. The outside taper being turned at the same time with the tool post taper attachment. This taper boring head is the same as shown in figure FH72.

Figure 246Z. This head is more difficult to make than that shown in FH72, but is more reliable.

The principles of operation are the same except that this head is positive in operation as will be seen by cut, while the operation of the FH72 head is dependent on a spring action, and the pressure on the tool.



The head or body "A" is of cast iron and held to the turret in the same manner as is the facing head.

The arbor "B" is of steel, heat treated and ground, with a sliding fit in the main body at both "C" and "D".


The taper at "K" and "L" is exactly the same and, of course, the same as that wanted in the work to be done. This taper is milled flat on the bar, then a groove or keyway of sufficient width is milled in the flat into which is inserted a hardened and ground flat steel key.

The outer end of the pilot is fitted with a bushing which supports directly in the work. Back of the supporting bushing is a flange against which fits a ball thrust bearing.

A sheet iron shield "Y" is bolted to face of head. A close fitting hole is made for stud "N". Then a canvas sleeve "V" is fastened to this shield and the arbor. This keeps the chips out of taper bearing "K" and the canvas sleeve does not interfere with movement of arbor.

After the center hole in the work has been bored for the supporting bushing, and the web of wheel faced, the head is brought forward and the pilot enters the hole. The ball thrust bearing rests against the web of the work and pushes the pilot back into the head as the head is fed forward. This movement forces stud "M" up and stud "N" down thus causing the tool to travel on a taper plane.

The cutter or tool is held in arm "E," which is a gib sliding fit on main arm "H."



Adjustment for size is obtained by stud "N" which is more clearly shown in enlarged section "AA". When adjustment is made, the clamp bolt "O" shown in enlarged section "BB" should be loosened, and, after proper setting is made, the clamp bolt should be tightened up. The cross beam "P" should be held up tight and the stud "M" pushed down tight, so as to remove all lost motion in these parts before tightening the clamp bolt.

To produce accurate diameters or duplicate work, the faces "R" and "S" should be finished before the finish boring of the taper is done.

As head is pulled out of work, the spring "T" returns the arbor "B" to position for starting another cut.

Other arms are frequently arranged on these heads to do outside turning or other operations in connection with the taper boring.

Thread Cutting and Feed Changes.

Nine change gears are furnished with each size of the Gisholt Standard Turret Lathe. Each gear will fit on the upper stud, and also the feed reverse shaft shown in figure 1868, page 14.

In each set of nine gears are two with the same number of teeth; one of these two should always be on upper stud in order to obtain the feeds and threads that are shown on the chart below. This leaves eight of the set to be used on the feed reverse shaft.

Driven Gear		32	36	40	44	46	48	52	56
Threads Per Inch	A	4	4.5	5	5.5	5.75	6	6.5	7
	B	8	9	10	11	11.5	12	13	14
	C	16	18	20	22	23	24	26	28
	D	32	36	40	44	46	48	52	56
Fine Feed In Thousandths	A	.0215	.019	.017	.0156	.015	.014	.0132	.012
	B	.0107	.0095	.0086	.0078	.0075	.007	.0066	.006
	C	.0053	.0048	.0043	.004	.0037	.0036	.0033	.003
	D	.0027	.0024	.0021	.002	.0019	.0018	.0016	.0015

With the eight standard change gears, sixty-four different feed changes are available, ranging from $\frac{1}{4}$ " to .0015" per revolution. Thirty-two changes are shown on chart as threads per inch (which also means cuts per inch) and are obtained with the pull pin in the feed box pulled *out* as far as it will go. The feeds given in decimal figures are obtained with pull pin *in* as far as it will go. (See figure 1868, page 14.)

Thirty-two different leads of thread may be cut with the standard change gears furnished, ranging from 4 to 56 threads per inch. Among these are even threads per inch, such as 4, 6, 8, etc., odd numbers per inch such as 5, 7, 9, etc., also $4\frac{1}{2}$, $5\frac{1}{2}$, $6\frac{1}{2}$, $11\frac{1}{2}$, and $5\frac{3}{4}$ threads per inch. All of these may be cut without the use of backing or reverse belts.

The different size lathes have the following pitch lead screws: the G-13", 3"; H-21", $3\frac{1}{2}$ "; I-24", 4"; J-28", $4\frac{1}{2}$ "; K-34", and L-41", 5".

The lead screw nuts have a number of notches into which a pull pin fits when cutting threads.

On the lead screw nuts having the following pitches—3", 4" and 5", the

notches are located so that one notch equals 1" travel of the carriage, there being three notches in the 3" lead screw nut, four in the 4" and five in the 5".

The 3½" and 4½" lead screw nuts have 7 and 9 notches, respectively, one notch being equal to ½" travel of the carriage.

Threads of even pitch, such as 4, 6, 8, etc., may be cut on any of the lathes regardless of the pitch of the lead screw and you can catch a full thread with the pull pin in any notch on the lead screw nut. An example of this is shown on page 178, figure 187Z. Three tools shown in figure as A, A1 and A2 are located ½" apart, it being ½" from A to A1, and 1" from A to A2. This shows that all threads of even pitch, such as 4, 6, 8, etc., can be caught with the pull pin in any notch on any of the machines, as on some of the machines, each notch represents ½" travel of the carriage, while on others each notch represents 1" travel. In figure 188Z on page 178 is shown a screw with 5 threads per inch. As 5 is an odd number, it is necessary to move the carriage back one full inch in order to catch a full thread. This requires two notches or any number of notches evenly divided by two on H-21" and J-28" machines (where one notch is equal to ½" travel of carriage), while on the others, it is possible to catch full threads with every notch. Three tools shown in figure 31 are located as follows: ½" from A to B and 1" from A to A1. The tool B being ½" from A or, 2½ threads, strikes on top of the thread, as shown.

Figure 189Z on page 178 shows a screw with 5½ threads per inch. As before stated, it is necessary to move the carriage back by half inches or inches, depending entirely on the pitch of the lead screw or the number of notches in lead screw nut. Therefore, in cutting 5½ threads, it is necessary to move the carriage 2" or, 11 threads, to be able to catch a full thread.

The distance from A to B is ½" or one notch on H-21" and J-28" machines and it is apparent that the tool would strike the thread if the carriage were moved back ½". The distance from A to C is 1" and shows where the tool would strike the thread if the carriage were moved back 1". The distance from A to A1 is 2" or 11 threads and shows the tool at the bottom of the thread.

In figure 190Z on page 178 is shown a screw with 5¾ threads per inch. In cutting 5¾ threads per inch it is necessary to move back 4", or 23 threads, to catch a full thread.

The distance between A and B in figure 33 is ½" and shows where the tool would strike if the carriage were only moved ½".

The distance from A to C is 1" and from A to D, 2" and from A to E is 3", so that the tool would strike the thread if the carriage were moved back 1, 2 or 3". The distance from A to A1 is 4" and the tool is shown in position to catch a full thread.

The foregoing rules and the following tables do not apply to lathes, which do not have the notches in lead screw nuts.




FIG. 187-Z




FIG. 188-Z




FIG. 189-Z






FIG. 190-Z

THREAD CUTTING REFERENCE CHART

FOR

Size H-21" with Lead Screw Pitch $3\frac{1}{2}"$.

Size J-28" with Lead Screws Pitch $4\frac{1}{2}"$.



Letters in Table Refer to Foot Notes

— THREADS PER INCH —							
4-R	4.5-Y	5-X	5.5-Y	5.75-Z	6-R	6.5-Y	7-X
8-R	9-X	10-R	11-X	11.5-Y	12-R	13-X	14-R
16-R	18-R	20-R	22-R	23-X	24-R	26-R	28-R
32-R	36-R	40-R	44-R	46-R	48-R	52-R	56-R

R-ANY NOTCH WILL CATCH A FULL THREAD.

X-TWO NOTCHES OR ANY NUMBER EVENLY DIVIDED BY TWO WILL CATCH A FULL THREAD.

Y-FOUR NOTCHES OR ANY NUMBER EVENLY DIVIDED BY FOUR WILL CATCH A FULL THREAD.

Z-EIGHT NOTCHES OR ANY NUMBER EVENLY DIVIDED BY EIGHT WILL CATCH A FULL THREAD.

191-Z



THREAD CUTTING REFERENCE CHART

FOR

Size G-13" with Lead Screw Pitch 3".

Size I-24" with Lead Screw Pitch 4".

Size K-34" with Lead Screw Pitch 5".



Letters in Table Refer to Foot Notes.

— THREADS PER INCH —							
4-R	4.5-X	5-R	5.5-X	5.75-Y	6-R	6.5-X	7-R
8-R	9-R	10-R	11-R	11.5-X	12-R	13-R	14-R
16-R	18-R	20-R	22-R	23-R	24-R	26-R	28-R
32-R	36-R	40-R	44-R	46-R	48-R	52-R	56-R


R-ANY NOTCH WILL CATCH A FULL THREAD.

X-TWO NOTCHES OR ANY NUMBER EVENLY DIVIDED BY TWO WILL CATCH A FULL THREAD.


Y-FOUR NOTCHES OR ANY NUMBER EVENLY DIVIDED BY FOUR WILL CATCH A FULL THREAD.

192-Z

COLLAPSIBLE TAPS AND SELF-OPENING DIES



Collapsible Tap.



Self-Opening Die.

The demand for accurate, rapid production in large quantities has not only helped to develop the turret lathe, but also many time saving devices used in connection with the turret lathe, among which are the Collapsible Tap and Self-Opening Dies for various forms of thread cutting.

The collapsible tap is made with a number of blades inserted in a steel body. When the proper depth is obtained the blades collapse, eliminating the necessity of backing the tap out of the hole.

Straight threads ranging from $1\frac{1}{4}$ " to $5\frac{1}{2}$ " in diameter, and from $\frac{3}{8}$ " to $2\frac{1}{2}$ " deep; also pipe threads from 1" to 5" in diameter may be tapped at a great saving with collapsible taps.

The self-opening die is made to open automatically when reaching a predetermined point on the screw, eliminating the necessity of screwing it off the work, and will cut straight threads ranging from $\frac{1}{16}$ " to $3\frac{1}{2}$ " in diameter and pipe threads from $\frac{5}{8}$ " to 3" diameter.

The shanks of both taps and dies can be made to suit holders in use.

The principles of operation are practically the same in both the collapsible tap and self-opening die.

The blades or dies vary in number with the size of the head, and are brought into cutting position by cams and plungers, and are usually released by a spring action of some kind. Many of them are arranged to take roughing and finishing cuts, thereby getting a better and smoother thread. Adjustment being provided to compensate for wear, gives the dies a very long life and also makes it possible to hold a standard size.

By reference to the current issues of the trade papers, names of various makers will be found who are glad to furnish catalogs with data and information covering the use and operation of their taps and dies.

At times, two taps are used to finish a thread of particular dimensions, one as a rougher which may be of the collapsible type, and one as a finisher which may be of either the collapsible or solid type.

It may be found a little difficult always to start the second tap in the lead of the first tap if the second tap is held solid in the turret.







Figure 2004 shows a method which we have used successfully. Here the shank of tap is a sliding and revolving fit in the tap holder. It has a hole thru it in which is inserted a round piece of stock that serves as a driver.

The operator starts the tap by this driver as he would in hand tapping. After tap is started in a couple of threads, the driver may be allowed to rest on cross slide until tap has reached its proper depth.



The work shown in this cut is a 6" high explosive shell and a solid tap is used for finish tapping. It is run all the way thru the piece and removed when piece is taken from jaws.




TH1




TH2




TH3



TH4








TH5




TH6

121Z

- TH1. Standard tap holder.
 TH2. Holder for square shank taps. Part of bar tool equipment.
 TH3. Solid tap.
 TH4. Tap holder extension.
 TH5. Tap with inserted blades.
 TH6. Extension for using square shank taps in standard tap holder.



- TH7. Tap bar for tapping threads on both ends of work.
 TH8. Tap for cutting thread of two diameters and same pitch at same time.
 TH9. Special tap, inserted blades.
 TH10. Pipe tap, solid.
 TH11. Pipe tap, inserted blade.
 TH12. Tap with pilot.




TH 13

TH13. Standard die holder.

Machining of Heavy Pieces.

On this and the following pages are a few illustrations, showing how a rather heavy automobile fly wheel (see cut 137Z page 188) was finished complete in two operations on a Gisholt Turret Lathe.

In figure B45a is shown a set of three oscillating jaws, each having two points bearing on the work, giving a six point bearing. These jaws were used for chucking on the inside of the fly wheel rim. In one of these jaws is shown a pin which serves as a driver and holds that jaw solid, the other two being arranged so that they are free to oscillate and adjust themselves to the rough surface of the casting.



You will note there are six studs located on the face of the chuck, three of which are used for locating the wheel for the first operation and three for the second. The circles, at which the studs support the fly wheel for the first and second operations, are of different diameters so it is possible to leave all six studs permanently located.

The amount of work on this particular wheel requires more than four tool post tools.


In figure B45b, six of these tools, are shown on bed and cross slide, which were used and changed in one side of the tool post. These tools were all used in connection with carriage stops and the index dial on the cross feed screw.

Adjusting screws were placed in the end of each tool and used as locating

points against a small square block set in the corner of the tool post. This plan works out very nicely and also very accurately, it being necessary to adjust the screw in the end only after each grinding, and, by having a finished piece in the machine, the tool can be ground and the screws adjusted to the proper length.

The wheel being very large and quite wide, a special arm was made and used on the back side of the facing head for finish turning the outside diameter.

Figure B45c illustrates how a casting may be rough turned with a tool in the tool post and finish turned with a tool in the facing head at the same time. The finishing tool, or 2nd roughing tool, follows the tool post roughing tool within approximately $\frac{1}{4}$ ". A better illustration of this particular point is shown in figure 137Z, page 188.






By this method, it is possible to take two cuts over the same surface in the time of one.

In figure B46a, page 189, is shown a set of special extra wide, soft jaws, turned to fit the bore as finished in the first operation.

The studs shown at the small end, or inner circle of the jaws, support the web of the wheel when rough facing the opposite side; the wheel is also supported on the rim by studs in the face of the chuck. On wheels of this kind, where the web is comparatively thin, the web will spring away from the tool during roughing cut. By keeping the distance from the face of the rim to the face of the finished web accurate on the first operation, it is possible to arrange supporting studs at both these points.


This fly wheel is quite heavy for an automobile fly wheel, weighing approxi-





mately 225 lbs. in the rough. For this reason, a table was built about the same height as the top of the tool post carriage and placed in front of the machine far enough away so as not to interfere with movements of the operator. The table was then loaded with wheels as often as necessary by helpers, and, by means of a removable board between the table and the machine, the wheels could be rolled very easily to and from the machine by the operator. Thus he could proceed with his work at all times without having to wait for assistance to take a piece in and out of the machine, or bothering with a hoist of any kind.

Figure B46b shows two tool posts tools at work at the same time, facing the web and the rim of the wheel.



It shows the serving table as previously described and shown in figure B46a.


The inside of the rim of this wheel is rough bored with a tool post tool and finish bored with a tool held in the facing head.

In figure B46c, the tool post tool is rough boring and the facing head tool is finish boring at the same time, the finishing cutter following very close to the roughing cutter. The other tools shown in the top arm are arranged for rounding the corners.


Layout, Instruction and Time Study Sheets.

The cast iron fly wheel ring as shown in figure EB5, page 191, was finished complete, within the size limits shown, in four operations on a standard 24"-6 $\frac{1}{4}$ " bore Gisholt Turret Lathe. This work was done in a plant, which, like many others, is compelled to run thru work in rather small quantities, necessitating

frequent changes from one job to another. To enable an operator or set-up man to accomplish these changes in the shortest possible time, form sheets have been worked out and successfully used to record the location of tools in a very efficient manner. Also records of feeds, speeds, etc., may be kept.



These sheets may be obtained at cost upon application to the Gisholt Machine Company, and, when called for, should always be ordered by form number which is found in the lower left hand corner of the sheet. These are called layout, instruction and time study sheets.



E.B. 5 250-2

The layout sheet (form No. 96) is used primarily to lay out the location of the tools in the turret and the tool post, when considering new equipment for a job. On page 193 is shown a sample of the layout sheet, as it was filled in when planning the tools for the Cast Iron Fly Wheel Ring, shown in figure EB5.

Another way in which they are used is shown on pages 205 and 206. Here the number of each tool is recorded opposite the tool, and when they are being arranged on the machine, this proves a very valuable guide and time saver for the set-up man.

After the tools have been tried out in actual practice and all changes made, their location should be recorded on instruction sheet (Form No. 57).

Provision is made on this sheet to record the change gear used in the feed box and also the length of any special stop screws for either the tool post carriage or the turret.

A cut of the Drill Support is shown where any standard or special bushing may be recorded.

On some of these sheets, you will note that an end view of the facing head is shown, giving the numbers of the cutters with arrows running to the slots in which they are used.

The time study sheet (form No. 90) is for belt driven machines and is used to record all the data on operating machine, including feeds and speeds, the position of the operating levers, and the step of the cone pulley which is used.

On pages 195, 198, 201 and 204, are samples of these forms which have been filled out complete including detail time for each cut.

The term "operate machine" used on these sheets means the time used between cuts or the time required to turn the tool post and turret, and change them from one position to another, or all the time spent when no tool was actually cutting.

Form No. 365, page 207, is used to record this data for motor driven machines. A controller is shown at the top of sheet with graduations from one to ten in both forward and reverse directions. The controller on your machine may not be marked in this way, but in order to get the greatest benefit from the Time Study Sheet they should be marked, and numbered.

The column headed by "Controller at" should be filled in with the graduation number at which the lever pointer stands when proper speed is found.

The column headed "Speeds" is filled in with either of the letters "H", "I", or "S" thus recording the position of the operating levers and whether the High, Intermediate, or Slow Speed was used.

The "Spindle R. P. M." column is for recording the revolutions per minute of the spindle.

The "Pull pin" is in the feed box and a record should be made as to its location whether "in" or "out".

The "Feed" used should be recorded in the column provided for that purpose.

The last column is for the time required for each individual cut or operation.

The rest of the sheet is very plain, as is the one used for Belt Driven Machines which is shown filled in with an actual record made.

LAYOUT SHEET— Operation No 1


202-Z

For arranging tools on 24" GISHOLT TURRET LATHE, No. 6-601 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL RING Mat C1 Drawing No 11798 Part No. 11798

Change Gear 40 Teeth



REMARKS:—

- 1-Chuck on O.D. with soft jaws.
- 2-Rough turn A with tool in side 4 of tool post.
- 3-Rough face B with tool in side 4 of tool post
- 4-Rough bore C with tool in side 3 of tool post, 1" deep.

204-Z

INSTRUCTION SHEET—Operation No. 1

For arranging tools on 24" GISHOLT TURRET LATHE, No. 6-601 Date 6-6-66.
Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.
Part FLYWHEEL RING Mat. C.I. Drawing No. 11798 Part No. 11798

Change Gear 40Teeth

PULL PIN OUT- FOR COARSE FEED
IN- FOR FINE FEED

FEED LEVER

CARRIAGE STOPS

No.	1	2	3	4
LENGTH				

DRILL SUPPORT

TOOL POST

TURRET

LATHE No. 6-601
FOUND HERE

TURRET STOPS

No.	LENGTH
1	
2	
3	
4	
5	
6	

TOOL POST

Tool for rough turning and rough facing.

D-6

Tool for rough boring.

D-7

TOOL POST

CHUCK

DRILL SUPPORT

TURRET

FACE No. 1

FACE No. 2

FACE No. 3.

FACE No. 4

FACE No. 5

FACE No. 6

BELT DRIVE

TIME STUDY - Operation No. 1


203-Z

For 24"-4 1/4"

GISHOLT TURRET LATHE, No. 6-601 Date 6-6-'66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.


Part FLYWHEEL RING Mat. C.I. Drawing No. 11798 Part No. 11798



Change Gear 40 Teeth

BELT ON CONE STEP

SPEEDS	SPINDLE R.P.M.	PULL PIN	FEED	MIN.-SEC.
--------	----------------	----------	------	-----------



Chuck

Rough turn A

Rough bore C-1" deep

Rough face B

Operate machine

Total floor to floor time

1 ST OPERATION	4:00
2 ND	
3 RD	
4 TH	
Complete	

LAYOUT SHEET ~ Operation No 2


199-Z

For arranging tools on 24" GISHOLT TURRET LATHE, No 6-601 Date 6-6-66

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL RING Mat. C.I. Drawing No 11798 Part No 11798

Change Gear 40 Teeth



REMARKS:—

- 1-Chuck in special split jaws
- 2-Rough turn D with tool in side 4 of tool post.
- 3-Rough face E with tool in side 4 of tool post.
- 4-Rough turn F with tool in side 4 of tool post.
- 5-Rough face G with tool in side 4 of tool post.
- 6-Rough bore C to jaws with tool in side 3 of tool post.
- 7-Finish face E & G with tools in side 1 & 2 of tool post.
- 8-Finish turn D & F & finish bore C with tools in facing head, side 1 of turret
- 9-Break corners with file

INSTRUCTION SHEET—Operation No 2

201-Z

For arranging tools on 24 " GISHOLT TURRET LATHE, No 6-601 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL RING Mat. C.I. Drawing No 11798 Part No. 11798

Change Gear 40Teeth



PULL PIN
OUT- FOR COARSE FEED
IN- FOR FINE FEED

FEED LEVER



CARRIAGE STOPS

No.	1	2	3	4
LENGTH				

DRILL SUPPORT




CHUCK



TOOL POST



TURRET



LATHE NO. FOUND HERE



TURRET STOPS

No.	LENGTH
1	
2	
3	
4	
5	
6	

TOOL POST

Tool for rough turning and rough facing.

Tool for rough boring.

Tools for finish facing.

Tools for finish turning and finish boring.


D-6

D-7

D-12

D-13

TOOL POST



Chuck in special split jaws.

DRILL SUPPORT

TURRET


FACE No. 1 FACING HEAD

Cutter No D-8

" " D-9

" " D-10

Tools for finish turning and finish boring.



FACE No. 2

FACE No. 3

FACE No. 4

FACE No. 5

FACE No. 6

Form No. 57

GISHOLT MACHINE CO., MADISON, WIS.

SHEET No. I-311-2

Digitized by Google

SHEET No. T-311-2

LAYOUT SHEET ~ Operation No. 3


196-Z

For arranging tools on 24" GISHOLT TURRET LATHE, No. 6-601 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL RING Mat. C.I. Drawing No. 1179B Part No. 1179B

Change Gear 40 Teeth



REMARKS:-

- 1-Chuck in face plate fixture driving with soft jaws turned to fit
- 2-Rough face K with tool in side 4 of tool post.
- 3-Rough turn A with tool in side 4 of tool post.
- 4-Rough face B with tool in side 4 of tool post.
- 5-Rough bore C with tool in side 3 of tool post.
- 6-Finish face K & B with tools in side 1 & 2 of tool post.
- 7-Finish turn A & M & bore C with tools in facing head, side 1 of turret.
- 8-Break corners with file.


INSTRUCTION SHEET—Operation No. 3

198-Z

For arranging tools on 24" GISHOLT TURRET LATHE, No. 6-601 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL RING Mat. C. I. Drawing No. 11798 Part No. 11798



TOOL POST		CHUCK in fixture D-1 with soft jaws D-4 turned to fit for driving
Tool for rough turning and rough facing. D-6	Tool for rough boring. D-7	
Tools for finish facing. D-12 D-13		DRILL SUPPORT

TURRET		
FACE No. 1 FACING HEAD Cutter No. D-8 " " D-9 " " D-14 Tools for finish turning and finish boring	FACE No. 2	FACE No. 3
FACE No. 4	FACE No. 5	FACE No. 6

[illegible]

LAYOUT SHEET~ Operation No. 4


193-Z

For arranging tools on 24" GISHOLT TURRET LATHE, No. 6-601 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL RING Mat. C.I. Drawing No. 11798 Part No. 11798

Change Gear 40 Teeth



REMARKS:—

1-Chuck in face plate fixture & hold with clamps.

2-Finish bore C with tool in facing head, side 1 of turret.


INSTRUCTION SHEET—Operation No. 4

195-Z

For arranging tools on 24" GISHOLT TURRET LATHE, No. 6-601 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL RING Mat. C.I. Drawing No. 11798 Part No. 11798



TOOL POST		CHUCK in face plate with clamps D-13 for driving.
4	TOOL POST 3	
1	2	DRILL SUPPORT

TURRET		
FACE No. 1 FACING HEAD CUTTER No. D-8 Tool for finish boring.	FACE No. 2	FACE No. 3
FACE No. 4	FACE No. 5	FACE No. 6

Form No. 57

GISHOLT MACHINE CO., MADISON, WIS.

SHEET No. I-311-4

BELT DRIVE **TIME STUDY—Operation No 4** 194-Z


For 24"-4 1/4" GISHOLT TURRET LATHE, No. 6-601 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.


Part FLYWHEEL RING Mat C.I. Drawing No. 11798 Part No. 11798




FEED LEVER




PULL PIN
OUT- FOR COARSE FEED
IN- FOR FINE FEED




K L M
SPEED SPEED SPEED
150 R.P.M. 260 R.P.M. 370 R.P.M.
COUNTERSHAFT



1 2 3
LATHE
CONE PULLEY



OPERATING
LEVERS
S SLOW
SPEED
H HIGH
SPEED
I INTERMEDIATE
SPEED

Change Gear 40 Teeth		BELT ON CONE STEP	SPEEDS	SPINDLE R.P.M.	PULL PIN	FEED	MIN-SEC.
 c	Chuck						1:00
	Finish bore C with						
	facing head.	3	M-S	14	OUT	B-10	1:35
	Operate machine						:55
Total floor to floor time							4:00 15:00 9:30 3:30 Complete 32:00

LAYOUT SHEET ~ Operation No. 2


206-Z

For arranging tools on 34" GISHOLT TURRET LATHE, No. 10-702 Date 6-6-66.

Company HIGH POWER MOTOR PARTS CO., BAY CITY, CAL.

Part FLYWHEEL Mat. C.1 Drawing No. 2819 Part No. 2819

Change Gear 32 Teeth



REMARKS:-

- 1-Chuck with soft jaws against 3 chuck jacks faced off parallel.
- 2-Rough L-M-N & O with tool in side 2 of tool post.
- 3-Rough K with tool in side 4 of tool post.
- 4-Rough A with tool in side 4 of tool post. First cut.
- 5-Rough A-N & O with cutters in facing head, side 1 of turret.
- 6-Finish A-N & O with cutters in facing head, side 4 of turret.
- 7-Finish K with tool in side 2 of tool post.

SHEET No.



TOOL STORAGE.

In order to have a department of turret lathes working to the highest point of efficiency, it is necessary to have a place of some kind in which to store and properly take care of all extra tools, and tools not in use.

Figure B5a shows a cabinet containing open bins, as well as drawers, which was used in a department of ten Gisholt Turret Lathes.


Some of the drawers were used for blue prints and other data concerning the department work.

Correctly machined samples of the different pieces were made and used to gage the setting of facing head cutters when setting up the jobs.

A desk for the department foreman was built in one end of the cabinet and proved very convenient.

All the tool post tools were ground on the Gisholt Universal Tool Grinder shown, and then stored away, sharpened, ready for use.

Small cabinets, like one shown at the left hand of large cabinet, were made for each machine. These were for individual use of each operator in which he kept all tools for his particular machine, such as standard chuck jaws, wrenches, etc. The two drawers were fitted with separate locks and were used by the night and day man for their own private tools.



RANGE OF GISHOLT TURRET LATHE.

In above figure B31, is shown a standard 24" Gisholt Turret Lathe and tools for finish turning and cutting off cross head pins.

On the floor at the end of the machine are shown a number of jobs which were successfully handled on this machine, ranging from small nuts and washers to comparatively large piston rings, crank discs and cylinder heads.

This machine is used in rather a small plant, engaged in the manufacture of steam engines and employing about fifty men. The size of the shop in a way accounts for the great variety of work, and large variation in the sizes of the parts. This work is done in lots of not more than twelve pieces of a kind at one time.

HELPFUL SUGGESTIONS.

Locate your trouble, then remove the cause.

Keep the machine well oiled at all times.

Keep the spindle bearings properly adjusted. Bearings will wear longer and proper adjustment helps to prevent tool chatter.

Keep end play out of spindle. The work will be more nearly true and the tools less apt to chatter.

Provide support for all tools as near as possible to cutting edge. Lack of support sometimes causes unnecessary breakage and chatter.

Have no more clearance on cutters and tools than absolutely necessary. This insures longer life to cutters and helps to reduce chatter.

Excessive speed will cause chatter.

As a last resort, to eliminate chatter, reverse the tool and run the lathe backward.

Have all cutting tools ground on bottom, after hardening, if possible. If bottom is uneven, they are apt to break when clamped in position.

Keep your tools sharp and have a suitable place in which to store them when not in use.

If cutters require grinding too often, have them tested for hardness.

Reamer blades should never be backed off closer than .006" to .010" to the cutting edge.

Always use cutting oil of some kind when reaming steel. Be sure reamer has plenty of chip clearance and keep it sharp.

The corners of blades in reamers, boring bars or cutter heads should never be ground by hand, as they should be exactly even.

If reamer cuts just a little large in cast iron use a little oil for a few holes, then discontinue oil.

Leave as little stock as possible for reaming.

The slower the speed and the finer the feed for forming cutters, the better the finish.

Kerosene or coal oil gives a fine finish on aluminum. Also when mixed: one part kerosene to three or four of lard oil, it produces fine finish on steel, if run slow, with fine feed for forming cutters.





One part powdered sulphur to forty parts thread cutting oil will help produce fine finish on steel, especially soft mushy steel.





A little sulphur mixed with machine oil will increase its lubricating qualities.

Running fits or boring bar pilots and supporting bushings require approximately .001" clearance to each inch in diameter.

If rapid traverse frictions do not engage readily put in a little kerosene or coal oil. NEVER GASOLINE.

Instructions for Ordering Parts.





Repair Parts.

In its quarter century of manufacturing experience, the Gisholt Machine Company has furnished to the manufactures of the world several thousand turret lathes.

The machines from the start have been so simple in design, and so well constructed that the repair part of the business has been relatively very small.

However, accidents occasionally will happen, and at times repairs must be made, at which time speed is generally all important.

After many months of painstaking effort, our service department has compiled a list of parts, giving symbols, numbers and names, also illustrated by photographs and line drawings, so as to enable anyone who desires to get what he needs quickly and exactly.

When parts are ordered from these lists, we must have the **SYMBOL, NUMBER AND FULL NAME OF PIECE**, also the **NUMBERS FOUND ON THE ENDS OF THE V'S OF THE LATHE** (See fig. 1).


If the numbers cannot be found on the ends of the V's, the **EXTREME WIDTH OF THE BED AT THE V'S SHOULD BE GIVEN** (See fig. 2), also the **BORE OF THE SPINDLE**. This information is essential owing to the different sizes and types of lathes that have been built.

In case the part wanted cannot be found in these lists, and, if that part shown, which performs the same function, is not near enough like the part wanted, a **SKETCH WITH THE PRINCIPAL DIMENSIONS** should be furnished with the above mentioned information regarding **NUMBERS ON V'S OR DISTANCE BETWEEN V'S, ALSO THE SPINDLE BORE**.


Parts for types 1899, 1905, 1913 and 1916 are usually carried in stock.

Parts for types 1885, 1887, 1890 and 1893 must be made up after receipt of order. (See pages 212 and 213.)

When ordering parts for chucks, always send a **SKETCH OF PART REQUIRED WITH PRINCIPAL DIMENSIONS**.



172 Z



HEADSTOCK. UNIT A. SYMBOL H.



WHEN ORDERING REPAIRS FOLLOW INSTRUCTIONS ON PAGE 214.

LISTS OF PARTS FOR HEADSTOCK


I Assembled Headstock

Symbol and No.	Code Word	Name
H1	Fabab	Friction, Long
H2	Fabdi	Headstock, Rear Bushing
H3	Fabed	Friction, Short
H4	Fabho	Friction Gear
H5	Fabig	Chuck, Ring Gear
H6	{ Fabju }	{ Spindle, Rear Box Adj. Nuts
H7		
H8	Fabry	Cone Pulley Adj. Nut
H9	Fabun	Spindle
H10	Fabva	Spindle, Front Thrust Washer
H11	Facaz	Spindle, Front Box Rear Adj. Nut
H12	Facdo	Spindle, Front Box Front Adj. Nut
H13	Facef	Back Gear Shaft Lever Bracket
H14	Fachu	Back Gear Shaft, End Collar
H15	Facjy	Back Gear Shaft Lever Link
H16	Facok	Back Gear Feather Key
H17	Facra	Back Gear Shaft, Locating Collar
H18	Facup	Back Gear Shaft
H19	Facve	Headstock, Front Bushing
H20	Fadad	Spindle, End Thrust Washer
H21	Faddu	Spindle, End Thrust Adj. Nut
H22	Fadeg	Back Gear
H23	Fadhy	Back Gear Nut
H24	Fadja	Friction Slider Blocks
H25	Fadol	Friction Slider Block Screws
H26	Fadre	Headstock Bracket Plunger
H27	Fadur	Headstock Bracket Plunger Spring
H28	Fadvi	Headstock Friction Lever Yoke Shaft
H29	Fafaf	Back Gear Shaft Lever
H30	Fafdy	Back Gear Shaft Lever Bracket, Single Shoulder Screw
H31	Fafha	Back Gear Shaft Lever, Double Shoulder Screw
H32	Fafik	Friction Slider Dog Pins
H33	Fafje	Friction Slider Dogs
H34	Fafom	Spindle Driving Nut Screws
H35	Fafri	Friction Slider
H36	Fafus	Friction Gear Driving Pinion

Symbol and No.	Code Word	Name
H37	Fafvo	Spindle, Front Box Oil Ring
H38	Fagag	Headstock Friction Lever
H39	Fagda	Headstock Friction Lever Yoke
H40	Fagej	Spindle, Feed Driving Gear
H41	Faghe	Back Gear Driving Pinion
H42	Fagil	Spindle Driving Nut
H43	Fagji	Spindle, Rear Box Oil Ring
H44	Fagon	Spindle, Rear Box
H45	Fagro	Cone Pulley
H46	Fagut	Friction Gear Adj. Nut
H47	Fagvu	Spindle, Front Box
H48	Fajah	Headstock Bracket

WHEN ORDERING REPAIRS FOLLOW INSTRUCTIONS ON PAGE 214.

MAIN FEED BOX. UNIT B. SYMBOL E.



WHEN ORDERING REPAIRS FOLLOW INSTRUCTIONS ON PAGE 214.

LIST OF PARTS FOR MAIN FEED BOX


- 1—End View Assembled Feed Box
 2—Front View Assembled Feed Box
 3—Back View Assembled Feed Box
 4—Top View Assembled Feed Box

Symbol and No.	Code Word	Name
E1	Falky	Fine Feed Loose Gear
E2	Falni	Fine Feed Driving Pinion
E3	Falos	Pull Pin & Cross Pin for Coarse or Fine Feed
E4	Falta	Change Gear Nuts
E5	Falux	Change Gear Washer
E6	Famal	Change Gear 56 Tooth
E7	Fambu	Change Gear 32 Tooth
E8	Famen	Change Gear 36 Tooth
E9	Famfy	Change Gear 40 Tooth
E10	Famir	Change Gear 44 Tooth
E11	Famka	Change Gear 46 Tooth
E12	Famno	Change Gear 48 Tooth
E13	Famot	Change Gear 52 Tooth
E14	Famte	Feed Reserve Shaft
E15	Famuz	Feed Reserve Shaft Mitre Gear Complete
E16	Fanam	Feed Gear Shaft Collar
E17	Fanby	Feed Gear Shaft
E18	Fanco	Feed Reverse Sector
E19	Fanep	Feed Reverse Lever
E20	Fanfa	Feed Reverse Clutch
E21	Fanis	Feed Gear 20 Tooth
E22	Fanke	Feed Gear 30 Tooth
E23	Fannu	Feed Gear 40 Tooth
E24	Fanov	Intermediate Stud Washer
E25	Fanti	Intermediate Gear Bracket & Stud
E26	Fapan	Intermediate Gear Bushing
E27	Fapba	Intermediate Stud Driving Gear
E28	Faper	Intermediate Stud Driven Gear
E30	Fapit	Feed Worm Shaft Gear 48 Tooth
E31	Fapki	Feed Worm Shaft Gear 40 Tooth
E32	Fapny	Feed Worm Shaft Gear 30 Tooth
E33	Fapoc	Feed Worm Shaft Gear 20 Tooth
E35	Fapud	Feed Worm Shaft Feather Key Disengaging Rings

Symbol and No.	Code Word	Name
E36	Farap	Feed Box
E37	Farbe	Feed Worm Shaft Feed Pinion Retaining Nut
E38	Farfi	Feed Worm Shaft
E39	Faric	Feed Worm Shaft Feed Pinion & Collar
E40	Farko	Feed Worm
E41	Farna	Feed Worm Shaft Slider
E42	Farox	Feed Box Front Housing Top Cover
E43	Fartu	Feed Worm Shaft Feather Key & Spring
E44	Faruf	Feed Worm & Vertical Spiral Gear Shaft Idler Gear
E45	Fasar	Feed Worm & Vertical Spiral Gear Shaft Idler Stud
E46	Faset	Feed Box Front Housing
E47	Fasgo	Feed Change Slider
E48	Fasiv	Feed Change Slider Shaft
E49	Faslu	Vertical Spiral Gear Shaft Drive Gear
E50	Fasme	Vertical Spiral Gear Shaft
E51	Fasoz	Vertical Spiral Gear
E52	Faspy	Fine Feed Back Gear Pinion
E53	Fasug	Feed Change Slider Shaft Collar
E54	Fatas	Quadrant Clamping Bolt
E55	Fatev	Quadrant
E56	Fatgu	Quadrant Idler Gear Stud Collar
E57	Fatix	Quadrant Idler Gear Stud
E58	Fatly	Quadrant Idler Gear Stud Nut
E59	Fatmi	Fine Feed Back Gear Stud
E60	Fatob	Fine Feed Back Gear Collar
E61	Fatpa	Quadrant Idler Gear
E62	Fatso	Fine Feed Back Gear
E63	Favat	Feed Gear Shaft Bevel Gear

WHEN ORDERING REPAIRS FOLLOW INSTRUCTIONS ON PAGE 214.

TURRET SLIDE. UNIT C. SYMBOL C.



WHEN ORDERING REPAIRS FOLLOW INSTRUCTIONS ON PAGE 214.

LIST OF PARTS FOR TURRET SLIDE

- 1—Turret Slide Complete
- 2—Turret Apron (Front View)
- 3—Rapid Traverse Friction Housing
- 4—Rapid Traverse Friction Housing
- 5—Turret Apron (Rear View)


Symbol and No.	Code Word	Name
C1	Fefut	Turret Apron Bonnet
C2	Fefvu	Turret Clamp Ring Bracket
C3	Fegah	Turret Apron Pilot Wheel Shaft
C4	Fegde	Turret Clamp Ring Bracket Handle
C5	Fegek	Turret Slide Feed Trip Crank Shaft
C6	Feghi	Turret Apron Pilot Wheel
C7	Fegim	Turret Apron Bonnet Retaining Screws
C8	Fegjo	Turret Stop Screws
C9	Fegop	Turret Apron Pilot Wheel Handle Bar
C10	Fegru	Turret Apron Pilot Handle
C11	Feguv	Turret Bushings
C12	Fegvy	Turret Clamping Screws
C13	Fejaj	Turret Base Retaining Screws
C14	Fejbi	Turret Spindle Retaining Screws
C15	Fejel	Rapid Traverse Friction Ring Plungers
C16	Fejfo	Rapid Traverse Friction Ring Adjusting Screws
C17	Fejin	Rapid Traverse Friction Nut Thrust Washer Screws
C18	Fejku	Turret Clamp Ring Stud
C19	Fejne	Turret Locating Pin Bushings
C20	Fejor	Turret Stop Bar Nut
C21	Fejty	Turret Apron, Feed Friction Link Catch Screw
C22	Fejuc	Turret Slide Stop Block Clamp Screws
C23	Fekak	Rapid Traverse Friction, Link Retaining Screw
C24	Fekbo	Rapid Traverse Friction Housing Retaining Screws
C25	Fekem	Rapid Traverse Friction Operating Lever Bracket
C26	Fekfu	Rapid Traverse Friction Operating Lever Retaining Screw
C27	Fekip	Rapid Traverse Friction Operating Lever
C28	Fekky	Turret Slide Gib Front (Left)
C29	Fekni	Turret Slide Gib Front (Right)
C30	Fekos	Turret Slide Front Gib Screws
C31	Fekta	Turret Stop Bar Rotating Screw
C32	Fekux	Turret Base Dowel Pins

Symbol and No.	Code Word	Name
C33	Felal	Turret Slide Gib Adjusting Screw (Front)
C34	Felbu	Turret Slide Front Gib Clamp Screw (Left)
C35	Felen	Turret Slide Gib Adjusting Screws (Rear)
C36	Felfy	Turret Apron Screws
C37	Felir	Turret Slide Gib Clamp Screws (Rear)
C38	Felka	Turret Clamp Ring Bracket Retaining Screws
C39	Felno	Turret Clamp Ring
C40	Felot	Turret Clamp Ring Clamping Screw
C41	Felte	Turret Spindle, End Thrust Adjusting Nut
C42	Feluz	Turret Base, Locating Pin Collar Retaining Pin
C43	Femam	Turret Stop Bar Stop Carrier Plunger and Spring
C44	Femby	Turret Stop Bar Carrier Plunger and Spring Retaining Screw
C45	Femco	Turret Locating Pin Pinion Tappet Plate and Screws
C46	Femep	Turret Base, Locating Pin Retaining Plate Screws
C47	Femfa	Turret Stop Bar Positive Stop Adjusting Nut
C48	Femis	Turret Base, Locating Pin Collar
C49	Femke	Turret Base Bushings for Guiding Locating Pin
C50	Femnu	Turret Stop Bar Spring
C51	Femov	Turret Apron, Feed Trip Link
C52	Femti	Turret Apron, Feed Trip Lever
C53	Fenan	Turret Apron, Feed Trip Lever Handle
C54	Fenba	Turret Apron, Feed Trip Link Stud
C55	Fener	Turret Slide Feed Trip Crank
C56	Fenfe	Turret Apron, Feed Friction Dog Plug
C57	Fenit	Turret Apron, Feed Change Lever
C58	Fenki	Turret Apron, Feed Change Lever Collar
C59	Fenny	Turret Apron, Feed Friction Dog
C60	Fenoc	Turret Apron, Feed Friction Dog Handle
C61	Fento	Rapid Traverse Friction Eccentric Shaft Crank
C62	Fenud	Rapid Traverse Friction Eccentrics
C63	Fepap	Rapid Traverse Friction Eccentrics Shaft
C64	Fepbe	Turret Apron Lead Screw Adjusting Nut
C65	Fepes	Rapid Traverse Friction Ring
C66	Fepfi	Turret Apron, Feed Friction Dog Handle Catch Pin
C69	Fepna	Turret Apron, Feed Change Lever Handle
C70	Fepox	Rapid Traverse Friction Nut (Left Hand Thread)
C71	Feptu	Rapid Traverse Friction Nut (Right Hand Thread)
C72	Fepuf	Rapid Traverse Friction Nut Thrust Washer
C73	Ferar	Turret Apron Lead Screw Nut

Symbol and No.	Code Word	Name
C74	Feret	Rapid Traverse Friction, Release Cam (Rear)
C75	Fergo	Rapid Traverse Friction, Release Cam Clamp
C76	Feriv	Rapid Traverse Friction, Release Cam (Front)
C77	Ferlu	Turret Slide Stop Block Clamp
C78	Ferme	Turret Slide Stop Block
C79	Feroz	Rapid Traverse Friction Housing
C80	Ferpy	Turret Apron, Feed Friction Ring
C81	Ferug	Turret Apron Lead Screw Nut Pinion
C82	Fesas	Turret Apron, Feed Friction Ring Housing
C83	Fesev	Turret Apron Pilot Wheel Shaft Bevel Gear
C84	Fesgu	Rapid Traverse Friction Lever Link
C85	Fesix	Turret Apron
C86	Fesly	Rapid Traverse Friction, Shifter Plate
C87	Fesmi	Rapid Traverse Friction, Shifter Plate Roller
C88	Fesob	Turret Slide
C89	Fespa	Turret Slide Gib (Rear)
C90	Fesso	Turret
C91	Fetat	Turret Base
C92	Fetcu	Turret Base, Turret Locating Pin
C93	Fetec	Turret Stop Bar Sleeve
C94	Fetgy	Turret Base, Locating Pin Retaining Plate
C95	Fetiz	Turret Base, Locating Pin Spring
C96	Fetla	Turret Stop Bar Spiral Pinion
C97	Fetmo	Turret Locating Pin Pinion Tappet
C98	Fetod	Turret Locating Pin Pinion
C99	Fetpe	Turret Stop Bar Stop Screw Carrier
C100	Fetuj	Turret Stop Bar
C101	Fevav	Turret Spindle

WHEN ORDERING REPAIRS FOLLOW INSTRUCTIONS ON PAGE 214.

MISCELLANEOUS PARTS. UNIT D. SYMBOL B, E, F, H.



WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.


LIST OF MISCELLANEOUS PARTS

Symbol and No.	Code Word	Name
B117		(Order B130)
B118	Fofor	Carriage Stop Bar on Bed
B119	Fofty	Carriage Stop Bar Bracket Plunger Spring
B121	Fogak	Carriage Stop Bar Bracket Plunger Screw
B122	Fogbo	Carriage Stop Bar Bracket Plunger
B123	Fogem	Carriage Stop Bar Bracket
B125	Fogip	Taper Attachment Slide Rod
B130	Fogux	Cross Slide Shield
E32		(Order F32)
E64	Favcu	Lead Screw Feed Worm Gear Oil Pan
E65	Favec	Lead Screw Feed Worm Gear Shield
E66	Favgy	Fine Feed Gear Shield
E68	Favla	Feed Box Back Shield
E70	Favod	Lead Screw
E71	Favpe	Feed Change Spline Shaft
E72	Favuj	Cross Feed Spline Shaft
E75	Febef	Lead Screw Collar
E77	Febjy	Feed Change Spline Shaft Collar
E78	Febok	Cross Feed Spline Shaft Collar
E80	Febup	Cross Feed Spline Shaft Spiral Gear
E83	Fecdu	Feed Change Lever
E84	Feceg	Lead Screw Feed Worm Gear
E85	Fechy	Feed Change Lever, Index Pointer and Screw
E87	Fecol	Cross Feed Spline Shaft Bed Bushing
F1	Ficik	Rapid Traverse Screw
F5	Ficus	Rapid Traverse Screw Bracket Shaft Pinion
F8	Fidda	Rapid Traverse and Pump Drive Pulley
F9	Fidej	Rapid Traverse Screw Bracket Shaft
F10	Fidhe	Rapid Traverse Worm Shaft Sprocket
F12	Fidji	Rapid Traverse Screw Gear
F13	Fidon	Rapid Traverse Worm Gear Housing Cover
F14	Fidro	Rapid Traverse Worm Gear Housing
F17	Fifah	Rapid Traverse Worm Shaft
F18	Fifde	Rapid Traverse Screw Worm Gear
F19	Fifel	Rapid Traverse Worm

Symbol and No.	Code Word	Name
F21	Fifm	Rapid Traverse Worm Gear Housing Screw Bushing
F22	Fifjo	Rapid Traverse Worm Gear Housing Bronze Bushing
F23	Fifop	Rapid Traverse Worm Gear Housing Steel Bushing
F24	Fifru	Rapid Traverse Worm Thrust Washer
F25	Fifuv	Rapid Traverse Housing Felt Washer Retaining Washer
F26	Fifvy	Rapid Traverse Housing Felt Washer
F29	Figel	Rapid Traverse Screw Bracket
F30	Figfo	Taper Attachment Slide Rod Bracket
F32	Figku	Rapid Traverse Screw Gear Shield
H49	Fajde	Friction Gear Shield
H50	Fajek	Back Gear Shield
H51	Fajhi	Tool Shelf
H52	Fajim	Chuck Ring Gear Pinion Shield

WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

TOOL POST CARRIAGE. UNIT E. SYMBOL B.



WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

LIST OF PARTS FOR TOOL POST CARRIAGE

- 1—Tool Post Carriage & Cross Slide Complete
 2—Carriage Apron (Front)
 3—Carriage Apron (Rear)

Symbol and No.	Code Word	Name
B1	Fikno	Carriage Apron Hand Wheel
B2	Fikot	Cross Feed Screw Tail Block
B3	Fikte	Cross Feed Screw Tail Block Dowel Pin
B4	Fikuz	Taper Attachment Swivel Slide Stud
B5	Filam	Cross Feed Screw Tail Block Gib Screws
B6	Filby	Cross Slide Retaining Rod Clamp Screw
B7	Filco	Cross Feed Screw Tail Block Gib
B8	Filep	Cross Slide Retaining Rod
B9	Filfa	Carriage Apron Bonnet
B10	Filis	Carriage Apron Bonnet Shaft Bevel Gear
B11	Filke	Carriage Apron Bonnet Shaft
B12	Filnu	Cross Feed Tumbler Lever
B13	Filov	Cross Feed, Friction Gear Housing Back Plate
B14	Filti	Cross Feed Internal Friction Gear
B15	Fiman	Cross Feed External Friction Gear
B16	Fimba	Cross Feed Housing
B17	Fimer	Carriage Stop Bar, Stop Carrier Retaining Screw
B18	Fimfe	Carriage Stop Bar Stud
B19	Fimit	Carriage Apron Feed, Trip Lever Catch
B20	Fimki	Taper Attachment Swivel Clamp Screws
B21	Fimny	Taper Attachment Swivel Clamp Screw Washers
B22	Fimoc	Carriage Apron Bonnet Retaining Screws
B23	Fimto	Carriage Apron Feed, Friction Dog Handle Catch Pin
B24	Fimud	Cross Feed Tumbler Lever, Pinion Studs
B25	Finap	Cross Feed Friction Gear Shaft
B26	Finbe	Carriage Apron Feed, Friction Dog Handle
B27	Finfi	Cross Feed Friction Star Nut Retaining Collar
B28	Finic	Carriage Apron, Thread Cutting Pull Pin Spring
B29	Finko	Cross Feed Tumbler Lever, Idler Gear Stud Bushing
B30	Finna	Cross Feed Tumbler Lever, Idler Gear Stud Washer
B31	Finox	Carriage Apron, Thread Cutting Pull Pin Lever
B32	Fintu	Carriage Apron, Thread Cutting Pull Pin Bushing
B33	Finuf	Cross Feed, Internal Friction Gear Retaining Collar


Symbol and No.	Code Word	Name
B34	Fipar	Carriage Apron Feed, Friction Dog Plug
B35	Fipet	Carriage Apron Feed Trip Lever
B36	Fipgo	Cross Feed Friction Star Nut
B37	Fipiv	Carriage Apron Feed, Friction Dog
B38	Fiplu	Carriage Apron, Thread Cutting Pull Pin
B39	Fipme	Cross Feed Tumbler Lever, Idler Gear Stud
B40	Fipoz	Cross Feed Friction Star Nut, Split Retaining Washer
B41	Fippy	Cross Feed Tumbler Lever, Small Pinion
B42	Fipug	Cross Feed Tumbler Lever, Large Pinion
B43	Firas	Cross Feed Tumbler Lever, Idler Gear
B44	Firev	Cross Feed Friction Gear Shaft, End Collar
B45	Firgu	Cross Feed Screw Dial
B46	Firix	Cross Feed Screw Pinion Nut
B47	Firly	Cross Feed Screw Nut
B48	Firmi	Carriage Apron Feed, Trip Lever Adjusting Screw
B49	Firob	Cross Feed Tumbler Lever, Pull Pin Spring
B50	Firpa	Cross Feed Tumbler Lever, Pull Pin
B51	Firso	Cross Feed Housing Dowel Pins
B52	Fisat	Cross Feed Friction Star Nut, Split Washer Retaining Screws
B53	Fiscu	Cross Feed Housing Retaining Screws
B54	Fisec	Cross Feed, Friction Gear Housing Back Plate Retaining Screws
B55	Fisgy	Drill Support Chuck Clamping Bolt
B56	Fisiz	Carriage Apron Feed, Trip Lever Stud
B57	Fisla	Cross Feed Tumbler Lever, Pull Pin Knob
B58	Fismo	Drill Support Stud Adjusting Nut
B59	Fisod	Drill Support Stud Washer
B60	Fispe	Cross Feed Screw Hand Wheel
B61	Fisuj	Drill Support Stud
B62	Fitav	Drill Support Chuck
B63	Fitex	Drill Support Chuck Wrench
B64	Fitga	Drill Support
B65	Fitub	Drill Support Clamp Bolt, Stud Nut
B66	Fitle	Drill Support Clamp Bolt Stud Washer
B67	Fitmu	Drill Support Clamp Bolt Stud
B68	Fitof	Drill Support Clamp Bolt
B69	Fitpi	Cross Feed Screw Pinion
B70	Fitsy	Cross Feed Screw
B71	Fituk	Tool Post Elevating Handle

Symbol and No.	Code Word	Name
B72	Fivaw	Carriage left front Gib Adjusting Screw
B73	Fivca	Carriage left front Gib
B74	Fivez	Carriage right front Gib
B75	Fivge	Carriage right front Gib Adjusting Screw
B76	Fivid	Carriage right front Gib Clamping Screw
B77	Fivli	Carriage Front Gib Screws
B78	Fivmy	Tool Post
B79	Fivog	Carriage Apron Retaining Screws
B80	Fivpo	Carriage Gib Adjusting Screws (Rear)
B81	Fivul	Cross Slide Gib Screws
B82	Fobaf	Carriage Gib Clamp Screws (Rear)
B83	Fobdy	Tool Post Carriage
B84	Fobha	Cross Slide Gib
B85	Fobik	Cross Slide (Complete)
B86	Fobje	Carriage Gib (Rear)
B87	Fobom	Taper Attachment Base
B88	Fobri	Taper Attachment Slide
B89	Fobus	Taper Attachment Gib
B90	Fobvo	Taper Attachment Swivel
B91	Focag	Carriage Apron, Cross Feed Shaft Bevel Gear
B92	Focda	Carriage Apron Spline Shaft Bevel Pinion
B93	Focaj	Carriage Apron Spline Shaft Bevel Pinion Retaining Collar
B94	Foche	Carriage Apron, Cross Feed Shaft Pinion
B95	Focil	Carriage Apron, Cross Feed Shaft Bushing
B96	Focji	Carriage Apron, Cross Feed Shaft
B97	Focon	Taper Attachment Swivel Stud
B98	Focro	Carriage Apron Feed, Friction Ring
B99	Focut	Carriage Apron Feed, Friction Ring Housing
B100	Focvu	Carriage Apron
B101	Fodah	Tool Post Top Plate
B102	Fodde	Taper Attachment Base Retaining Screws
B103	Fodek	Tool Post Cone
B104	Fodhi	Taper Attachment Swivel Slide
B105	Fodim	Tool Post Adjusting Screws
B106	Fodjo	Tool Post Tool Set Screws
B107	Fodop	Tool Post Top Plate Retaining Screws
B108	Fodru	Tool Post Washer Screws
B109	Foduv	Taper Attachment Swivel Slide Gib
B110	Fodvy	Tool Post Washer

Symbol and No.	Code Word	Name
B111	Fofaj	Carriage Stop Screws
B112	Fofbi	Carriage Stop Bar Stop Carrier
B113	Fofel	Carriage Stop Bar Spring
B114	Foffo	Carriage Apron Lead Screw Adjusting Nut
B115	Fofin	Carriage Apron Lead Screw Nut Pinion
B116	Fofku	Carriage Apron Lead Screw Nut
B117	Fofne	Carriage Stop Bar

WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

PUMP. UNIT F. SYMBOL X.



WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

LIST OF PARTS FOR PUMP


1—Piping and Swing Joints

2—Complete Pump with Check Valve

Symbol and No.	Code Word	Name
X1	Folan	Rear Oil Pan Splash Guard, Front
X2	Folba	Front Oil Pan Splash Shield
X3	Foler	Chuck Splash Guard, Rear
X4	Folfe	Chuck Splash Guard, Front
X5	Folit	Chip Pocket Shield
X6	Folki	Chuck Splash Guard, Top
X7	Folny	Rear Oil Pan Splash Guard, Rear
X8	Foloc	Rear Oil Pan
X9	Folto	Front Oil Pan
X10	Folud	Swing Joint
X11	Fomap	Pump Body Screws
X12	Fombe	Relief Valve
X13	Fomes	Button Head Screws
X14	Fomfi	Pump Body Cap
X15	Fomic	Pump Body
X16	Fomko	Pump Body Cap Stuffing Box
X17	Fomna	Pump Body Cap Screws
X18	Fomox	Pump Body Gear Shaft Pulley
X19	Fomtu	Pump Body Gear
X20	Fomuf	Pump Body Gear Shaft
X21	Fonar	Globe Valve
X22	Fonet	Check Valve
X23	Foniv	Pipe Bracket
X24	Fonlu	Pipe Bracket Screws
X25	Fonme	Oil Distributer
X26	Fonoz	Chuck Splash Guard Guide Screws
X27	Fonpy	Chuck Splash Guard Guides, Top
X28	Fonug	Chuck Splash Guard Guide Screws
X29	Fopas	Chuck Splash Guard Guides, Bottom
X30	Fopev	Oil Pan Strainer
X34	Fopmi	Oil Tank
X35	Fopob	Pump Body Gear

WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

COUNTERSHAFT. 3 STEP CONE. UNIT G. SYMBOL J.



WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.


LIST OF PARTS FOR COUNTERSHAFT. 3 STEP CONE.

1. Complete Turret Lathe Countershaft

Symbol and No.	Code Word	Name
J1	Fossy	Friction Pulleys
J2	Fosuk	Friction Pulley Dog Plate Grease Cups
J3	Fotaw	Hanger Box Drip Pans
J4	Fotca	Hangers
J5	Fotez	Hanger Boxes and Adjusting Screws
J6	Fotge	Friction Pulley Dog Plate Collars
J7	Fotid	Shifter Rods
J8	Fotli	Shifter Rod Guides
J9	Fotmy	Friction Ring Expanding Pins
J11	Fotpo	Friction Pulley Friction Rings
J12	Fotul	Friction Pulley Dog Plates
J13	Fovax	Friction Ring Expanding Pin Dogs
J15	Fovgi	Friction Ring Expanding Pin Dog Adjusting Screws
J16	Fovif	Double Cam
J17	Fovlo	Cam Shifter Arms
J20	Fovpu	Countershaft End Thrust Collars
J21	Fovse	Hanger Box Oil Wicks
J24	Fubda	Shifter Rod Dogs
J27	Fubil	Friction Pulley Dog Plate Keys
J30	Fubro	Countershaft
J37	Fucim	Cone Pulley Key
J42	Fucvy	Single Cam
J44	Fudbi	Cone Pulley
J45	Fudel	Hanger Box Oil Chamber Covers
J46	Fudfo	Hanger Pins

WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

COUNTERSHAFT—2 STEP CONE—UNIT G. SYMBOL J.




WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

LIST OF PARTS FOR COUNTERSHAFT. 2 STEP CONE

Symbol and No.	Code Word	Name
J51	Fumar	Friction Pulley
J52	Fumet	Friction Pulley Dog Plate
J53	Fumgo	Friction Pulley Dog Plate Collar
J54	Fumiv	Cam Shifter Arm
J55	Fumlu	Single Cam
J56	Fumme	Double Cam
J57	Fumoz	Friction Pulley Friction Rings
J58	Fumpy	Friction Ring Expanding Pin
J59	Fumug	Friction Ring Expanding Pin Dog
J60	Funas	Friction Ring Expanding Pin Dog Adjusting Screw
J61	Funev	Shifter Rod Guide Arm
J62	Fungu	Shifter Rod Guide Arm Block
J63	Funix	Shifter Rod Guide Arm Clamp Screw
J64	Funly	Hanger Box Adjusting Screw, Side
J65	Funmi	Hanger Box Adjusting Screw, Top and Bottom
J66	Funob	Countershaft End Thrust Collar
J67	Funpa	Grease Cup
J68	Funso	Hanger Box, Upper Half
J69	Fupat	Hanger Box, Lower Half
J70	Fupcu	Hanger Box Oil Pan
J71	Fupec	Hanger, Pressed Steel
J72	Fupgy	Hanger Box Oil Rings
J73	Fupiz	Loose Pulley Shifter Rod Dog
J74	Fupla	Friction Pulley Shifter Rod Dog
J75	Fupmo	Shifter Rod Collar
J76	Fupod	Friction Pulley Shifter Rod
J77	Fuppe	Loose Pulley Shifter Rod
J78	Pupuj	Shifter Rod Guide, Cone Pulley End
J79	Furav	Shifter Rod Guide, Center Hanger
J80	Furex	Shifter Rod Guide, Friction Pulley End
J81	Furga	Loose Pulley Shifter Rod Fingers
J82	Furib	Countershaft

WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

CHUCK. UNIT H. SYMBOL A.



WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.

LIST OF PARTS FOR CHUCK

1. Complete 3 jawed scroll chuck.

Symbol and No.	Code Word	Name
A1	Fugir	Chuck Wrench
A2	Fugka	Chuck Scroll Pinion Nut Lock Screw Brass Plugs
A3	Fugno	Chuck Scroll Pinion Nut Lock Screws
A4	Fugot	Oil Hole Screw Plug
A5	Fugte	Felt Block, Flat Head Screws
A6	Fuguz	Felt Blocks
A7	Fujam	Chuck Scroll Pinion Retaining Nuts
A8	Fujby	Chuck Scroll Pinions
A9	Fujco	Chuck Scroll
A10	Fujep	Chuck Body Back Plate
A11	Fujfa	Chuck Body Spindle Screws
A12	Fujis	Chuck Body
A13	Fujke	Chuck Jaw, Screws
A14	Fujnu	Chuck Body Back Plate Screws
A15	Fujov	Chuck Jaw, Base Tops (Hard)
A16	Fujti	Chuck Jaw Base Top Cross Tongues
A17	Fukan	Chuck Jaw Base Top Cross Tongue Screws
A18	Fukba	Chuck Jaw Bases, Dust Proof
A19	Fuker	Chuck Jaw, Base Tops (Soft)
A20	Fukfe	Screw Driver
A21	Fukit	Chuck, False Jaw Screw
A22	Fukki	Chuck, False Jaw

Pieces A10 and A12 cannot be furnished separately.

WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.


PIECE NUMBERS AND NAMES FOR ORIGINAL POWER CROSS
FEED

See Drawing 178Z page 242

WHEN ORDERING PARTS FROM THIS LIST ALWAYS MENTION 178Z

14	B—100	Carriage Apron
15	B—16	Cross Feed Housing
69		Spring
95		Carriage Shield Gear
96		Carriage Shield Gear
97		Carriage Shield Gear
98		Hand Wheel Friction
99		Bonnet for Power Cross Feed
100	B—36	Cross Feed Friction Star Nut
103	B—115	Carriage Apron Lead Screw Nut Pinion
105	B—116	Carriage Apron Lead Screw Nut
109	B—45	Cross Feed Screw Dial
111		Carriage Feed Friction
113	B—83	Tool Post Carriage
116		Carriage Friction Feed Lever
126	B—60	Cross Feed Screw Hand Wheel
127	B—1	Carriage Apron Hand Wheel
133	B—85	Cross Slide
139	B—69	Cross Feed Screw Pinion
140	B—46	Cross Feed Screw Pinion Nut
209	B—112	Carriage Stop Bar Stop Carrier
274		Apron Bracket
275		Friction Clutch
277		Hatchet Lever
278		Collar
279		Connecting Bracket
397	B—103	Tool Post Cone
408	B—47	Cross Feed Screw Nut
589	B—117	Carriage Stop Bar
591	B—110	Tool Post Washer
597	B—10	Carriage Apron Bonnet Shaft Bevel Gear
607	B—71	Tool Post Elevating Handle
611		Pin for Friction on Power Cross Feed

CONSTRUCTION OF ORIGINAL POWER CROSS FEED
GISHOLT MACHINE CO., MADISON, WIS.




613	E—70	Lead Screw
653	B—11	Carriage Apron Bonnet Shaft
648		Carriage Feed Friction Lever Catch Pin
654		Clamp Rod on Power Feed Carriage
708		Plunger
755		Carriage Hand Wheel Shaft Collar
816	B—70	Cross Feed Screw
832		Drill Support Stud
916		Shoulder Screw
975		Friction Bracket Shaft
1117	B—35	Carriage Apron Feed Trip Lever
1263		Cross Slide Block Nut
0456	B—78	Tool Post

Numbers refer to figure 178Z, page 242.

“B” numbers refer to Tool Post Carriage section, page 229.

“E” numbers refer to Miscellaneous Parts section, page 226.

WHEN ORDERING REPAIRS, FOLLOW INSTRUCTIONS ON PAGE 214.



MADISON AND THE FOUR LAKE REGION

COME TO MADISON

"What is there left in Madison for a community organization to do except to say to the rest of the world, 'Come' ".—HOWARD STRONG.

The Gisholt plants are always open to visitors.

A cordial invitation is extended to all to visit us—see the modern buildings and equipment, as well as to become acquainted with the organization which has made Gisholt Service a by-word in metal working industries.

The home plant and office is at Madison, Wisconsin, the "city of the four lakes," situated on an isthmus between two beautiful lakes—Mendota and Monona. In describing the scenery on Monona, Rev. C. H. Richards says, "The far-famed bay of Naples is not more lovely than Monona."

The scenery in and about Madison holds many surprises for a stranger and we can best describe it in the words of U. S. Senator Moses E. Clapp when he said, "It is hard to speak of the beauties of Madison without being charged with exaggeration."

Madison is reached by three railroads, with 102 passenger trains daily. It is only a four hours ride over either of two direct lines from Chicago, where connections are made from all points East, West, South and Southwest. There is one line running directly West, from Madison, another directly South and two lines to St. Paul and Minneapolis, connecting with all points for the great Northwest.

MADISON IN A NUTSHELL

Population—in 1916, 32,136; including suburbs and students, over 40,000;
7th city in state.

Area—9 square miles.

Water front—8 miles.

Boating—100 miles by lake and river.

Water—11 artesian wells.

Altitude—974 feet above the sea.

Parks—282 acres.

Sewage disposal—Bacteriological process.

Streets—Over 75 miles improved.

Capitol—\$7,000,000 statehouse.

Residences—7,000.

Bank deposits—\$13,000,000.00.

Electric street railway—15 miles.

Telephones—9,700.

Passenger trains—Three roads, 102 trains daily.

Hospitals—General, St. Mary's, Stoeber, Contagious and Madison Sanitarium.

Churches—43.

Educational—Site of University, enrollment over 7,600; four high schools;
thirteen graded schools; five parochial schools; two business colleges; two
academies and two schools of music.

Distances—To Milwaukee, 82 miles; Chicago, 130; St. Paul, 269.

Newspapers—Three Dailies, 9 Weeklies.

City library—144,762 volumes.

INDEX

	Page
Adapters, Turret	136
Adjustment, General	13
Adjustment, Countershaft	17
Adjustment, Feed Box	13
Adjustment, Headstock	13
Adjustment, Power Traverse	15
Adjustment, Taper Attachment	115
Adjustment, Tool Post Carriage	17
Adjustment, Turret	15
Adjustment of Universal Tool Grinder Spindle	92
Arbors, Boring Bar Cutter Grinding	135
Arbors, Facing Head Supporting	170
Arbors, Shell Reamer	155
Arbors, Straight Shank Reamer	156
Arms, Facing Head	166
Arrangements of Facing Head Cutters	164
Bar Tools	29
Boring Bars, Special	138
Boring Bars, Standard	124
Boring Bar, List of Gisholt Standard	132
Boring Bar Cutters, Expansion	133
Boring Bar Cutters, Special	142
Boring Bar Cutters, Solid	134
Boring Bar Cutter Heads	144
Boring and Turning Tools	27
Bushings, Self-Lubricating Chuck	85
Care and Operation	12
Centers	80
Centering Spider, External	53
Centering Spider, Internal	54
Chart, Standard Thread Cutting	176
Chart, Thread Cutting Reference	179-180
Chart, Tool Grinding	99
Chucking	33
Chuck Bushings	85
Chuck, Drill Support	36
Chuck, Four Jaw Independent	35

	Page
Chuck Jacks -----	40
Chuck Jaws, Auxiliary -----	57
Chuck Jaws, Boring and Fitting -----	37
Chuck Jaws, Face Plate -----	56
Chuck Jaws, Special Shape -----	42
Chuck, Three Jaw Universal Scroll -----	33
Chuck, Ordering Parts for -----	239
Countershaft, Adjustment of -----	17
Countershaft, Ordering Parts for -----	235-237
Cross Slide, Tool Post -----	87
Cutter Heads, Boring Bar -----	144
Cutters, Arrangement of Facing Head -----	164
Cutters, Boring Bar Expansion -----	133
Cutters, Boring Bar Solid -----	134
Cutters, Boring Bar Special -----	142
Cutters, Grinding of Facing Head -----	165
Cutters, Special Facing Head -----	168
Cutting Speeds and Feeds, Meaning of the terms -----	23
Dies, Taps and -----	181
Die Holders -----	185
Drills, Grinding of -----	123
Drills, Special -----	118
Drill Support -----	117
Drill Support Chuck -----	36
Drill Support, Special -----	118
Drill Support, Use of -----	122
Emery Wheels, Gisholt Universal Tool Grinder -----	100
Estimates, Time and Tool -----	25
Extensions, Turret -----	136
Facing Heads -----	162
Facing Heads and Accessories -----	30
Facing Head Arbors -----	170
Facing Head Arms, Special -----	166
Facing Head, Arrangement of Cutters in -----	164
Facing Head Cutters, Grinding of -----	165
Facing Head Cutters, Special -----	168
Facing Heads, Taper Boring -----	172-174
Face Plate Jaws -----	56
Feed Box, Adjustment of Main -----	13
Feed Box, Ordering Parts for Main -----	218

	Page
Feed Changes and Thread Cutting	176
Feeds, Speeds and Grinding of Tool Post Tools.....	88
Fixtures, Chucking	58
Forging, Tool Post Tools	102
Four Jaw Independent Chuck	35
Gisholt Standard Turret Lathe, Care and Operation of	12
Gisholt Standard Turret Lathe, Operating Levers	10
Gisholt Standard Turret Lathe, Range of	209
Gisholt Standard Turret Lathe, Uses and Advantages	11
Grinder, Gisholt Universal Tool	91
Grinding Boring Bar Cutters, Arbor for.....	135
Grinding Chart, Tool	99
Grinding, Drill	123
Grinding Mandrels, Reamer	152.
Grinding by Gisholt Method, Tool	94
Grinding, Tool Post Tool.....	88
Heads, Boring Bar Cutter	144
Heads, Facing	162
Headstock Adjustment	13
Headstock, Ordering Parts for	215
Helpful Suggestions	210
Holders, Die	185
Holders, Special Tool Post Tool	106
Holders, Standard Tool Post Tool	101
Holders, Tap	183
Installation of Gisholt Standard Turret Lathe.....	12
Instruction and Time Study Sheets, Layout.....	190
Instructions for Ordering Parts.....	211
Jacks, Chuck	40
Jaws, Auxiliary	57
Jaws, Boring and Fitting	37
Jaws, Face Plate	56
Jaws, Special Shape	42
Layout Instruction and Time Study Sheets.....	190
Machining of Heavy Pieces	186
Main Feed Box, Adjustment of	13
Main Feed Box, Ordering Parts for	218
Mandrels, Reamer Grinding	152
Miscellaneous Parts, Ordering of	225
Oiling	12

	Page
Operating -----	18
Ordering Parts, Instructions for -----	214
Power Cross Feed—Old Style Lathe, Ordering Parts for -----	241
Power Traverse Adjustment -----	15
Pump, Ordering Parts for -----	233
Reamers -----	148
Reamer Arbors, Shell -----	155
Reamer Arbors, Straight Shank -----	156
Reamers, Special -----	158
Reamers, Special Spiral Fluted Large -----	157
Reamers, Spiral Fluted Shell -----	153
Reamers, Spiral Fluted Straight Shank -----	154
Rests, Steady -----	83
Rest, Wing -----	87
Self-lubricating Chuck Bushing -----	85
Setting up Tools -----	31
Speeds and Feeds, Meaning of the Terms Cutting -----	23
Spiders, External Centering -----	53
Spiders, Internal Centering -----	54
Spiders, Supporting -----	55
Standard Tool Equipment -----	25
Steady Rest -----	83
Stops, Tool Post Carriage and Turret -----	19
Storage, Tool -----	208
Supports, Tool Post Tool -----	105
Tap, Special -----	183
Taps and Dies -----	181
Tap Holders -----	183
Taper Attachment, Adjustment and Connection -----	115
Taper Attachment, Use of -----	116
Taper Boring and Facing Heads -----	172-174
Thread Cutting and Feed Changes -----	176
Threading Cutting Reference Chart -----	179-180
Three Jaw Universal Geared Scroll Chuck -----	33
Time Study Sheets, Layout Instruction and -----	190
Time and Tool Estimates -----	25
Tooling, Gisholt Turret Lathe -----	25
Tools, Tool Post -----	88 & 104
Tools, Setting up -----	31
Tool Grinding Chart -----	99

	Page
Tool Grinding by Gisholt Method -----	94
Tool Holders for Tool Post, Special -----	106
Tool Holders for Tool Post, Standard -----	101
Tool Post Carriage Adjustment -----	17
Tool Post Carriage, Ordering Parts for -----	228
Tool Post and Tool Post Tools -----	87
Turret Adapters -----	136
Turret Adjustment -----	15
Turret Extensions -----	136
Turret Slide, Ordering Parts for -----	221
Turret Tools -----	123
Universal Geared Scroll Chuck, Three Jaw -----	33
Universal Tool Grinder, Gisholt -----	91
Uses and Advantages -----	11
Universal Tool Grinder, Spindle Adjustment -----	92
Wing Rest -----	87

Index by Chapters

	Page
CARE AND OPERATION -----	12
Adjustment -----	13
Countershaft Adjustment -----	17
Feed Box Adjustment -----	13
Headstock Adjustment -----	13
Installation -----	12
Oiling -----	12
Operating -----	18
Power Traverse Adjustment -----	15
Stops, Tool Post Carriage and Turret -----	19
Tool Post Carriage Adjustment -----	17
Turret Adjustment -----	15
CHUCKING -----	33
Bushings, Self-lubricating Chuck -----	85
Centers -----	80
Chuck Jacks -----	40
Drill Support Chuck -----	36
Fixtures -----	58
Four Jaw, Independent Chuck -----	35
Jaws, Auxiliary -----	57
Jaws, Boring and Fitting -----	37
Jaws, Face plate -----	56
Jaws, Special Shape -----	42
Spiders, Centering, External -----	53
Spiders, Centering, Internal -----	54
Spiders, Supporting -----	55
Steady Rest -----	83
Three Jaw Universal Geared Scroll Chuck -----	33
CUTTING SPEEDS AND FEEDS, MEANING OF THE TERMS -----	23
DRILL SUPPORT -----	117
Special -----	118
Standard -----	117
Use -----	122
FACING HEADS -----	162
Arbors -----	170
Arms, Special -----	166
Arrangement of cutters -----	164

Index	Page 253
FACING HEADS—continued	Page
Cutters, Special -----	168
Grinding of Cutters -----	165
Taper Boring -----	172 & 174
FEED CHANGES AND THREAD CUTTING -----	176
GISHOLT TURRET LATHE, RANGE OF -----	209
GISHOLT UNIVERSAL TOOL GRINDER -----	91
Dimensions -----	103
Emery Wheel -----	100
Forging -----	102
Spindle Adjustment -----	92
Tool Grinding Chart -----	99
Tool Grinding by Gisholt Method -----	94
Tool Holders for Tool Post—Standard -----	101
Tool Holders for Tool Post—Special -----	106
HELPFUL SUGGESTIONS -----	210
LAYOUT, INSTRUCTION AND TIME STUDY SHEET -----	190
MACHINING OF HEAVY PIECES -----	186
ORDERING PARTS -----	211
Chuck -----	239
Countershaft—2 step cone -----	237
Countershaft—3 step cone -----	235
Headstock -----	215
Instructions -----	214
Main Feed Box -----	218
Miscellaneous Parts -----	225
Power Cross Feed—Old Style Lathe -----	241
Pump -----	233
Tool Post Carriage -----	228
Turret Slide -----	221
REAMERS -----	148
Arbors—Shell Reamer -----	155
Arbors—Straight Shank Reamer -----	156
Grinder Mandrels -----	152
Shell—Spiral Fluted -----	153
Shell—Special Spiral Fluted -----	157
Special Reamers -----	158
Straight Shank Spiral Fluted -----	154
TAPER ATTACHMENT -----	115
Adjustment and Connection -----	115
Use -----	116

	Page
THREAD CUTTING AND FEED CHANGES	176
Chart, Reference	179 & 180
Chart, Standard	176
Die Holders	185
Taps and Dies	181
Taps, Holders	183
Taps, Special	183
TOOLING	25
Bar Tools	29
Boring and Turning Tools	27
Facing Heads and Accessories	30
Setting up Tools	31
Standard Tool Equipment	25
Time and Tool Estimates	25
TOOL POST AND TOOL POST TOOLS	87
Cross Slide Tool Post	87
Feeds, Speeds and Grinding	88
Supports for Tool Post Tools	105
Tool Post Tools	88 & 104
Wing Rest	87
TOOL STORAGE	208
TURRET LATHE	10
Operating Levers	10
Uses and Advantages	11
TURRET TOOLS	123
Adapters, Turret	136
Arbors for Grinding Boring Bar Cutters	135
Boring Bars	124
Boring Bars—Special	138
Cutter Heads, Boring Bar	144
Cutters, Boring Bar Expansion	133
Cutters, Boring Bar Solid	134
Cutters, Boring Bar Special	142
Drills—Grinding	123
Drills—Special	118
Extensions, Turret	136

**Compiled by
Service Department**

**Issued by
Publicity Department**

**Gisholt Machine Company
Madison, Wis., U. S. A.**

**Democrat Printing Co.,
Madison, Wis.**

621.94 R701 c.1

Gisholt turret lathe guide for care



087 215 767

UNIVERSITY OF CHICAGO