


OPERATOR'S MANUAL



MODELS
W7, W-7S AND W-7PF
W & H MOLDER-PLANER

MODEL W7S

**Your Savings Pile Up
As Your Shavings Pile Up**

Manufactured and Sold by

Williams & Hussey Machine Corp.

MILFORD, NEW HAMPSHIRE 03055


•

TEL. 603-673-3446

W & H Molder-Planer—Models W-7, W7PF and W7S Super

MOUNTING DIAGRAM AND INSTRUCTIONS

OVERHEAD PERSPECTIVE



24" x 24" TABLE (OR LARGER)

To obtain proper cutting speed, 3450 r.p.m. motors are recommended. Suggested *minimum* horsepower requirements.

Model W-7 — 1/2 h.p.

Model W-7PF — 3/4 h.p.

Model W-7S — 1 h.p.

Best results will be obtained by using "W & H" Motor Mounts.

NOTE: Motor *must* be mounted horizontally to maintain proper belt ten-

sion when cutting head is raised or lowered. A rocker type motor mount *must* be used.


Mount your planer on a sturdy bench or stand. Excessive vibration will result in poor quality work.

A 10" pulley is required with a 1750 r.p.m. motor. In this case, elevate the W & H Motor Mount by placing it on a 3" x 12" block 1" thick screwed or bolted to bench.

HOW TO SET GUIDES OR FENCE

For planing, clamp one guide strip to inside edge of table. For moldings, be sure to size stock properly as to width of molding desired. Place stock on table directly be-

neath molding knives. Now clamp guide strips on either side of stock making sure that there is no binding. Use C clamps.



LUBRICATING INSTRUCTIONS

Model W-7

No lubrication required except occasional oiling of #54-11 cutting head elevating screw.

Model W-7PF and Model W-7S Super

Before Operating Your Planer fill gear box approximately *half full* of W & H "No-Drip" oil supplied with your machine. Check each time before starting your Molder-Planer, and maintain proper oil level. NOTE: Gear boxes are shipped dry and **MUST** be filled **BEFORE**

being put into operation, or serious damage may result. While filling or adding oil, rotate cutter head back and forth to eliminate air bubbles and ensure entry of sufficient lubricant.

Oil cutter head elevating screw when needed.

CARE OF MACHINE AND KNIVES

For easier processing of stock, we recommend waxing the table from time to time, using any good grade of paste wax or ordinary paraffin.

Keep knives and all working parts free of pitch. (Kerosene is a good cleaning agent.)

To keep knives in good condition, stone frequently **ON FLAT REVERSE SIDE**. Do **NOT** attempt to sharpen on bevel edge except when necessary to remove nicks. All grinding should be done on flat reverse side!

ACCESSORIES

There is nothing better for handling long stock to and from your machine than our telescopic roller stands. See your dealer about them. You may use them to advantage with your bench saw, jointer or any power tool where handling long stock is a problem. We recommend our bench rollers when machine is mounted on long bench. V-type rail easily made by you permits sliding rollers to any desired position.

ORDERING KNIVES

Standard knives, as per patterns illustrated on our price list may be obtained from dealers stock. Be sure to order by pattern number. For moldings of special design, submit line sketch or sample to your dealer. Be sure line sketch is true as to pattern or molding detail. If molding requires depth cut greater than $\frac{3}{4}$ ", submit sample or line sketch direct to Williams & Hussey Machine Corporation, Milford, New Hampshire for consideration.

OPERATING INSTRUCTIONS

For access to cutting head, raise chip deflector with left hand and withdraw axis pin with right hand.

Remove chip deflector, being careful to avoid striking knives.

ON MODEL W-7

Chip deflector should ride on stock, acting as an anti-kick-back mechanism and hold-down.


ON MODELS W-7PF AND W-7S

Adjust screw and lock nut on chip deflector so that it will *not* be in actual contact with stock being processed as this puts an unnecessary load on the feed mechanism.

EXCEPTION

When processing pieces 12" long or less, or when running stock $\frac{1}{4}$ " thick or less, adjust screw and lock nut so that chip deflector *will* ride on the stock.

Be sure to loosen head locking screw (knob) #54-21 before raising or lowering head. Tighten before starting machine.



OPERATING INSTRUCTIONS (Cont.)

Molding knives are made to fit against shoulder of cutting head, as illustrated. Cutting edge of planing knives should be maintained $\frac{1}{2}$ " off head at all times.

After putting bolts in place, slide knives to right as far as possible to ensure alignment.

You may process material requiring molding cuts, such as knotty pine panelling, cabinet doors, etc., regardless of width, with Models W-7 and W-7PF. However, the Model W-7S is not designed to plane the stock more than 7" wide.

When using machine for planing edges or jointing, or for processing stock which must be run edgewise, prepare guides approximately two-thirds as high as stock. This will maintain stock perfectly upright and assure precision work.

Before starting machine be sure infeed and outfeed rolls are not riding on table.

IMPORTANT: Do not have more spring tension on infeed and outfeed rolls than is necessary to provide traction for processing stock. To increase tension, turn knurled screws to right; to decrease turn left. The pins which ride up and down inside knurled screws should not be more than $\frac{1}{8}$ " above top of screws. *Too much tension on feed rolls* will cause gear reduction unit to run hot and will cause unnecessary wear of working parts. Variable feed speeds may be obtained

by increasing or decreasing motor pulley size.


MOLDING BOOK

Over eight hundred standard molding patterns are illustrated in our molding book. They may be obtained from your dealer or by writing Williams & Hussey Machine Corporation, Milford, New Hampshire. All patterns are full size illustrations which permit you to definitely determine your need.

GENERAL INFORMATION

Although your W & H Molder-Planer is ruggedly constructed to give you a lifetime of satisfactory use, it is entirely dependent upon your taking good care of it. When you change from one operation to another, check your machine carefully. Make certain that you have followed the few details mentioned heretofore. Lumber may be sawed unevenly as to width or thickness. Some rough-sawn lumber may vary in thickness as much as $\frac{1}{2}$ " from end to end. Don't try to even it up in one pass. Stock for moldings should be properly sized to width before processing. Don't try to force uneven stock between guides. Check stock for loose knots, scab or splinters which might catch on edge of table. Do not attempt to reclaim varnished or painted lumber. It will ruin your knives. Be sure lumber is free of foreign substance, such as nails, grit, etc.

FORM #101



KEY TO DIAGRAM — FORM #101

Note: When ordering, please include Model and Serial Number of Machine to be repaired.

Part No.	No. Req.	Nomenclature			
P-100	1	Swing arm, infeed	54-26	2	Guide, roll pressure adjusting
P-101	1	Gear box	54-15A	2	Screw, swing arm axis
P-102	1	Chain guard	54-16	1	Stop pin, swing arm
P-103	1	Primary shaft	P-140	3	Cap screw, chain guard attaching $\frac{1}{4}$ —20x3"
P-104	1	Primary worm	P-139	1	Cap screw, chain guard attaching $\frac{1}{4}$ —20x1½"
P-105	1	Primary worm gear	P-141	5	Cap screw, Hex socket (gear box)
P-106	1	Secondary shaft	P-138	2	Dowel pins 3/16" x 1¼"
P-107	1	Secondary worm	54-1	1	Base
P-108	1	Secondary worm gear	54-2	1	Head
P-109	1	Sprocket drive shaft	54-3	1	Deflector, chip
P-110	1	Drive sprocket	54-4	1	Swing arm, outfeed
P-111	1	Sprocket, feed roll (driven)	54-5	1	Bar, top brace, tube
P-112	1	Drive chain	54-6	1	Crank arm
P-113	2	Oil retention plug	54-7	1	Collar, elevating screw
P-114	3	Oilite bushing. (worm and gear shafts)	54-8A	1	Tube A, plain
P-115	1	Bearing support plug	54-8B	1	Tube B, slotted
P-116	1	Oil cup	54-9	1	Screw, crank knob
P-117	1	Fiber drive coupling	54-10	1	Arbor, blade
P-118	1	Tru-arc bearing retaining ring	54-11	1	Screw, elevating
P-120	1	Sprocket shaft spacer $\frac{3}{8}$ x 5/16 x .550	54-12	1	Outfeed roll, steel
P-121	1	Primary shaft spacer $\frac{3}{8}$ x $\frac{1}{4}$ x .057	54-13	2	Journal, outfeed roll
P-122	1	Journal, infeed roll	54-14	1	Axis pin, chip deflector
P-123A	1	Feed roll, rubber	54-15A	2	Screw, swing arm axis
P-124	1	Sprocket journal, infeed roll	54-16	1	Stop pin, swing arm
P-124A	1	Complete rubber feed roll assembly	54-19	1	Knob, crank arm
P-125	2	Ball bearing #1601 (primary and secondary)	54-20	2	Ball bearing, arbor
P-126	1	Ball bearing #1602 (primary shaft only)	54-21	1	Knob, head locking
P-127	2	Gear and sprocket shaft spacer	54-22	1	Screw, head locking
P-127A	1	Gear shaft spacer	54-23	8	Cap screw, blade attaching
P-128	1	Gasket, gear box	54-24	2	Spring, roll pressure adjusting
P-129	1	Screw, chip deflector adjustment	54-25	2	Screw, roll pressure adjusting
P-130	1	Check-nut, chip deflector adjustment	54-26	2	Guide, roll pressure adjusting
P-133	1	Name plate	54-28	1	Sheave (pulley) 2½"
P-137	2	Oilite bushings, swing arm	54-32	1	Scale
54-24	2	Spring, roll pressure adjusting	54-36	1	Catch, chip deflector axis pin
54-25	2	Screw, roll pressure adjusting	54-41	2	Blade, high speed steel planer
			54-50	1	Name plate

KEY TO DIAGRAM — FORM #102

Note: When ordering, please include Model and Serial Number of Machine to be repaired.



Part No.	No. Req.	Nomenclature			
54-1	1	Base	P-107	1	Secondary worm
254-2	1	Head	P-108	1	Secondary worm gear
54-3	1	Deflector, chip	P-209	1	Drive shaft, sprocket
254-4	1	Swing arm, outfeed	P-110	1	Drive sprocket, infeed
54-5	1	Bar, top brace, tube	P-210	1	Drive sprocket, outfeed (narrow hub)
54-6	1	Crank arm	P-211	2	Sprocket, feed roll (driven)
54-7	1	Collar, elevating screw	P-112	1	Chain, infeed (short)
54-8A	1	Tube A, plain	P-113	2	Oil retention plug
54-8B	1	Tube B, slotted	P-114	3	Oilite bushing (worm and gear shafts)
54-9	1	Screw, crank knob	P-115	1	Bearing support plug
54-10	1	Arbor, blade	P-116	1	Oil cup
54-11	1	Screw elevating	P-117	1	Fiber drive coupling
54-14	1	Axis pin, chip deflector	P-118	1	Tru-arc bearing retainer ring
54-15A	4	Screw, swing arm axis	P-120	1	Sprocket shaft spacer $\frac{3}{8}$ x 5/16 x .550
54-16	2	Stop pin, swing arm	P-121	1	Primary shaft spacer $\frac{3}{8}$ x $\frac{1}{4}$ x .057
54-19	1	Knob, crank arm	P-122	2	Journal, feed roll (short)
54-20	2	Ball bearing, arbor	P-123A	2	Feed roll, rubber
54-21	1	Knob, head locking screw	P-124	1	Sprocket journal, infeed roll
54-22	1	Screw, head locking	P-224	1	Sprocket journal, outfeed roll
54-23	8	Cap screw, blade attaching	P-124A	1	Complete rubber infeed roll assembly
54-24	4	Spring, roll pressure adjusting	P-124B	1	Complete rubber outfeed roll assembly
54-25	4	Screw, roll pressure adjusting	P-125	2	Ball bearing #1601 (primary and second)
54-26	4	Guide, roll pressure adjusting	P-126	1	Ball bearing #1602 (primary shaft only)
54-28	1	Sheave (pulley) 2½"	P-127	2	Spacer, gear and sprocket shaft
54-32	1	Scale	P-127A	1	Spacer gear shaft
54-36	1	Catch, chip deflector axis pin	P-128	1	Gasket, gear box
54-41	2	Blade, high speed steel planer	P-129	1	Screw, chip deflector adjustment
54-50	1	Name plate	P-130	1	Check nut, chip deflector adjustment
P-100	1	Swing arm, infeed	P-137	4	Bushing, oilite, swing arm
P-101	1	Gear box	P-212	1	Chain outfeed (long)
P-202	1	Chain guard	P-213	1	Bushing, nylon
P-203	1	Primary shaft	P-214	1	Collar, nylon
P-104	1	Primary worm	P-240	3	Cap screw, chain guard attaching $\frac{1}{4}$ —20x2"
P-105	1	Primary worm gear	P-239	1	Cap screw, chain guard attaching $\frac{1}{4}$ —20x3½"
P-106	1	Secondary shaft	P-241	5	Cap screw, Hex socket (gear box)
			P-238	2	Dowel pins 3/16" x 2"

PERSPECTIVE VIEW W & H MOLDER-PLANER PARTS

MODEL W-7S SUPER

DOUBLE ROLL POWER FEED

FORM #102



obsolete



OPERATOR'S MANUAL

& PARTS LIST

INSTRUCTIONS FOR ATTACHING W-7 PFA POWER FEED ATTACHMENT TO MODEL W-7 W & H MOLDER-PLANER

1. Insert P-100 swing arm assembly in #54-2 head (held in place by 2 — #54-15 A screws.
2. Assemble P-112 chain on sprockets #P-111 and #P-210 *with swing arm in lowered position.*
3. Locate gear box on head by dowels, and insert screws supplied.
4. Raise swing arm assembly and insert #54-16 stop pin.
5. Assemble #P-129 and P-130 adjusting screw and lock nut in head casting.
6. Assemble and insert #P-24, 25, and 26 tension screw and spring assembly.
7. **FILL GEAR BOX WITH NO-DRIP OIL TO PROPER LEVEL BEFORE OPERATING MACHINE!**

**W & H MOLDER-PLANERS
MODELS W-7, W-7PF & W-7S**

are covered by U.S. patents

2,780,250

2,780,251

2,780,254

2,780,255

Printed in U.S.A. 8/74/ WP