








WALKER-TURNER COMPANY Inc.
Flexible Shaft Machines.

PARTS LISTING
For S.F.H and S.F.L Series.



"ADD 20% TO PRICES SHOWN"

PARTS LISTING
For SFH and SFL Series

Key No.	Part No.	Description	Price	Key No.	Part No.	Description	Price
	SF10-X	BASE ASSEMBLY (SFH)	25.00		SF62	DRIVING HEAD	17.50
		consists of:				consists of:	
1	SF10	Base Casting only	16.00	1	SF58	Spindle	7.00
2	SF44	Column	3.75	2	SF59	Spindle Collar	
3	SF18	Column Cap	2.50	3	SF22	Housing Cover	2.00
4	T-63	Thrust Bearing	.45	4	SF59	Fibre Washer	.10
5	MD97	Stop Collar	.50	5	I-70336	Ball Bearing (2 used)	ea. 1.50
6	SF43	Swivel Stud w/nuts	.25	6	SF25	Bearing Spacer	1.00
7	3" x 1 1/2"	Casters (3 used)	ea. .75	7	SF29	Housing	3.00
	SF4-X	BASE ASSEMBLY (SFL)	8.00	8	SF13	Bearing Adj. Collar	.50
		consists of:		9	SF26	Adapter	2.25
8	SF4	Base Casting	7.00	10	Comm.	1/4" - 20 x 1/2" Allen Screw	.10
9	T-63	Thrust Bearing	.45	SF108	Adapter for WSP116 Casing	2.75	
10	SF43	Swivel Stud w/nuts	.25	SF123	Lock Handle for above	.25	
11	2" x 1 1/2"	Casters (3 used)	ea. .50				
	SF16-X	YOKE ASSEMBLY	9.00			CORES, CASINGS AND HANDPIECES	
		consists of:		SF87	CORE 7/16" dia.	11.25	
12	SF16	Yoke only	4.50	SF91A	CASING	17.75	
13	SF15R or L	Motor Plate Brackets	ea. 1.50	SF96	HEAVY DUTY HANDPIECE	24.25	
14	SF12-C	Lock Handle (2 used)	ea. .75		consists of:		
15	Comm.	1/2" Flat Washer (4 used)	ea. .05	1	SF24	Spindle Lock Nut	1.50
16	Comm.	1/2" Lock Washer (4 used)	ea. .05	2	SF20	Spindle	6.50
	SF5-X	MOTOR PLATE ASSEMBLY	3.50	3	SF22	Housing Cover	2.00
		consists of:		4	SF59	Fibre Washer	.10
17	SF5	Motor Plate	3.00	5	I-70336	Ball Bearing (2 used)	ea. 1.50
18	58C	Lock Handle	.30	6	SF21	Housing	8.50
19	Comm.	5/16"-18 x 1 1/4" Sq. Hd. Bolt (4)ea.	.05	7	SF25	Bearing Spacer	1.00
20	Comm.	5/16"-18 Hex Nut (4 used)	ea. .05	8	SF13	Bearing Adj. Collar	.50
21	Comm.	5/16" I.D. Flat Washer (4 used)ea.	.05	9	SF26	Adapter	2.25
	SF41-X	HAND PIECE HOLDER	3.00	10	Comm.	1/4"-20 x 1/4" Allen Screw	.10
		consists of:				ADAPTERS	
22	SF41	Support Bar	1.50	SF129	5/8" Adapter w/nut	1.75	
23	SF19	Holder Bracket	1.50	SF130	Chuck Adapter	1.50	
24	Comm.	5/16"-18 x 5/16" Allen Screw	.10	SF156	6" Extension Adapter	8.25 (net)	
	SF11-X	PULLEY HOUSING ASSEMBLY	16.00			Flange Washers for SF129	1.00
		consists of:		WSP117	CORE 5/16" dia. x 53-3/8" long	4.25	
25	SF11	Pulley housing	6.50	WSP117B	CORE 1/4" dia. x 55-3/8" long	4.25	
26	SF12	Pulley housing cover	3.50	WSP116	CASING	7.50	
27	SF14	Jackshaft Bracket	5.50	WAC4	HANDPIECE	16.00	
28	SF49	Eye Bolt	.50		consists of:		
29	ID9508	Lock Screw	.25	45	SF180	Spindle	6.00
30	VB24	24" V. Belt	.55	46	SF180C	Collar	ea. 1.50
31	PF40	Pulley	.75	47	382-VLC 3	Ball Bearing (2)	ea. 3.00
32	PF40	Pulley	1.00	48	SF111	Housing	1.00
33	Comm.	1/2"-15 x 1 1/4" Hex Bolt (2)	.05	49	SF180-3	Rubber Cover	1.00
34	Comm.	5/8"-16 x 1 1/2" " "	.05	50	SF112	Spacer	1.00
35	Comm.	5/8" Standard flat washer	.05	51	SF178	Casing Adapter	1.00
36	Comm.	1/2" " " "	.05	52	SF131	Shaft Adapter	1.50
				53	SF119-W	Fibre Washer (2)	ea. .05
				54	SF177-C	1/4" Collet	2.50
				55	SF177-W	Collet Nut	1.00

(MOTOR AS SPECIFIED)

Walker-Turner Company, Inc.

PLAINFIELD

The Walker-Turner Company reserves the right to make changes in design or to make additions to or improvements in its products without imposing any obligation upon itself to install them on its product previously manufactured.

New Jersey, U.S.A.

3-47 Spencer